FIRE RISK ASSESSMENT

RECORD OF SIGNIFICANT FINDINGS

REGULATORY REFORM (FIRE SAFETY) ORDER 2005

as amended by the Building Safety Act 2022

LOCATION: DRAYTON VILLAGE HALL, STRATFORD ROAD, DRAYTON, OX15 6EH

AREA: VILLAGE HALL

<u>RESPONSIBLE PERSON:</u> VILLAGE HALL MANAGEMENT COMMITTEE

PERSON RESPONSIBLE FOR FIRE SAFETY: JILL BROWN

DATE: JULY 2025 - to be reviewed annually

OBJECTIVE: The objective is to assess the likelihood of a fire starting, its development and the risk to perso

DESCRIPTION OF THE BUILDING:

Constructed in 1868. Former village school.

Southern part: stone walls; single storey with attic over (accessed by collapsable loft ladder) Northern part: solid brick walls; single storey with insulated suspended ceiling (void over)

All under a concrete tiled roof.

ACTIVITIES CARRIED OUT: Village Hall

NUMBERS AFFECTED: 96

FREQUENCY OF USE: Intermittent

SOURCES OF IGNITION:

IGNITION SOURCE		PERCEIVED RISK OF FIRE	ELIMINATION OR REDUCTION OF HAZARD
Electrical Equipment:	Electrical distribution board in Hall.	Worn, damaged or untested electrical	The fuse board was largely replaced in 2017
	Electric lighting.	equipment or wiring could start a fire	and electrical equipment is checked every 5 years
	Electric radiant heaters in Hall (6 No.)		by a competent electrician.
	Water heaters in toilets & kitchen (3 No.)		Portable electrical equipment is PAT tested
	Frost heaters in toilets & kitchen (3 No.)		every 12 months by a competent person.
	Hand driers in toilets (2 No.)		
	Extractor fan in kitchen		
	Electrical appliances in kitchen		
Smokers (cigarettes):	No smoking allowed	Slight possibility this could be ignored.	No Smoking signs displayed
		Carelessly discarded or improperly extinguished	
		cigarettes could start a fire.	
Arson/Vandalism:		Risk of combustable materials being deliberately	No letter box
		ignited.	

SOURCES OF FUEL - COMBUSTIBLE & FLAMMABLE MATERIALS:

COMBUSTIBLE MATERIALS	PERCEIVED RISK OF FIRE SPREAD	ELIMINATION OR REDUCTION OF FUEL SOURCES
Timber panelling to lower part of walls in Hall.	Timber building materials could become ignited	
Suspended plywood ceiling panels in Hall.	& start or aid the spread of fire.	
Timber floor boards in Hall.		
Wooden card tables	Extraneous combustable materials could assist	Combustable materials kept in their designated
Chair cushions.	in the starting / spread of fire.	areas; clutter avoided.
Curtains In Hall (100% Polyester)	Because of the structure of the fabric and the way it is woven, Polyester is inherently flame retardant & tends to be slow to ignite and self-extinguish. Window curtains are high up & out of the way. Hall is small with ample exits allowing quick exit. Cupboard curtain sited by fire exit and is more	Considered acceptable. Treated with fire-retardant chemicals
w	assessible.	Mark to the latest and the
Waste	Minimal	Waste is regularly removed outside
Cleaning materials	Flammable gases & liquids could assist in the	Small quantities of flammable liquids & gases
	spread of fire if not stored correctly.	are stored in a safe manner to minimise risk.

SOURCES OF OXYGEN:

OXYGEN SOURCE		PERCEIVED RISK OF FIRE SPREAD	ELIMINATION OR REDUCTION OF OXYGEN SOURCES
Natural ventilation:	Doors, windows	Minimal risk - No sources other than in normal	It is not possible to reduce oxygen sources.
		acceptable quantities.	
Mechanical ventilation:		None	

IDENTIFICATION OF PEOPLE AT RISK:

People who use the Hall	Recommend limiting numbers to maximum of 96 people standing and 65 seated (not at tables)
People with disabilities or special needs	None identified at time of inspection, but should be catered for as and when the need arises.

ELIMINATION OR REDUCTION OF RISK TO PEOPLE:

Are the means of detecting and giving warning of fire adequate	No alarm but a verbal (shouted) warning is	Smoke detector fitted in kitchen
for the risk?	deemed adequate.	
Is there sufficient, well-maintained fire fighting equipment	Sufficient extinguishers are provided and these	2 No. 3 litre water extinguishers in Hall.
sited throughout the building?	are serviced annually with certificate given.	1 No. 2 kg CO2 extinguisher in kitchen.
		Signage for extinguishers.
		Fire blanket in kitchen.
Are the means of escape safe, of sufficient width and numbers	Yes - Escape from Hall is via 2 No. rear fire doors	
and within acceptable travel distance limits?	both with panic bars.	
	(Note: door from Hall to lobby opens inwards)	
Is normal and emergency lighting sufficient for the premises?	Yes - Final exits & Hall to lobby door have	
	illuminated maintained emergency escape	
	route signs.	
Are there enough appropriate signs & notices?	Yes - 'Fire Action' notices sited by each exit door.	
Are maintenance and testing arrangements adequate?	Emergency escape route signs tested monthly	
	& a record kept in Fire Safety Log Book	
Are there fire compartments?	No fire compartments.	
Is means of escape adequate?	There are sufficient fire escape doors.	
Is any training required?	None deemed necessary.	

Are fire procedures adequate for the premises?	On discovering a fire verbal warning to be given	
	to others including those in the toilets.	
	People to leave premises by fire exits.	
	Assembly point is in rear car park.	

GENERAL COMMENTS:

Seating: minimum clear space between rows to be 305mm. Gangways should be minimum 1.05 metres wide.

Standing or sitting in gangways or in front of fire exit doors should not be permitted.

Ensure fire exits are kept clear at all times.

Persons with mobility issues to be seated within easy access to fire exit.

Exterior pathway to rear of hall to be kept clear at all times.

Notice board should be kept tidy.

Ensure waste bins are emptied regularly

Cooker to be inspected regularly for damage and kept clean and in good order.

RECOMMENDATIONS:

All portable electrical appliances to be tested anually

Smoke alarm in kitchen- annual testing & replacement of batteries,

Cupboard curtain to be retreated with fire-retardant chemicals after it has been washed/dry cleaned

RISK ASSESSMENT:

The risk of fire is considered low but in the event occupants should be able to evacuate safely.

July 2025