

the play inspection company

Annual Inspection

Fields in Trust - (NPFA)

Bockhampton

Bockhampton Lane, Lower Bockhampton, Dorset, DT2 8PZ











Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL t- 01202 590675 e- info@playinspections.co.uk





RPII Inspection Methodology

This document outlines the RPII position on inspections undertaken by the Inspectors listed on the RPII Register of Inspectors for Indoor Annual, Outdoor Operational and Outdoor Routine.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it the date of the standard will be that current at the time of inspection with the exception of where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this would include public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below);

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, including ancillary items).

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standard (BS EN 71 – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance within the inspection will still refer to BS EN 1176.

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

BS EN 15312 - Free access multi-sports equipment

BS EN 14974 - Skateparks

BS EN 16630 - Permanently installed outdoor fitness equipment

BS EN 16899 - Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with current standards and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area up to 3.0 metres around, or the fence line if closer.

Operational inspections only take into consideration defects related to wear and vandalism. Routine visual inspections (if undertaken) relate only to the most obvious defects such as broken or missing parts, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

The inspection is non-dismantling, non-destructive and does not include for any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all standing surfaces as necessary on the equipment and assess all parts up to 2.5m above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment. Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document to ensure as far as is reasonably practicable the continued safe use of the items concerned. The owner/operator is responsible for the overall safety of the equipment and area. Inspectors who are trained to use ladders may use them where it is safe to do so, but if members of the public are present on-site ladders may not be used to access the equipment.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of impact absorbing properties of any surfaces. The identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection or the inspection of any equipment (or part thereof) that is underground. Tightening any bolts, hinges or other fixing devices on any apparatus or equipment. Assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment. Assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming).

Where planting or trees are mentioned in the report no aboricultural or horticultural assessments of toxicity, suitability or condition are undertaken; the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity and this inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/ or that of the inspection company. The owner/operator should seek the advice of the manufacturer or a competent person at all times when undertaking repairs and/or modifications to equipment.

A full copy of the Play Inspection Company Ltd. Terms & Conditions is available on our website (www.playinspections.co.uk)

© The Play Inspection Company & the Register of Play Inspectors International 9th September 2020





Table 1

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual Outdoor/ Fully enclosed Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	V	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	V	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	V	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	~	✓ [3]
6.1 d) Effects of weather	V	✓
6.1 d) Presence of rot, decay or corrosion (see note 1)	✓	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	V	✓ [4]
6.1 d) Excavation or dismantling/additional measures	V	×
6.2.1 Assessment of glass reinforced plastics (see note 5)	✓	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	V	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	V	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

- [1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.
- [2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.
- [3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.
- [4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance
- [5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

Risk Assessment Matrix

			Scores in the report are multiplication factors of Likelihood x Severity						
			Severity>>						
	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)	
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)	
Likelihood	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)	
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)	
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)	
		•		Very Low	Low	Moderate	High	Very High	
				1	2	3	4	5	
	PI			No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality	
	Severity>>								

Note 1: The total risk scores included within our reports are a multipication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

Equipment has been assessed to the following standards where relevant:

BS EN 1176 Parts 1-11 (Playground equipment and surfacing)

BS EN 14974 (Facilities for users of roller sports equipment)

BS EN 15312 (Free access multi-sports equipment)

BS EN 16899 (Parkour Equipment)

BS EN 16630 (Outdoor Fitness Equipment).



Bockhampton

Inspection Ref: 1211202 Site Ref: 3582 Customer Order: N/A

Inspected: 19-October-2020 - 12:25 by Matt Clay (RPII Annual Inspector)

Risk Assessment: 10 Low Risk



Location:

The site is partially overlooked by properties in the local community **Disabled Access:**

Some accessible features; an area that presents difficulties to the majority of people with disabilities but in favourable circumstances and certainly in partnership can be accessed.





5 - Very Low Risk

Item: Sign

Owner/Operator Manufacturer:

Surface Type: N/A **Item Quantity:** 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 1



Finding 1

It is recommended that signage, with information including the site address, contact information for maintenance issues and emergency contact details are provided for the facility - Provide in accordance with the recommendations



3 - Very Low Risk

Item: Gate

Manufacturer: Owner/Operator **Surface Type:** N/A **Item Quantity:** 1 **Equipment Compliance:** N/A

Surface Area Compliance: N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -





6 - Low Risk

Item:Gate - MaintenanceManufacturer:Owner/Operator

Surface Type: N/A
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

There is no padlock on the maintenance gate - Provide a padlock to secure the gate



8 - Low Risk

Item:Fence - ChainlinkManufacturer:Owner/Operator

Surface Type: N/A
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

There are areas or parts of the timber on the structure that have rotted - Replace all affected timbers

Finding 2

There are a number of loose posts around the fence - Monitor for any further deterioration and reset as required





3 - Very Low Risk

Fencing - Post & Rail Item: Manufacturer: Owner/Operator

Surface Type: N/A **Item Quantity:** 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -



3 - Very Low Risk

Picnic Table Item: Manufacturer: Owner/Operator

Surface Type: Concrete

Item Quantity: 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -



음 6 - Low Risk

Item:Site GeneralManufacturer:Owner/Operator

Surface Type:N/AItem Quantity:1Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 2



Finding 1

The grass is overgrown within the play area and may hide hazards - Reduce the length of grass to an acceptable height and maintain

Finding 2

The site is accessible to the public during the COVID 19 pandemic. The government have released guidelines for safely re-opening these types of facilities which is available on the government website. - Ensure there is an appropriate risk assessment in place and review regularly



10 - Low Risk

Item: 1 Bay 2 Seat (Flat)
Manufacturer: Playline Design

Surface Type:GrassItem Quantity:1Equipment Compliance:NoSurface Area Compliance:Yes

Total Findings: 7



Finding 1

The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required

Finding 3

The seat has minor damage or wear - Monitor for any further deterioration and replace as required

Finding 5

The seats are too close to the frame as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended

Finding 7

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required

Finding 2

There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

Finding 4

There is algae or moss on the surface of the equipment - Clean and treat appropriately

Finding 6

A number of fixing(s) have worked loose on the crossbar - Secure all loose fixings





8 - Low Risk

Item: 1 Bay 1 Seat (Cradle) - Type 1

Manufacturer: Playline Design

Surface Type:GrassItem Quantity:1Equipment Compliance:NoSurface Area Compliance:Yes

Total Findings: 4



Finding 1

There is algae or moss on the surface of the equipment - Clean and treat appropriately

Finding 3

There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

Finding 2

The seats are too close to the frame as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended

Finding 4

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required



6 - Low Risk

Item:Goal EndManufacturer:Playline Design

Surface Type: Grass Item Quantity: 2
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

NB: We have undertaken a maintenance inspection only of the football goal(s); full load testing falls outside the scope of our inspection. - Implement load testing as required

Finding 2

The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required





Findings information



Item: Ancillary Items - Sign

Manufacturer: Owner/Operator

Risk Level: V - Very Low Risk Surface: N/A





Finding: It is recommended that signage, with information including the site address, contact information for maintenance issues and emergency contact details are provided for the facility

Action: Provide in accordance with the recommendations



6 - Low Risk (Finding 1)

Item: Ancillary Items - Gate - Maintenance F

Manufacturer: Owner/Operator

Risk Level: L - Low Risk Surface: N/A





Finding: There is no padlock on the maintenance gate

Action: Provide a padlock to secure the gate







Item:Ancillary Items - Fence - ChainlinkRisk Level:L - Low Risk

Manufacturer: Owner/Operator Surface: N/A





Finding: There are areas or parts of the timber on the structure that have rotted

Action: Replace all affected timbers

6

6 - Low Risk (Finding 2)

Item:Ancillary Items - Fence - ChainlinkRisk Level:L - Low RiskManufacturer:Owner/OperatorSurface:N/A





Finding: There are a number of loose posts around the fence

Action: Monitor for any further deterioration and reset as required







6 - Low Risk (Finding 1)


Item: Ancillary Items - Site General

Manufacturer: Owner/Operator

Risk Level: Surface: L - Low Risk

urface: N/A







Action: Reduce the length of grass to an acceptable height and maintain



0 - Risk Assessment not Undertaken (Finding 2)

Item: Ancillary Items - Site General

Manufacturer: Owner/Operator

Risk Level: N - Risk Assessment not Undertaken **Surface:** N/A



Finding: The site is accessible to the public during the COVID 19 pandemic. The government have released guidelines for safely re-opening these types of facilities which is available on the government website.



Action: Ensure there is an appropriate risk assessment in place and review regularly







6 - Low Risk (Finding 1)

Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:Manufacturer:Playline DesignSurface:



L - Low Risk

Grass

Finding: The item is slightly loose in its foundations

Action: Monitor for any further deterioration and repair as required

6 - Low Risk (Finding 2)

Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:L - Low RiskManufacturer:Playline DesignSurface:Grass




Finding: There is some evidence of rot in the timber



Action: Monitor for any further deterioration and replace as required







Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:L - Low RiskManufacturer:Playline DesignSurface:Grass





Finding: The seat has minor damage or wear

Action: Monitor for any further deterioration and replace as required

8 - Low Risk (Finding 4)

Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:L - Low RiskManufacturer:Playline DesignSurface:Grass





Finding: There is algae or moss on the surface of the equipment

Action: Clean and treat appropriately







4 - Very Low Risk (Finding 5)

Swings - 1 Bay 2 Seat (Flat) V - Very Low Risk Risk Level:

Manufacturer: Playline Design Surface: Grass





Finding: The seats are too close to the frame as defined in Action: Monitor - No remedial work recommended BS EN 1176 Part 2; this is a low risk failure and no remedial action is required

10 - Low Risk (Finding 6)

Item: Swings - 1 Bay 2 Seat (Flat) Risk Level: L - Low Risk Manufacturer: Playline Design Surface: Grass





Finding: A number of fixing(s) have worked loose on the

Action: Secure all loose fixings crossbar







Item: Swings - 1 Bay 2 Seat (Flat)

Manufacturer: Playline Design

Risk Level: L - Low Risk Surface: Grass



Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process



Action: Monitor for any deterioration (rot) and replace as required

8 - Low Risk (Finding 1)

Item: Swings - 1 Bay 1 Seat (Cradle) - Type 1

Manufacturer: Playline Design

Finding: There is algae or moss on the surface of the equipment

Risk Level: L - Low Risk
Surface: Grass



Action: Clean and treat appropriately







4 - Very Low Risk (Finding 2)

Swings - 1 Bay 1 Seat (Cradle) - Type 1 Risk Level:

Manufacturer: Playline Design






V - Very Low Risk

Finding: The seats are too close to the frame as defined in Action: Monitor - No remedial work recommended BS EN 1176 Part 2; this is a low risk failure and no remedial action is required

6 - Low Risk (Finding 3)

Item: Swings - 1 Bay 1 Seat (Cradle) - Type 1 Risk Level: L - Low Risk Manufacturer: Playline Design Surface: Grass







Action: Monitor for any further deterioration and replace as required







Swings - 1 Bay 1 Seat (Cradle) - Type 1 Item: Playline Design Manufacturer:



Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process

Risk Level: L - Low Risk Surface: Grass



Action: Monitor for any deterioration (rot) and replace as required

0 - Risk Assessment not Undertaken (Finding 1)

Multi Use Games Area - Goal End Item: Manufacturer: Playline Design



Finding: NB: We have undertaken a maintenance inspection only of the football goal(s); full load testing falls outside the scope of our inspection.

Risk Level: N - Risk Assessment not Undertaken Surface: Grass



Action: Implement load testing as required







Item: Multi Use Games Area - Goal End

Manufacturer: Playline Design

Risk Level: L - Low Risk Surface: Grass



Finding: The item is slightly loose in its foundations



Action: Monitor for any further deterioration and repair as required