Elite Playground Inspections

'Keeping Our Children Safer at Play'

Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

Inspections included in this report

| Provider | Elite Playground Inspections | |
|-------------------|------------------------------|------------|
| Site Name | Cerne Abbas Play Area | |
| Actual Date | 01/06/2022 05:56:15 | |
| Inspection Type | Playground-Operational | |
| Inspector | Steve Day | |
| Inspection Status | Completed | |
| | | |
| | | |
| | | 01/06/2022 |

Finding Summary

Cerne Abbas Play Area Findings

| Asset | Finding Title | Creation Date | Resolve By Date | Risk Level |
|----------------------------------|--------------------------------|------------------------|-----------------|------------|
| Litter Bin | Bin - Not locked | 02/02/2022 09:53:57 | | Low |
| Fencing | Timber - Rotting | 02/02/2022 09:58:06 | | Low |
| Basket, Cradle & Flat Seat Swing | Item - Loose in Ground | 02/02/2022 10:08:29 | | Low |
| Site | RECOMMENDATIONS | 02/02/2022 10:10:20 | | Low |
| 5 Tower Multiplay Unit | Timber - Not in Good Condition | 02/02/2022 10:13:00 | | Low |
| Pedestrian Gates | Other / Miscellaneous | 02/02/2022 10:20:19 | | Low |
| Outside Area - MUGA | Other / Miscellaneous | 02/02/2022 10:26:10 | | Low |
| Outside Area - MUGA | Item - Damaged | 02/02/2022 10:27:20 | | Low |
| Site | Other / Miscellaneous | 01/06/2022 06:02:39 | | Low |
| 5 Tower Multiplay Unit | Chain - Links Worn | 01/06/2022 06:06:50 | | Low |
| Benches | RECOMMENDATIONS | 02/02/2022 10:17:34 | | Very Low |

Inspection - Cerne Abbas Play Area - 01/06/2022 05:56:15

| Provider | Elite Playground Inspections | |
|-------------------|------------------------------|--------------|
| Site Name | Cerne Abbas Play Area | C_{γ} |
| Actual Date | 01/06/2022 05:56:15 | |
| Inspection Type | Playground-Operational | |
| Inspector | Steve Day | 01/06/2022 |
| Inspection Status | Completed | |

| Site Name | Cerne Abbas Play Area |
|-----------|-----------------------|
| Address | |
| Postcode | |
| Notes | |

Cerne Abbas Play Area Inspected Asset List (see Inspection Notes for exceptions)

| Asset Name | 5 Tower Multiplay Unit | |
|----------------|--------------------------|--|
| Asset Sub Type | Multiplay Unit - Junior | |
| Asset Type | Multiplay | |
| Asset Category | Equipment (Outdoor Play) | |
| Manufacturer | | |
| | | |
| | | |



| Asset Sub Type Ru | ibber Mulch |
|-------------------|--------------|
| | |
| Asset Type Sa | ıfer Surface |
| Asset Category Su | ırface |
| Manufacturer | |



| Asset Name | Backless Bench |
|----------------|----------------------|
| Asset Sub Type | Bench with back rest |
| Asset Type | Seating |
| Asset Category | Facilities |
| Manufacturer | |
| | · |



| Asset Name | Basket, Cradle & Flat Seat Swing | |
|----------------|----------------------------------|----|
| Asset Sub Type | Type 1 - Traditional (Other) | |
| Asset Type | Swing | |
| Asset Category | Equipment (Outdoor Play) | 27 |
| Manufacturer | | 1 |
| | | |



| Asset Name | Basket, Cradle & Flat Seat Swing - Surface |
|----------------|--|
| Asset Sub Type | Rubber Mulch |
| Asset Type | Safer Surface |
| Asset Category | Surface |
| Manufacturer | |
| | |



| | | 02/02/2022 |
|------------|---------|------------|
| | | |
| | | 7490 |
| Asset Name | Benches | |

| Asset Sub Type | Bench |
|----------------|------------|
| Asset Type | Seating |
| Asset Category | Facilities |
| Manufacturer | |




| 02/02/2022 |
|------------|
| |

| Asset Name | Crazy Nellie Springer |
|----------------|--|
| Asset Sub Type | Type 2B - Single Point - Multi-directional |
| Asset Type | Rocker |
| Asset Category | Equipment (Outdoor Play) |
| Manufacturer | |
| | |



| Asset Name | Crazy Nellie Springer - Surface | |
|----------------|---------------------------------|----|
| Asset Sub Type | Rubber Mulch | |
| Asset Type | Safer Surface | |
| Asset Category | Surface | 60 |
| Manufacturer | | |
| | ' | |



| 02 | /N | 2 | 12 | n | 22 | |
|----|-------------|---|----|---|----|--|
| 02 | $^{\prime}$ | _ | _ | u | ~~ | |

| Asset Name | Fencing | 100 |
|----------------|-----------------------------|------|
| Asset Sub Type | Post & Rail with Chain Link | |
| Asset Type | Fencing | |
| Asset Category | Perimeter | W 10 |
| Manufacturer | | 0.00 |
| | | G |



| 02/02/2022 |
|------------|
|------------|

| Asset Name | Inclusive Roundabout |
|----------------|--------------------------|
| Asset Sub Type | Type B Classic - Flush |
| Asset Type | Carousel |
| Asset Category | Equipment (Outdoor Play) |
| Manufacturer | |



| Asset Name | Inclusive Roundabout - Surface |
|----------------|--------------------------------|
| Asset Sub Type | Wet Pour |
| Asset Type | Safer Surface |
| Asset Category | Surface |
| Manufacturer | |



| Asset Name | Litter Bin | |
|----------------|------------|-------------|
| Asset Sub Type | Bin | |
| Asset Type | Bins | |
| Asset Category | Facilities | |
| Manufacturer | | September 1 |
| | | |



02/02/2022

| Asset Name | Maintenance Gate |
|----------------|------------------|
| Asset Sub Type | Maintenance Gate |
| Asset Type | Entrance |
| Asset Category | Perimeter |
| Manufacturer | |
| | |



| Asset Name | Outside Area - MUGA | |
|----------------|--------------------------|--|
| Asset Sub Type | Multi Use Games Area | |
| Asset Type | Ball Play | |
| Asset Category | Equipment (Multi Sports) | |
| Manufacturer | | |



|)2 | 2/C | 12 | 2 | 0 | 2 | 2 | |
|----|-----|----|---|---|---|---|--|
| | | | | | | | |

| Asset Name | Pedestrian Gates |
|----------------|------------------|
| Asset Sub Type | Pedestrian Gate |
| Asset Type | Entrance |
| Asset Category | Perimeter |
| Manufacturer | |



| Asset Name | Picnic Table | |
|----------------|--------------|--|
| Asset Sub Type | Picnic Table | |
| Asset Type | Seating | |
| Asset Category | Facilities | |
| Manufacturer | | |
| | | |



| 02/02/2022 | 02/ | 02 | /20 | 22 |
|------------|-----|----|-----|----|
|------------|-----|----|-----|----|

| Asset Name | Signs |
|-----------------------|-----------------------|
| Asset Sub Type | Children's playground |
| Asset Type | Children's Playground |
| Asset Category | Site |
| Manufacturer | |



| | s |
|-------------------|----|
| | |
| State of the last | g |
| Was . | |
| LEADING THE | 60 |

| Asset Name | Site |
|----------------|-----------------------|
| ASSELIVATILE | Site |
| Asset Sub Type | Children's playground |
| Asset Type | Children's Playground |
| Asset Category | Site |
| Manufacturer | |
| | |



02/02/2022

| Asset Name | Tyre Agility Course |
|----------------|-------------------------------------|
| Asset Sub Type | Tyre Walk |
| Asset Type | Outdoor Fitness (Traditional Style) |
| Asset Category | Equipment (Outdoor Fitness) |
| Manufacturer | |



| Asset Name | Ziggy Springer | 44/1 |
|----------------|--|---|
| Asset Sub Type | Type 2B - Single Point - Multi-directional | |
| Asset Type | Rocker | |
| Asset Category | Equipment (Outdoor Play) | |
| Manufacturer | | |
| | | |
| | | TANK THE PARTY OF |




02/02/2022

| Asset Name | Ziggy Springer - Surface | |
|----------------|--------------------------|--|
| Asset Sub Type | Rubber Mulch | |
| Asset Type | Safer Surface | |
| Asset Category | Surface | Table 100 |
| Manufacturer | | The state of the s |
| | | |
| | | 02/02/2022 |

Findings and Tasks reported within the Inspection

5 Tower Multiplay Unit - Findings

| Finding Title | Chain - Links Worn | W W |
|-----------------------|--|---|
| Asset | 5 Tower Multiplay Unit | |
| Cause | Wear and Tear | |
| Finding Creation Date | 01/06/2022 06:06:50 | |
| Finding Group | Maintenance | NAME OF TAXABLE PARTY AND PERSONS ASSESSED. |
| Finding Notes | Chain connecting links are worn to approximately 50% | |
| Finding Resolved Date | | |
| Finding Status | Open | 10/ |
| Location | | Asset Photo |
| Resolve By Date | | ASSEL FIIOLO |
| Risk Level | Low | |



01/06/2022

Chain - Links Worn - Task

| Replace chain links (meeting ISO 1834) |
|--|
| |
| |
| 2541 |
| |
| Unapproved |
| |

Site - Findings

| -110 1 1110111190 | | |
|-----------------------|--|---------------|
| Finding Title | Other / Miscellaneous | |
| Asset | Site | |
| Cause | Act of God | |
| Finding Creation Date | 01/06/2022 06:02:39 | |
| Finding Group | Maintenance | CALLED CALLED |
| Finding Notes | Timber edging is rotting away and is missing in places | |
| Finding Resolved Date | | |
| Finding Status | Open | |
| Location | | Asset Photo |
| Resolve By Date | | ASSEC PHOLO |
| Risk Level | Low | |



01/06/2022

Other / Miscellaneous - Task

| Task Title | Refer to Inspection Notes / Description |
|---------------------|---|
| Resolve By Date | |
| Task Completed Date | |
| Task ID | 2537 |
| Task Notes | |
| Task Status | Unapproved |
| | |

Previously Reported Findings and Tasks (unresolved at time of Inspection)

5 Tower Multiplay Unit - Findings

| - Findings | | |
|--|---|--|
| Timber - Not in Good Condition | | N WA |
| 5 Tower Multiplay Unit | | |
| Act of God | | |
| 02/02/2022 10:13:00 | | |
| Maintenance | | THE PERSON NAMED IN |
| preserver or paint. It was notes down th | | |
| | | |
| Open | | Asset Photo |
| | | |
| | | |
| Low | | |
| 02/02/2022 | 02/02/2022 | 02/02/2022 |
| | | 02/02/2022 |
| | Timber - Not in Good Condition 5 Tower Multiplay Unit Act of God 02/02/2022 10:13:00 Maintenance Replace all timber that is rotting and o preserver or paint. It was notes down that turned over. Open Low Finding F 02/02/2022 02/02/2 | Timber - Not in Good Condition 5 Tower Multiplay Unit Act of God 02/02/2022 10:13:00 Maintenance Replace all timber that is rotting and or splitting. Treat the rest with a wood preserver or paint. It was notes down that some of the timber slats have been turned over. Open Low Finding Photos O2/02/2022 02/02/2022 02/02/2022 02/02/2022 02/02/2022 |

Timber - Not in Good Condition - Task

| Task Title | Repair item |
|---------------------|-------------|
| Resolve By Date | |
| Task Completed Date | |
| Task ID | 2218 |
| Task Notes | |
| Task Status | Unapproved |
| | |

Basket, Cradle & Flat Seat Swing - Finding

| , | | |
|-----------------------|--|--------------|
| Finding Title | Item - Loose in Ground | - CHARLES |
| Asset | Basket, Cradle & Flat Seat Swing | |
| Cause | Unknown | X X |
| Finding Creation Date | 02/02/2022 10:08:29 | |
| Finding Group | Maintenance | |
| Finding Notes | Swing leg appears to be slightly loose in the ground - monitor condition | |
| Finding Resolved Date | | |
| Finding Status | Open | |
| Location | | Asset Photo |
| Resolve By Date | | ASSEL FIIOLO |
| Risk Level | Low | |



02/02/2022

Item - Loose in Ground - Task

| Task Title | Monitor |
|---------------------|------------|
| Resolve By Date | |
| Task Completed Date | |
| Task ID | 2214 |
| Task Notes | |
| Task Status | Unapproved |
| | |

Benches - Finding

| Deficites - I maing | | |
|-----------------------|--|-------------|
| Finding Title | RECOMMENDATIONS | |
| Asset | Benches | |
| Cause | Act of God | |
| Finding Creation Date | 02/02/2022 10:17:34 | |
| Finding Group | Maintenance | |
| Finding Notes | I am recommending that all timber on the benches is cleaned off & treated with a wood preserver or paint | |
| Finding Resolved Date | | |
| Finding Status | Open | |
| Location | | Asset Photo |
| Resolve By Date | | |
| Risk Level | Very Low | |





02/02/2022

RECOMMENDATIONS - Task

| Task Title | RECOMMENDATION |
|---------------------|----------------|
| Resolve By Date | |
| Task Completed Date | |
| Task ID | 2217 |
| Task Notes | |
| Task Status | Unapproved |
| | • |

Fencing - Finding

| Finding Title | Timber Detting | |
|-----------------------|----------------------------|--------------|
| Finding Title | Timber - Rotting | |
| Asset | Fencing | |
| Cause | Act of God | |
| Finding Creation Date | 02/02/2022 09:58:06 | |
| Finding Group | Maintenance | No. |
| Finding Notes | Posts rotten in the ground | |
| Finding Resolved Date | | |
| Finding Status | Open | |
| Location | | Asset Photo |
| Resolve By Date | | Asset Filoto |
| Risk Level | Low | |



02/02/2022

Timber - Rotting - Task

| Replace item |
|--------------|
| |
| |
| 2220 |
| |
| Unapproved |
| |

Litter Bin - Finding

| Finding Title | Bin - Not locked | THE WALL THE WAY |
|-----------------------|---|------------------|
| Asset | Litter Bin | |
| Cause | Operator Error | |
| Finding Creation Date | 02/02/2022 09:53:57 | |
| Finding Group | Maintenance | |
| Finding Notes | Lock bin to help stop contents being emptied out in the play area | |
| Finding Resolved Date | | |
| Finding Status | Open | |
| Location | | Asset Photo |
| Resolve By Date | | ASSEL PHOLO |
| Risk Level | Low | |



Bin - Not locked - Task

| Task Title | Lock Bin |
|---------------------|------------|
| Resolve By Date | |
| Task Completed Date | |
| Task ID | 2212 |
| Task Notes | |
| Task Status | Unapproved |

Outside Area - MUGA - Findings

| Finding Title | Item - Damaged | |
|-----------------------|--------------------------|--------------|
| Asset | Outside Area - MUGA | |
| Cause | Wear and Tear | |
| Finding Creation Date | 02/02/2022 10:27:20 | |
| Finding Group | Maintenance | R. L. |
| Finding Notes | Net is damaged in places | |
| Finding Resolved Date | 01/01/1900 00:00:00 | |
| Finding Status | Closed | |
| Location | | Asset Photo |
| Resolve By Date | | ASSEL FIIOLO |
| Risk Level | Low | |

Item - Damaged - Task

| Task Title | Replace item |
|---------------------|-------------------------|
| Resolve By Date | |
| Task Completed Date | 01/01/1900 00:00:00 |
| Task ID | 2221 |
| Task Notes | Completed By: Steve Day |
| Task Status | Completed |

| Finding Title | Other / Miscellaneous | |
|-----------------------|--------------------------------------|--|
| Asset | Outside Area - MUGA | |
| Cause | Other - See Finding Notes | \$ 40 miles |
| Finding Creation Date | 02/02/2022 10:26:10 | |
| Finding Group | Maintenance | The last of the la |
| Finding Notes | Loose items found laying in the area | |
| Finding Resolved Date | | |
| Finding Status | Open | |
| Location | | Asset Photo |
| Resolve By Date | | ASSEL PHOLO |
| Risk Level | Low | |



02/02/2022

Other / Miscellaneous - Task

| Remove item |
|-------------|
| |
| |
| 2213 |
| |
| Unapproved |
| |
| |

Pedestrian Gates - Finding

| | 9 | |
|-----------------------|--|-------------|
| Finding Title | Other / Miscellaneous | LO LA TANK |
| Asset | Pedestrian Gates | |
| Cause | Other - See Finding Notes | No. |
| Finding Creation Date | 02/02/2022 10:20:19 | |
| Finding Group | Maintenance | |
| Finding Notes | Gates do not self close. It is recommended that they close between 4-8 seconds | |
| Finding Resolved Date | | |
| Finding Status | Open | |
| Location | | Asset Photo |
| Resolve By Date | | ASSEL PHOLO |
| Risk Level | Low | |





Finding Photos



02/02/2022

02/02/2022

Other / Miscellaneous - Task

| Task Title | Refer to Inspection Notes / Description |
|---------------------|---|
| Resolve By Date | |
| Task Completed Date | |
| Task ID | 2215 |
| Task Notes | Fit self closing mechanisms to gates to keep users in the park & dogs out |
| Task Status | Unapproved |
| | 1 1 |

Site - Findings

| Finding Title | RECOMMENDATIONS | |
|-----------------------|--|------------------|
| Asset | Site | |
| Cause | Other - See Finding Notes | |
| Finding Creation Date | 02/02/2022 10:10:20 | |
| Finding Group | Maintenance | EXTENSES NAME OF |
| Finding Notes | I am recommending that the redundant post that was part of the swing barrier is removed in case someone runs into it | |
| Finding Resolved Date | 01/01/1900 00:00:00 | |
| Finding Status | Closed | |
| Location | | Asset Photo |
| Resolve By Date | | |
| Risk Level | Low | • |

RECOMMENDATIONS - Task

| Task Title | RECOMMENDATION |
|---------------------|-------------------------|
| Resolve By Date | |
| Task Completed Date | 01/01/1900 00:00:00 |
| Task ID | 2216 |
| Task Notes | Completed By: Steve Day |
| Task Status | Completed |

Findings and Tasks Reported Outside of the Inspection (unresolved at time of Inspection)

None Recorded.