# Heritage at Risk



## Contents

Heritage at Risk	III	North Norfolk Norwich	44 49
The Register	VII	South Norfolk	50
Content and criteria	VII	Peterborough, City of (UA)	54
		Southend-on-Sea (UA)	57
Criteria for inclusion on the Register	IX	Suffolk	58
Reducing the risks	ΧI	Babergh	58
Key statistics	XIV	Forest Heath	59
Publications and guidance	XV	Mid Suffolk St Edmundsbury	60 62
Key to the entries	XVII	Suffolk Coastal	65
Entries on the Register by local planning authority	XIX	Waveney Suffolk (off)	68 69
Bedford (UA)	1	Thurrock (UA)	70
Cambridgeshire	2		
Cambridge	2		
East Cambridgeshire	3		
Fenland	5		
Huntingdonshire South Cambridgeshire	7 8		
Central Bedfordshire (UA)	13		
Essex	15		
Braintree	15		
Brentwood	16		
Chelmsford	17		
Colchester	17		
Epping Forest	19		
Harlow	20		
Maldon	21		
Tendring	22		
Uttlesford	24		
Hertfordshire	25		
Broxbourne	25		
Dacorum	26		
East Hertfordshire	26		
North Hertfordshire	27		
St Albans Three Rivers	29		
Watford	30 30		
Welwyn Hatfield	30		
Luton (UA)	31		
Norfolk	31		
Breckland	31		
Broadland	36		
Great Yarmouth	38		
King's Lynn and West Norfolk	<del>4</del> 0		
Norfolk Broads (NP)	44		

II







istoric England has again reduced the number of historic assets on the Heritage at Risk Register, with 412 assets removed for positive reasons nationally. We have seen similar success locally, achieved by offering repair grants, providing advice in respect of other grant streams and of proposals to bring places back into use. We continue to support local authorities in the use of their statutory powers to secure the repair of threatened buildings. Challenges remain. The percentage of buildings at risk which are capable of beneficial use, for example, has risen to its highest ever – 45.7%. This suggests that more usable buildings are beyond economic repair. Skills shortages may be in part to blame, but causes for the shift remain to be fully explored. This trend reinforces the importance of grant aid and of building the confidence of owners and other partners in order to achieve continued success.

John Neale Acting Planning Director, East of England



In the East of England the statistics reflect the national success with an overall reduction of 22 assets and the largest grant spend of any region, with over £1.9m tackling heritage at risk. This has resulted in improvements in condition, removals

from the Register or the development of projects which will ultimately lead to an efficient and successful repair phase in the future.

The region has seen an overall reduction of 9 scheduled monuments, 12 listed buildings and 4 places of worship. These figures take into account additions to the Register over the previous year, so the true number of assets removed is far higher, with 13 scheduled monuments removed, 15 listed buildings and 21 places of worship. We are on target to achieve our objective of 60 entries removed from the 2015 baseline Register by 2018.

In order to achieve this we are increasing our use of funding for capacity building. This year we funded a Project Officer post at **Coalhouse Fort** to oversee the actions set out in a Historic England funded Conservation Management Plan, and to apply for alternative and additional funding sources for the repair phases. This project is a prime example of successful collaborative

working with a local authority partner. We also work in partnership with local authorities to support and underwrite statutory notices on 'at risk' sites using the 'Stopping the Rot' process.

A particular challenge for the year ahead will be **Priory House** in Dunstable. This former priory guesthouse
complete with a medieval undercroft, is facing multiple
structural issues caused by excess moisture and
inappropriate materials used during modern repairs.
Work on this site, and others, encompasses new research
into the availability, use and effectiveness of **clunch** (a
white cretaceous limestone) as a building material.

Our work on archaeological and structural scheduled monuments has once again been successful this year. Particular success has derived from Countryside Stewardship funding in partnership with Natural England. Advances in our understanding of arable regimes have allowed the removal of some scheduled monuments from ploughing and arable activity altogether. Successes to be celebrated include repair projects at Stansted Castle, a substantial Norman ringwork and bailey, and at Thorney, where a stewardship agreement has seen a Bronze Age barrow removed from the plough, ensuring the continued survival of the remaining upstanding 30cm.

Gary Griffin Business Manager

Cover image: Sawston Tannery Drying Shed, grade II\*. Built in the mid-19th century, the shed survives as an exceptional example of its type due to its scale and unaltered form. The tannery, still active today, has been on site since at least the 17th century. The arcaded brick ground floor would formerly have housed steeping tanks and the three upper storeys with adjustable louvered ventilators and unencumbered floor space were for skin drying. The shed has long been redundant, but Historic England is seeking a secure future in partnership with the owners and local authority.



## Kersey Mill Ipswich, Suffolk



Kersey Mill is a grade II\* building which was added to the Heritage at Risk Register in 2014, after being in a deteriorating condition for many decades. New owners acquired the building in 2012 and immediately sought for a positive and sustainable solution to the structural issues and overall condition faced by the mill.

John Whitmore and Sons built the original section of the mill in 1810. It was later enlarged in 1868 with the introduction of a steam engine, large bolters (or sieve) and an elevator. This sophisticated array of equipment minimised the need for manual handling and produced fine white flour. The mill has over time been adapted to three main sources and phases of power: water, steam

and then gas. The milling machinery is still virtually complete and capable of sensitive repair and restoration to enable milling once again. The mill also has a fine iron waterwheel and the wheel pit has already been carefully repaired and rebuilt by the current owners.

The building is still substantially original, despite being subject to repairs and renewal over the years. However, a structural survey in summer 2015 discovered that two full-height principal posts, one axial beam and substantial areas of flooring were severely rotted and at risk of collapse. A leaky valley gutter and poor roof covering contributed to the rate of decay. The mill required urgent repair and replacement of these structural elements in order to reinstate structural integrity. A grant of £80,000 towards eligible costs of £101,760 was offered and accepted. The main elements of structural work were completed this summer to a high standard, resulting in a nomination for a Historic England Angel Award. The mill is now open to the public on selected open days.

## Coalhouse Fort Tilbury, Essex

Coalhouse Fort is a scheduled monument owned by Thurrock Borough Council. Built on the north side of the Thames estuary in 1861-74, it was part of the defences against the potential threat of French invasion. Successive modifications to the fort demonstrate the evolution of defence history and its technologies of ordinance, detection and monitoring from 1861 to 1945 all on one site. These include the installation of gun batteries, observation points, and searchlight and radar installations. A glacis or earth bank was added to the walls facing the river to reduce the prominence and vulnerability of the fort to heavy calibre shell fire.

The various structures on site are suffering increasingly from water ingress and resulting repairs and maintenance have accumulated. The dangerous condition of many areas impedes access and use of the site, while the risk of loss to historic fabric increases.

Now Historic England grant aid will fund a management strategy and emergency repairs. This includes thorough investigation of the causes of deterioration and the



strategies needed to realise the full potential of the site. A Project Officer will be responsible for overseeing immediate repairs, developing funding applications for future repairs to bring areas back into use and strategies to secure a sustainable future for the fort.

## 50th Anniversary of Conservation Areas

In 2017, Historic England will celebrate the 50th anniversary of conservation areas. These precious historic areas, from urban and industrial to rural and remote, create a strong sense of place and are likely to be what you think of when you think of special local character.

We'll carry out research into people's attitudes towards conservation areas and the challenges they

face in protecting them. We also plan to analyse local authorities' conservation area survey data to better understand what puts conservation areas up and down the country at risk. Finally, at a time when local authority resources are under pressure, we'll ask how local civic groups and organisations can become more involved to help safeguard conservation areas.

#### For more information contact:

Gary Griffin, Historic England East of England Brooklands, 24 Brooklands Avenue,

Cambridge, CB2 8BU

Telephone: 01223 582 749

 ${\bf Email: east of england@Historic England.org.uk}$ 

Twitter: @HE\_EoE

For a different format of this document contact our customer services department on:

Telephone: 0370 333 0608 Textphone: 0800 015 0516

Email: customers@HistoricEngland.org.uk

Product code: 52030

Find out what's at risk by searching or downloading the online Heritage at Risk Register at:

HistoricEngland.org.uk/har

## THE REGISTER

## Content and criteria

#### **DESIGNATION**

#### Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of designated assets. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture, Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

In June 2016 Historic England launched Enriching the List, a crowdsourcing initiative opening up the entries on the National Heritage List to contributions by users. Anyone can register as a volunteer and submit extra information about one of the assets on the List or submit photographs to illustrate it. This additional content will then be available for anyone to view with but separate from the official List Entry.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

#### LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Culture Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II\* and II. Grade I buildings are of outstanding interest, and II\* are particularly important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are over 376,000 listed entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

#### SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. Nearly 20,000 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and, often most seriously of all, wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not designated. Instead, they are managed through the planning system and other regimes.

VII

#### REGISTERED PARKS AND GARDENS

There are over 1,600 designed landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II\*, and the Gardens Trust on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

#### REGISTERED BATTLEFIELDS

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where often thousands were killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

#### PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

#### **CONSERVATION AREAS**

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For almost 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently nearly 10,000 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

# Criteria for inclusion on the Register

#### **RISK ASSESSMENTS**

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of designation. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

#### **BUILDINGS AND STRUCTURES**

To be considered for inclusion on the Register, buildings or structures must be:

- designated and included on the National Heritage List for England
- a grade I or II\* listed building
- a grade II listed building in London
- a structural scheduled monument with upstanding remains
- in secular (non-worship) use

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been

repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

### PLACES OF WORSHIP

To be considered for inclusion on the Register places of worship must be designated and listed grade I, II\* or II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

#### ARCHAEOLOGY

To be considered for inclusion on the Register archaeological sites must be designated as scheduled monuments and included on the National Heritage List for England. Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it ranging from 'extensive significant problems', to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

#### PARKS AND GARDENS

To be considered for inclusion on the Register parks and gardens must be designated as grade I, II\* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

#### **BATTLEFIELDS**

To be considered for inclusion on the Register battlefields must be designated and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings
- pressures of particular use within the site e.g. arable cultivation
- · damage e.g. unregulated metal detecting

Battlefields are removed from the Register either when damaging activities cease, are managed, or when threats recede due to effective planning.

#### WRECK SITES

To be considered for inclusion on the Register wrecks must be designated and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

#### **CONSERVATION AREAS**

Historic England has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. The information provides a detailed assessment of each conservation area. An overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Reducing the risks

One of the primary aims of the Historic England Corporate Plan 2015-2018 is reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grants to help remove heritage from the Register

Dedicated Heritage at Risk teams in our nine regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website, www.historicengland.org.uk. Key publications and guidance are listed on pages XV-XVI.

## **BUILDINGS AND STRUCTURES**

Our nine regional teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law.

Historic England can help with access to funding. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk for all asset types and Section 17 Management Agreements which are smaller grants for scheduled monuments. More information on funding can be found on the <a href="Historic England">Historic England</a> website. The support of other grant providers, including the Heritage Lottery Fund and Natural England, is also critical.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We are therefore working with local authorities to encourage them to develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; 'Stopping the Rot' is our published guidance on this. Our Heritage at Risk Solicitor can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the <u>Architectural Heritage Fund</u> and fund their regional support officers to work across the country. They help BPTs and other notfor-profit organisations to access funding, carry out feasibility studies and develop solutions for buildings at risk. The <u>Heritage Network Trust</u> also provides information about support officers and BPTs. Guidance and case studies are available on the <u>Historic England</u> website.

#### PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The <u>Maintenance</u> <u>Cooperatives Project</u> run by the Society for the Protection of Ancient Buildings helps to connect, inform and empower those people who look after places of worship. Other successful initiatives include the Yorkshire Maintenance Project run by the National Churches Trust.

The Heritage Lottery Fund runs the <u>Grants for Places</u> <u>of Worship</u> scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. Historic England's architects and surveyors, based in our regional Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's <u>Listed Places of Worship scheme</u>, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. New Work in Historic Places of Worship helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part funded by Historic England, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

#### **ARCHAEOLOGY**

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of the 19,850 scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agrienvironment grant schemes to best effect. This has been especially important under the new Countryside Stewardship Scheme, under which the first agreements commenced in January 2016. Historic England, Natural England and local authority curators have collaborated on developing a new web portal for the scheme which provides local advice to support landowner applications. Our work in partnership with

Natural England on agri-environment schemes has removed 778 scheduled monuments from the Register since 2009. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke recommendations for each monument, enabling cultivation to continue where it does not present a risk. It will also be an important tool for advising owners on the longer term management of their monuments as the existing ten year Environmental Stewardship agreements gradually expire.

Although great progress has been made, analysis of entries on the Register shows that prehistoric barrows continue to be one of the most 'at risk' types of archaeological site on the Register. Unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites - even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key. The delivery of this will always be reliant upon the help and goodwill of landowners.

#### PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

#### **BATTLEFIELDS**

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the National Planning Policy Framework makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II\*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal detecting.

Historic England also continues to encourage greater access to battlefields and the improvement of their amenity value and visitors' understanding of the impact these dramatic historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

### **WRECK SITES**

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their

national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival.

Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from <u>Historic England</u>.

#### **CONSERVATION AREAS**

Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them as well as those of us whose job it is to manage them or make decisions about their future.

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management.

Local authorities complete the Conservation Areas Survey, providing us with an understanding of what is particularly affecting the character and appearance of conservation areas, what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

## Key statistics

#### **BUILDINGS AND STRUCTURES**

- Nationally, 3.8% of grade I and II\* listed buildings (excluding places of worship) are on the Register. In the East of England the percentage is 2.3% (77 listed secular buildings).
- 19 building or structure entries have been removed from the 2015 East of England Register because their futures have been secured, and 7 have been added.
- 61.1% of buildings or structures (66) on the East of England baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 61.2%.

#### PLACES OF WORSHIP

- Nationally, 6.3% of listed places of worship are on the Register. In the East of England, 4.4% (103) are on the Register.
- 21 places of worship have been removed from the East of England Register following repair work, and 18 have been added.

#### **ARCHAEOLOGY**

- 2,528 (13.9%) of England's 19,848 scheduled monuments are on the Register. 184 (10.6%) of the East of England's 1,732 scheduled monuments are on the Register.
- 9 archaeology entries have been removed from the 2015 East of England Register for positive reasons, and 3 have been added.
- 40.4% of archaeology entries (82) on the East of England baseline 2009 Register have been

- removed for positive reasons, compared with the national figure of 42.2%.
- Nationally, damage from arable cultivation is the greatest cause of risk affecting 39% of archaeological entries on the Register. In the East of England the proportion is 73.2%.

#### PARKS AND GARDENS

 95 (5.8%) of England's 1,639 registered parks and gardens are on the Register. Of the 215 registered parks and gardens in the East of England, 5 (2.3%) are on the Register, the same as last year.

#### BATTLEFIELDS

Of the 46 registered battlefields in England, 6
(13.0%) are on the Register. The only registered
battlefield in the East of England is not on the
Register.

#### **WRECK SITES**

 Of the 49 protected wreck sites around England's coast, 6 (12.2%) are on the Register. The East of England's single protected wreck site is on the Register.

#### **CONSERVATION AREAS**

- 8,286 of England's 9,848 conservation areas have been surveyed by local authorities and 496 (6.0%) are on the Register. Of the 1,209 conservation areas in the East of England, 894 have been surveyed and 42 (4.7%) are on the Register.
- 2 conservation areas have been added to the 2015 East of England Register.

#### HISTORIC ENGLAND FUNDING

• £1.7 million in grant was spent on 28 entries on the East of England Register during 2015/16.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

# Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

<u>Assessment of Heritage at Risk from Environmental</u> <u>Threat: Key Message</u> (2013)

<u>Caring for Places of Worship 2010</u> (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 — Grappling with a 140-Year-Old Conservation Problem (2014) — <u>Historic England</u> Research News 21, available online

<u>Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers</u> (2013)

Heritage at Risk 2010 - Report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2016 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Online Register – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database.

<u>How to Assess the Condition of Historic Buildings</u> – an on-line introduction to assessing condition.

<u>Monuments at Risk (2008)</u> – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

<u>Protected Wreck Sites at Risk: A Risk Management</u> <u>Handbook</u> (2008)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

<u>Stopping the Rot: A Guide to Enforcement Action</u> <u>to Save Historic Buildings</u> (2016)

<u>Vacant Historic Buildings: An Owner's Guide to</u> <u>Temporary Uses, Maintenance and Mothballing</u> (2011)

#### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit <u>Heritage at Risk</u> where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the <u>National Heritage List for England</u> online database. Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address.

## CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website – <u>Historic England Publications</u>.

<u>Caring for Historic Graveyard and Cemetery</u> <u>Monuments</u> (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

<u>Caring for Places of Worship</u> (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

<u>Conservation Area Designation, Appraisal and Management</u> (2016)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Conservation and Management of War Memorial Landscapes (2016)

The Conservation, Repair and Management of War Memorials (2015)

Constructive Conservation in Practice (2008)

<u>Constructive Conservation: Sustainable</u> <u>Growth for Historic Places</u> (2013)

<u>Creativity and Care: New Works in English Cathedrals</u> (2009)

The Disposal of Heritage Assets: Guidance Note for Government Departments and Non Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological Sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Farming the Historic Landscape: Caring for Historic Parkland (2005)

## Guidance notes and application forms for grants:

- <u>Historic England Grant Schemes</u> overview of all our current grant schemes
- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Repair Grants for Heritage at Risk (2015)

Guidance on Looking after Historic Buildings

Guidance on Improving Streets and Public Spaces

Heritage Crime Prevention: A Guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the Use of Historic Buildings in Regeneration (2013)

<u>Landscape Advice Note: Trees and the Law</u> (2014)

Managing Local Authority Heritage Assets: Some Guiding <u>Principles for Decision Makers</u> (2003)

Management and Maintenance of Historic Parks and Gardens. The English Heritage Handbook (2007)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2007)

<u>Pillars of the Community: the Transfer of Local</u> <u>Authority Heritage Assets</u> (2015)

<u>Post-War Public Art: Protection, Care and Conservation</u> (2016)

<u>Practical Building Conservation</u> – revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012–2015)

<u>Scheduled Monument Consent: A Guide for Owners</u> <u>and Occupiers</u> (2014)

<u>Shared Interest: Celebrating Investment in the Historic Environment</u> (2006)

Theft of Metal from Church Buildings (2011)

<u>Valuing Places: Good Practice in Conservation Areas</u> (2011)

## Key to the entries

The Register includes the following risk assessment types:

Building or structure

(grade I and II\* listed buildings, grade II listed buildings in London and structural scheduled monuments)

Place of worship

(grade I, II\* and II listed buildings)

Archaeology

(scheduled monuments – earthworks and buried archaeology)

• Park and garden

(Registered parks and gardens)

Battlefield

(Registered battlefields)

Wreck site

(Protected wreck sites)

Conservation area

(Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

#### **ORDER**

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

#### DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II\*
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

#### CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments), parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

#### OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

#### **VULNERABILITY**

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

#### PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

#### **TREND**

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

#### **OWNERSHIP**

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

#### CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### **ABBREVIATIONS**

CA Conservation Area
HE Historic England
HLF Heritage Lottery Fund
LB Listed Building

LPA Local Planning Authority

NP National Park

PWS Protected Wreck Site
RB Registered Battlefield
RDC Registered Park and Co

RPG Registered Park and Garden

SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

## Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
BEDFORD (UA)							
Bedford (UA)	0	2	7	0	0	0	1
CAMBRIDGESHIRE							
Cambridge	0	2	1	0	0	0	0
East Cambridgeshire	0	0	16	0	0	0	0
Fenland	0	0	8	0	0	0	5
Huntingdonshire	2	I	5	0	0	0	0
South Cambridgeshire	2	5	21	0	0	0	5
CENTRAL BEDFORDSHIRE (	(UA)						
Central Bedfordshire (UA)	2	4	5	0	0	0	0
ESSEX							
Basildon	0	0	0	0	0	0	0
Braintree	1	3	2	0	0	0	2
Brentwood	2	I	0	0	0	0	0
Castle Point	0	0	0	0	0	0	0
Chelmsford	0	I	0	0	0	0	3
Colchester	2	I	3	0	0	0	3
Epping Forest	4	2	2	0	0	0	0
Harlow	I	0	I	0	0	0	0
Maldon	2	0	2	0	0	0	I
Rochford	0	0	0	0	0	0	0
Tendring	6	2	2	0	0	0	4
Uttlesford	2	I	3	I	0	0	0
HERTFORDSHIRE							
Broxbourne	0	0	0	0	0	0	2
Dacorum	0	0	0	I	0	0	0
East Hertfordshire	2	2	3	0	0	0	0
Hertsmere	0	0	0	0	0	0	0
North Hertfordshire	5	I	5	0	0	0	0
St Albans	ı	0	2	0	0	0	0
Stevenage	0	0	0	0	0	0	0
Three Rivers	ı	0	0	0	0	0	0
Watford	2	0	0	0	0	0	0
Welwyn Hatfield	1	0	0	0	0	0	0
LUTON (UA)	'		1	1			
Luton (UA)	0	0	0	0	0	0	2
NORFOLK	<u> </u>		1				
Breckland	6	13	4	0	0	0	2
Broadland	3	7	2	0	0	0	0
Great Yarmouth	4	6	0		0	0	0
King's Lynn and West Norfolk	8	6	7	0	0	0	0
Norfolk Broads (NP)	0	0	0	0	0	0	I
North Norfolk	6	12	4	I	0	0	4
Norwich	5	I	0	0	0	0	I
South Norfolk	0	13	5	0	0	0	0
PETERBOROUGH, CITY OF	(UA)		'				
Peterborough, City of (UA) SOUTHEND-ON-SEA (UA)	4	0	20	0	0	0	0
Southend-on-Sea (UA)	ı	0	0	0	0	0	I
SUFFOLK							
Babergh	I	3	4			0	0
Forest Heath	0	0		-		0	
Ipswich	0	0	0			0	0
Mid Suffolk	3	6		I	0	0	0

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
Norfolk Broads (NP)	0	0	0	0	0	0	0
St Edmundsbury	6	I	6	0	0	0	2
Suffolk Coastal	7	6	5	ı	0	0	1
Waveney	4	I	1	0	0	0	0
SUFFOLK (OFF)							
Suffolk (off)	0	0	0	0	0	ı	0
THURROCK (UA)							
Thurrock (UA)	2	0		0	0	0	1
TOTAL	98	103	153	5	0	1	42

#### BEDFORD (UA)



© Bernard Hooker

SITE NAME: Congregational Chapel, High Street, Roxton

Listed Place of Worship grade DESIGNATION:

II\*, CA

CONDITION: Poor

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

C (C) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1146376 Congregational chapel, created c1806 in Cottage Ornee style. Plastered walls and thatched roofs. Thatch mosscovered and deteriorating. Possibility that re-thatching required on some slopes. Church Elders applied unsuccessfully for a Listed Places of Worship Roof Repairs

Contact: Trudi Hughes 01223 582739

© Historic England

SITE NAME:	Parish Church of All Saints, High Street, Turvey
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (A)
OWNER TYPE:	Religious organisation

1039598

Medieval parish church with additions and alterations 1852-1854 by Sir George Gilbert Scott. "The finest mid-Victorian ecclesiastical ensemble in Bedfordshire" (McHardy). West part of the nave and the base of the tower has remains of Saxon work. The nave is mainly C13 with the north arcade added early C14 and the nave extended. Most of the windows were reworked by Scott. South aisle roof leaking badly over early C14 wall painting of the crucifixion. A Heritage Lottery Fund Grants for Places of Worship grant was accepted and repairs commenced in 2016.

Contact: Robert Parkinson 01223 582733

SITE NAME:	Manor Farm Iron Age univallate hillfort and medieva	al moated enclosur	re, Bolnhurst and Keysoe
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1012066
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Settlement site north of Chapel End Farm, Cardingt	con	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005390
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Site discovered by aerial photography south of villag	ge, Cardington	
SITE NAME: DESIGNATION:	Site discovered by aerial photography south of village Scheduled Monument	ge, Cardington  LIST ENTRY NUMBER:	1005413
		_	1005413 Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	
DESIGNATION: CONDITION:	Scheduled Monument  Extensive significant problems	LIST ENTRY NUMBER: TREND:	Declining
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Scheduled Monument Extensive significant problems Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No David Kenny 01223 582760
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument Extensive significant problems Arable ploughing Private	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No David Kenny 01223 582760
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument  Extensive significant problems  Arable ploughing  Private  Bury Hill Camp: a motte and bailey castle with three	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: e fishponds, Thurle	Declining No David Kenny 01223 582760
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Private  Bury Hill Camp: a motte and bailey castle with three Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: e fishponds, Thurle LIST ENTRY NUMBER:	Declining No David Kenny 01223 582760  eigh 1009155

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument

Unitary Authority World Heritage Site

SITE NAME:	Palaceyard Wood medieval moated enclosure and earthworks, Wyboston, Chawston and Colesden /	associated enclosu Great Barford	res, woodland bank and cultivation
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010948
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Claire Fidler 01223 582735
SITE NAME:	Yarl's Wood hermitage and moated site, Milton Er	nest	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012057
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Wold Farm moated enclosure, Odell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012490
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bedford		
DESIGNATION:	Conservation Area, 102 LBs, RPG grade II, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	lan Johnson (LPA) 01234 221953

#### **CAMBRIDGESHIRE**

#### **CAMBRIDGE**



Church of St Clement, Bridge SITE NAME: Street, Cambridge Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: B (A) OWNER TYPE: Religious organisation

The exterior of this church is dominated by the early C19 tower in a thin, Commissioners' Gothic style. The nave and aisles are externally entirely early C16, and the brick chancel is distinctively C18. There is a distinctive mix of building materials and blocked openings in the pre-C19 work. Church shared by Church of England and Greek Orthodox congregations. South aisle roof in particularly poor condition with significant water penetration.

LIST ENTRY NUMBER: 1126262 Contact: Robert Parkinson 01223 582733 © Historic England

© Historic England

SITE NAME: Church of St Andrew the Less, Newmarket Road, Cambridge Listed Place of Worship grade II, DESIGNATION: CA CONDITION: Very bad PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1126143

Abbey church of early C13 date consisting of chancel and nave. Rubble with some dressed stone. Built by Barnwell Priory on original Augustinian site. The church was restored 1854-6, the vestry and organ-chamber added in the late C19. Walls, roof and churchyard in very poor condition

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME: Old Cheddar's Lane pumping station  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1006896  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse  OWNER TYPE: Other not for profit group  EAST CAMBRIDGESHIRE  SITE NAME: All Saints' Church, remains of, Ashley  DESIGNATION: Scheduled Monument, LB grade II  LIST ENTRY NUMBER: 1006898  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Vandalism  NEW ENTRY: No  OWNER TYPE: No  Mixed, multiple owners  OID (CONTACT: David Kenny 01223 582760)
CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse OWNER TYPE: Other not for profit group  EAST CAMBRIDGESHIRE  SITE NAME: All Saints' Church, remains of, Ashley  DESIGNATION: Scheduled Monument, LB grade II  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Vandalism  Vandalism  Declining  Declining  TREND: Declining  No
PRINCIPAL VULNERABILITY: Collapse OWNER TYPE: Other not for profit group  EAST CAMBRIDGESHIRE  SITE NAME: All Saints' Church, remains of, Ashley  DESIGNATION: Scheduled Monument, LB grade II  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Vandalism  DECLIMING  Yes  CONTACT: Claire Fidler 01223 582735  LIST ENTRY NUMBER: 1006898  TREND: Declining  NEW ENTRY: No
Other not for profit group  EAST CAMBRIDGESHIRE  SITE NAME:  All Saints' Church, remains of, Ashley  DESIGNATION:  Scheduled Monument, LB grade II  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Vandalism  CONTACT:  Claire Fidler 01223 582735  Claire Fidler 01223 582735  Claire Fidler 01223 582735
EAST CAMBRIDGESHIRE  SITE NAME: All Saints' Church, remains of, Ashley  DESIGNATION: Scheduled Monument, LB grade II LIST ENTRY NUMBER: 1006898  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Vandalism  NEW ENTRY?: No
All Saints' Church, remains of, Ashley  DESIGNATION: Scheduled Monument, LB grade II  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Vandalism  All Saints' Church, remains of, Ashley  LIST ENTRY NUMBER: 1006898  TREND: Declining  NEW ENTRY?: No
DESIGNATION: Scheduled Monument, LB grade II  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Vandalism  LIST ENTRY NUMBER: 1006898  TREND: Declining  NEW ENTRY?: No
Generally unsatisfactory with major localised problems  TREND: Declining  PRINCIPAL VULNERABILITY: Vandalism  NEW ENTRY?: No
problems  PRINCIPAL VULNERABILITY: Vandalism  NEW ENTRY?: No
DWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760
Lumber Hill bowl barrow, 720m ENE of Chippenham Stud, Chippenham
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020395
Generally unsatisfactory with major localised TREND: Declining problems
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: Yes
DWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760
Bowl barrow 450m east of Shelford Farm, Haddenham
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020398
CONDITION: Extensive significant problems TREND: Declining
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No
DWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760
Long barrow at Foulmire Fen, 140m north west of the junction of Back and Small Fen Drove, Haddenh
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019983
EXTENSIVE SIGNIFICANT PROBLEMS  TREND: Declining
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No
DWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760
Oval barrow and round barrow at Small Fen, 250m north of the junction of Back and Small Fen Drove, Haddenham
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019984
Generally unsatisfactory with major localised TREND: Declining problems
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No
DWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760
Round barrow at Small Fen, 220m east of the junction of Back and Small Fen Drove, Haddenham
Round barrow at Small Fen, 220m east of the junction of Back and Small Fen Drove, Haddenham  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019986
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019986
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019986

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Three bowl barrows 450m and 570m east of Ne Haddenham	w England, part of the	e Haddenham round barrow cemeter
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019982
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Two bowl barrows 370m and 505m south of Ne Haddenham	w England, part of th	e Haddenham round barrow cemeter
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019985
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman settlement, Lode		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006793
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman site near Old Fordey Farm, Barway, Soha	ım	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006885
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Settlement site south of Tiled House Farm, Street	ham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006795
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Long barrow at South Fen, 90m south west of th	e west end of Ryman	nmoor Long Turning, Sutton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019988
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Long barrow at South Fen, 180m south east of B	etween Ditches Dro	ve, Sutton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009994
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	1 6 6		
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

### Note				
Extensive significant problems PRAND No Declining PRAND No Commercial company No Commerc	SITE NAME:	Round barrow 690m SSW of Stocking Drove F	arm, Sutton	
REMORAL VALUE ABOUT TO COMMERT THE COMMERT AND EXTENSIVE A	DESIGNATION:	•		1019987
OWNERTYPE         Commercial company         CONTACT         David Kenny 01223 582760           SITE MANDS         Scheduled Monument         UST CHITTMANDSCR.         1020843           CONCTION         Extensive significant problems         MENONAL MARKAMITY         Declining           OWNER TYPE         Arable ploughing         MENONAL MARKAMITY         David Kenny 01223 582760           SITE MANDS         Long barrow 410m south east of Partridge Hall Farm.         SWERTHAMEN         1020842           CONCRITION         Scheduled Monument         LIST MINISTRAMEN         1020842           CONCRITION         Extensive significant problems         NO         NO           DEMONDATION OF A TRABLE ploughing         NO         NO           PRINCIPLA WULK MARIUTY         Arable ploughing         NO         NO           PRINCIPLA WULK MARIUTY         Arable ploughing         NO         NO           PERLAND         Scheduled Monument         LIST MINISTRAMEN         NO           CONTROLL         Scheduled Monument         LIST MINISTRAMEN         NO           CONTROLL         Scheduled Monument         LIST MINISTRAMEN         NO           CONTROLL         Scheduled Monument         LIST TRIVIAL MARIUM         NO           CONTROLL         Scheduled Monument	CONDITION:	Extensive significant problems	TREND:	Declining
OWNERTYPE         Commercial company         CONTACT:         David Kenny 01223 582760           SITE NAMES         Long barrow 650m NNW of Lythel's Farm, Swafffaur         Bulbeck         1020843           CONDITION         Scheduled Monument         LOT OFTER NAMED         020843           CONDITION         Extensive significant problems         175000         David Kenny 01223 582760           CONDITION         Anable ploughing         No         Anable Ploughing         May NEW	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
ECREMENTON: Scheduled Monument Problems TREND Declining  MINIORAL VALUEMBRABUTY: Arable ploughing New DETRY: No  OWNER FITTH: Commercial company, multiple owners CENTACTIC  OWNER FITTH: Long barrow 410m south east of Partridge Hall Farm, Swaffham Prior  CORRECTION: Scheduled Monument LOT DUTTY NUMBER: 1020842  CONGRICON: Scheduled Monument LOT DUTTY NUMBER: 1020842  CONGRICON: Scheduled Monument LOT DUTTY NUMBER: 1020842  CONGRICON: Commercial company, multiple owners CONTACT: David Kenny 01223 582760  FENILAND: TREND: Declining  MINIORAL VALUEMBRABUTY: Arable ploughing New BETTATY: No  OWNER FITTE COMMERCIAL SCHEDULE SCHEDUL	OWNER TYPE:		CONTACT:	David Kenny 01223 582760
CONCETTION Extensive significant problems TRANC Declining PRINCEAR VILLINEARI TYPE  Arable ploughing New Manurem  COMMENTIFIES	SITE NAME:	Long barrow 650m NNW of Lythel's Farm, Swa	affham Bulbeck	
PRENCEDUL VILLIA REPORT LITTLE COMMERCIAL COMMERCIAL PROJUGITION OF TENDE OF TENDEE OF TENDE OF TENDE OF TENDE OF TENDE OF TENDE OF TENDE OF TENDEE OF TENDE OF TENDE OF TENDE OF TENDE OF TENDE OF TENDE OF TENDEE OF TENDE OF TEND	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020843
COMMERTIFIC  Commercial company, multiple owners  CONTACT: David Kenny 01223 582760  STENAME Long barrow 410m south east of Partridge Hall Farm, Swaffham Prior DESCRIATION Scheduled Monument LST ENTRY NUMBERS 1020842  CONDITION Extensive significant problems New Owner Three Commercial company, multiple owners CONTACT: David Kenny 01223 582760  FENLAND  STENAME Bowl barrow 200m south east of Horseley Fen Farm, Chatteris DESCRIATION Scheduled Monument LST ENTRY NUMBERS CONTACT: David Kenny 01223 582760  FENLAND  STENAME Bowl barrow 200m south east of Horseley Fen Farm, Chatteris DESCRIATION Scheduled Monument LST ENTRY NUMBERS CONTACT: David Kenny 01223 582760  FENLAND  STENAME Bowl barrow 250m south of Honey Farm, Chatteris DESCRIATION Scheduled Monument CONDITION Scheduled Monument Stename Scheduled Monument Descriation Scheduled Monument Scheduled Monument Descriation Descriation Scheduled Monument Descriation Descriatio	CONDITION:	Extensive significant problems	TREND:	Declining
DESCRIATION Scheduled Monument UST ENTRY NUMBER 1020842  CONDITION Extensive significant problems TREND: Declining  RENDER VAUDERWAULT Arable ploughing NEW ENTRY: NO NO NOTACT: DAVID Kenny 01223 582760  FENLAND  STENAME: Bowl barrow 200m south east of Horseley Fen Farm., Chatteris  PERSONATION Scheduled Monument UST ENTRY NUMBER 1011723  CONDITION Extensive significant problems TREND: Declining  RENDEATIVE: Arable ploughing NEW ENTRY: NO NO NOTACT: DAVID Kenny 01223 582760  STENAME: Bowl barrow 200m south east of Horseley Fen Farm., Chatteris  PERSONATION Scheduled Monument UST ENTRY NUMBER 1011723  CONDITION Extensive significant problems TREND: Declining  RENDEATIVE: Commercial company CONTACT: DAVID Kenny 01223 582760  STENAME: Bowl barrow 250m south of Honey Farm, Chatteris  DESCRIATION Scheduled Monument UST ENTRY NUMBER 1020393  STENAME: Bowl barrow 580m east of Mount Pleasant Bridge. Chatteris  DESCRIATION Scheduled Monument UST ENTRY NUMBER 1020394  STENAME: Bowl barrow 580m east of Mount Pleasant Bridge. Chatteris  DESCRIATION Scheduled Monument UST ENTRY NUMBER 1020394  STENAME: Bowl barrow 580m east of Mount Pleasant Bridge. Chatteris  DESCRIATION Scheduled Monument UST ENTRY NUMBER 1020394  CONDITION Extensive significant problems INFROD Declining  RENDER VALUERRABILITY: Arable ploughing NEW ENTRY: No  OWNER TITE: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESCRIATION Scheduled Monument UST ENTRY NUMBER 1011718  CONDITION Extensive significant problems RENDD Declining  RENDER VALUERRABILITY: Arable ploughing NEW ENTRY: NO  OWNER TITE: DAVID RENDER 1011718  CONDITION Extensive significant problems RENDD Declining  RENDER VALUERRABILITY: Arable ploughing NEW ENTRY: NO  OWNER TITE: DAVID RENDER 1011718  CONDITION Scheduled Monument UST ENTRY NUMBER 1011718  CONDITION Scheduled	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESCANATION  Scheduled Monument  Extensive significant problems  TREND: Declining  MINIORAL WALNERABULTY Arable ploughing  OWNER TITE:  Commercial company, multiple owners  CONTACT: David Kenny 01223 582760  FENLAND  FENLAND  BOWL barrow 200m south east of Horseley Fen Farm, Chatteris  DESCONATION Scheduled Monument SET ENTRY NALMBER: DESCONATION Extensive significant problems  REND: Declining  REND: Desconation  Scheduled Monument UST ENTRY NALMBER: DESCONATION Scheduled Monument UST ENTRY NALMBER: DESCONATION Extensive significant problems  REND: Desconation Scheduled Monument UST ENTRY NALMBER: DESCONATION Scheduled Monument UST ENTRY NALMBER: DESCONATION Scheduled Monument UST ENTRY NALMBER: DESCONATION Scheduled Monument REND: Declining  NEW ENTRY: No  OWNER TITE Mixed, multiple owners CONITACT: David Kenny 01223 582760  SITE NAME BOWL barrow 580m east of Mount Pleasant Bridge, Chatteris DESCONATION Scheduled Monument UST ENTRY NALMBER: Descining NEW ENTRY: No OWNER TYTE: Religious organisation CONTACT: David Kenny 01223 582760  STE NAME Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris DESCONATION Scheduled Monument UST ENTRY NALMBER: 1009993  Extensive significant problems REND: Declining PRINCIPAL WALNERABUTY: Arable ploughing NEW ENTRY: No OWNER TYTE: Religious organisation CONTACT: David Kenny 01223 582760  STE NAME Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris DESCONATION Scheduled Monument UST ENTRY NALMBER: Declining PRINCIPAL WALNERABUTY: No OWNE	OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760
CONDITION     REVENDED SETTINGEN SITE STATE NUMBERS  CONTRECTOR  SITE NAME  BOWL BARRYON  SETTINAME  BOWL BARRYON  SOMER TYPE  CONDITION  SITE NAME  BOWL BARRYON  SOMER TYPE  BOWL BARRYON  SHENAME  BOWL BARRYON  SCHOOLING MIXED AND BARRYON  SOMER TYPE  BOWL BARRYON  SCHOOLING MIXED AND BARRYON  SOMER TYPE  BOWL BARRYON  SHENAME  BOWL BARRYON  SOMER TYPE  BOWL BARRYON  MIXED, MIX	SITE NAME:	Long barrow 410m south east of Partridge Hall	Farm, Swaffham Prior	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No Commercial company, multiple owners CONTACT: David Kenny 01223 582760  FENLAND  STE NAME: Bowl barrow 200m south east of Horseley Fen Farth Chatteris  DESIGNATION Scheduled Monument LET ENTRY NUMBER 1011723  CONDITION Extensive significant problems TERNO: Declining  WINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No Declining  STE NAME: Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATION: Scheduled Monument LET ENTRY NUMBER 1020393  CONDITION: Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1020393  CONDITION: Extensive significant problems IRENO: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  STE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems IRENO: Declining  STENAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems IRENO: Declining  STENAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument  CONDITION: Extensive significant problems IRENO: David Kenny 01223 582760  STE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument  CONDITION: Extensive significant problems IRENO: David Kenny 01223 582760  STE NAME: No Declining  STENAME: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020842
COMMERTIFIE Commercial company, multiple owners CONTACT: David Kenny 01223 582760  FENLAND  STERNAME Bowl barrow 200m south east of Horseley Fen Farm, Chatteris  DESIGNATIONS Scheduled Monument IIST ENTRY NUMBER 1011723  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEWENTRY: No  OWNER TYPE Commercial company CONTACT: David Kenny 01223 582760  STERNAME Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATIONS Scheduled Monument ILST ENTRY NUMBERS 1020393  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEWENTRY: No  OWNER TYPE Mixed, multiple owners CONTACT: David Kenny 01223 582760  STERNAME Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATIONS Scheduled Monument ILST ENTRY NUMBERS 1020394  CONDITIONS Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE Religious organisation CONTACT: David Kenny 01223 582760  STERNAME Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATIONS Scheduled Monument ILST ENTRY NUMBERS 1011718  CONDITIONS Extensive significant problems TREND: David Kenny 01223 582760  STERNAME Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION Scheduled Monument ILST ENTRY NUMBERS 1011718  CONDITIONS Extensive significant problems TREND: David Kenny 01223 582760  STERNAME Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION Scheduled Monument ILST ENTRY NUMBERS 1011718  CONDITIONS Extensive significant problems TREND: David Kenny 01223 582760  STERNAME Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATIONS Scheduled Monument ILST ENTRY NUMBERS 1009993  CONDITIONS Scheduled Monument ILST ENTRY NUMBERS 1009993  CONDITIONS Scheduled Monument ILST ENTRY NUMBERS 1009993	CONDITION:	Extensive significant problems	TREND:	Declining
FENLAND  SITE NAME  Bowl barrow 200m south east of Horseley Fen Farm, Chatteris  DESIGNATION  Scheduled Monument  LIST ENTRY NUMBER  ID11723  CONDITION  Extensive significant problems  TREND  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY!  No  OWNER TYPE:  Commercial company  CONDITION  Scheduled Monument  LIST ENTRY NUMBER  ID20393  CONDITION  Scheduled Monument  LIST ENTRY NUMBER  ID20393  CONDITION  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY: No  OWNER TYPE:  Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION  Scheduled Monument  LIST ENTRY NUMBER  ID20394  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  OWNER TYPE: Religious organisation  CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION  Scheduled Monument  LIST ENTRY NUMBER: 1011718  Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  OWNER TYPE: Religious organisation  CONTACT: David Kenny 01223 582760  SITE NAME: Declining  NEW ENTRY: No  OWNER TYPE: Religious organisation  CONTACT: David Kenny 01223 582760  SITE NAME: No  OWNER TYPE: Religious organisation  CONTACT: David Kenny 01223 582760  SITE NAME: No  OWNER TYPE: Religious organisation  CONTACT: David Kenny 01223 582760  SITE NAME: No  OWNER TYPE: No  Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
STENAME Bowl barrow 200m south east of Horseley Fen Farm, Chatter's  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011723  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 250m south of Honey Farm, Chatter's  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020393  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatter's  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatter's  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011718  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: No  OWNER TYPE: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatter's  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009993  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatter's  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009993  Generally unsatisfactory with major localised TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  Declining	OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011723  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020393  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011718  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	FENLAND			
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020393  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020394  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: No  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  TREND: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Arable ploughing NEW ENTRY: No  DESIGNATION: Arable ploughing NEW ENTRY: Number: 1009993	SITE NAME:	Bowl barrow 200m south east of Horseley Fen	Farm, Chatteris	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020393  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011723
OWNER TYPE  Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DECINING: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: David Kenny 01223 582760  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Designation: Declining PRINCIPAL VULNERABILITY: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: David Kenny 01223 582760	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Bowl barrow 250m south of Honey Farm, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020393  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011718  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1011718  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Religious organisation UST ENTRY NUMBER: 1009993  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: Number: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020393  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYY: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No	SITE NAME:	Bowl barrow 250m south of Honey Farm, Chat	tteris	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020393
OWNER TYPE:  Mixed, multiple owners  CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: Religious organisation  CONTACT: David Kenny 01223 582760  Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: Religious organisation  CONTACT: David Kenny 01223 582760  TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Designation: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  Declining  TREND: Declining  PRINCIPAL VULNERABILITY: No Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  NO DECLINING  CONDITION: REND: Declining  PRINCIPAL VULNERABILITY: No Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020394  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Bowl barrow 580m east of Mount Pleasant Brid	lge, Chatteris	
PRINCIPAL VULNERABILITY: Arable ploughing New Entry?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020394
OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME:  Bowl barrow 600m west of Honey Hill Farm, Chatteris  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I 011718  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No  CONTACT:  David Kenny 01223 582760  SITE NAME:  Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I 009993  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011718  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582760
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	SITE NAME:	Bowl barrow 600m west of Honey Hill Farm, C	Chatteris	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011718
OWNER TYPE: Religious organisation CONTACT: David Kenny 01223 582760  SITE NAME: Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME:  Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1009993  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009993  CONDITION: Generally unsatisfactory with major localised problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582760
CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No	SITE NAME:	Neolithic enclosures at Grey's Farm, Horseley	Fen, Chatteris	
problems  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009993
1 0 0	CONDITION:		TREND:	Declining
OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:		CONTACT:	David Kenny 01223 582760

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 500m south of Bunting's Farm,	Whittlesey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020847
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Suet Hills round barrow cemetery, Whittless	<b>Э</b>	
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020844
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Romano-British settlement near Honeybridg	e, Wimblington / Chatter	is
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006906
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bowthorpe, Wisbech, Wisbech		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
vulnerability:	Low	CONTACT:	Nicola Duncan-Finn (LPA) 01354 622321
SITE NAME:	Chatteris		
DESIGNATION:	Conservation Area, 100 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Nicola Duncan-Finn (LPA) 01354 622321
SITE NAME:	March		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Nicola Duncan-Finn (LPA) 01354 622321
SITE NAME:	Whittlesey		
DESIGNATION:	Conservation Area, 63 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Nicola Duncan-Finn (LPA) 01354 622321
SITE NAME:	Wisbech		
DESIGNATION:	Conservation Area, 230 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
			N. I. D
VULNERABILITY:	Low	CONTACT:	Nicola Duncan-Finn (LPA) 01354 622321

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

#### **HUNTINGDONSHIRE**



© Historic England

SITE NAME: Great Gransden Windmill, Great Gransden DESIGNATION: CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY:

1006820

Scheduled Monument, LB grade E (C) Local authority

Constructed c1612, Great Gransden is allegedly, the oldest remaining mill in England. Building contains a flour dressing machine with the inscription 'IL 1774 RW'. A comprehensive survey shows that the mill is in poor condition. Consent for emergency repairs was granted, including dismantling of sails for safety reasons, in late 2013. Some emergency works completed in 2014. Historic England grant offered and repair work commenced in May 2016. Discussions on-going regarding formation of local Trust.

Contact: Trudi Hughes 01223 582739

Contact: Trudi Hughes 01223 582739

	SI
	D
	C
1 4	0
	PF
=1	0

OWNER TYPE:

SITE NAME:

LIST ENTRY NUMBER:

ITF NAME: St Andrew's Church, Church End, Wood Walton ESIGNATION: Listed Building grade II\* ONDITION: Poor CCUPANCY: N/A RIORITY CATEGORY: C (C) WNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1130123

Former church with CI3 south arcade of nave, CI4-CI5 west tower, C14 chancel, C16 north arcade much rebuilt 1856-9. Coursed limestone rubble, limestone dressings, plain tile roof. Very isolated. High level repairs were completed to tower and roofs in 2013. Building still thought to be moving and currently undergoing structural monitoring. We are not aware of any changes in this situation.

© Historic England

Church of St Thomas, Herne

Road, Ramsey DESIGNATION: Listed Place of Worship grade II

CONDITION: Poor

Parish church built in 1869 by subscription. Nave with polygonal east end, north west bell turret. Gault brick, slate roof. Early English fenestration. High level general mortar failure in brickwork and around windows with some cracking visible. Plant growth taking hold in porch and rainwater goods.



© Historic England

PRIORITY CATEGORY:	C (C)	3
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1330457	Contact: Claire Fidler 01223 582735

SITE NAME:         Roman site, Rushey Farm, Great Staughton           DESIGNATION:         Scheduled Monument         UST ENTRY NUMBER:         1006866           CONDITION:         Generally unsatisfactory with major localised problems         TREND:         Declining           PRINCIPAL VULNERABILITY:         Arable ploughing         NEW ENTRY):         No           OWNER TYPE:         Commercial company         CONTACT:         David Kenny 01223 582760           SITE NAME:         Monk's Hole barrow, 630m NNE of Monk's Wood Farm, Sawtry         Wistername Sawtry           CONDITION:         Scheduled Monument         UST ENTRY NUMBER:         1015007           CONDITION:         Extensive significant problems         TREND:         Declining           PRINCIPAL VULNERABILITY:         Arable ploughing         NEW ENTRY):         No           OWNER TYPE:         Site of Sawtry Judith village adjoining Archers Wood, Sawtry         Switz         David Kenny 01223 582760           SITE NAME:         Site of Sawtry Judith village adjoining Archers Wood, Sawtry         Switz         1006816           CONDITION:         Extensive significant problems         TREND:         Declining           CONDITION:         Extensive significant problems         TREND:         Declining           CONDITION:         Extensive significant problems <th></th> <th></th> <th></th> <th></th>				
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Monk's Hole barrow, 630m NNE of Monk's Wood Farm, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015007  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No	SITE NAME:	Roman site, Rushey Farm, Great Staughton		
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Monk's Hole barrow, 630m NNE of Monk's Wood Farm, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015007  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006866
OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Monk's Hole barrow, 630m NNE of Monk's Wood Farm, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015007  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:		TREND:	Declining
SITE NAME: Monk's Hole barrow, 630m NNE of Monk's Wood Farm, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015007  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015007  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Monk's Hole barrow, 630m NNE of Monk's Wood	Farm, Sawtry	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015007
OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760  SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Site of Sawtry Judith village adjoining Archers Wood, Sawtry  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006816  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Site of Sawtry Judith village adjoining Archers Wood	d, Sawtry	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006816
	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582760	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:Moated site in Prestley Wood, 800m north east of Cartwright's Farm, The StukeleysDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1017843CONDITION:Generally satisfactory but with significant localised problemsTREND:StablePRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Moated site in Toseland Wood, ToselandLIST ENTRY NUMBER:1017881CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1017881CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - moderateNEW ENTRY?:NoOWNER TYPE:Commercial companyCONTACT:Claire Fidler 01223 582735				
CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Scrub/tree growth  OWNER TYPE: Private  Moated site in Toseland Wood, Toseland  DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - moderate  TREND: Stable  Stable  New ENTRY: No  David Kenny 01223 582760  LIST ENTRY NUMBER: 1017881  TREND: Declining  New ENTRY: No	SITE NAME:	Moated site in Prestley Wood, 800m north east of Cartwright's Farm, The Stukeleys		
PRINCIPAL VULNERABILITY: Scrub/tree growth New Entry: No OWNER TYPE: Private CONTACT: David Kenny 01223 582760  SITE NAME: Moated site in Toseland Wood, Toseland  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017881  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017843
OWNER TYPE: Private CONTACT: David Kenny 01223 582760  SITE NAME: Moated site in Toseland Wood, Toseland  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017881  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY?: No	CONDITION:		TREND:	Stable
SITE NAME: Moated site in Toseland Wood, Toseland  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017881  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017881  CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No	OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - moderate  NEW ENTRY?:  No	SITE NAME:	Moated site in Toseland Wood, Toseland		
problems  PRINCIPAL VULNERABILITY: Animal burrowing - moderate  NEW ENTRY:: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017881
C C C C C C C C C C C C C C C C C C C	CONDITION:		TREND:	Declining
OWNER TYPE: Commercial company CONTACT: Claire Fidler 01223 582735				
	PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No

#### SOUTH CAMBRIDGESHIRE



© Historic England

SITE NAME:	Little Chishill Mill, Barley Road, Great and Little Chishill
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER: 1330927 Post mill, possibly rebuilt 1819, scratching on stud 1712, main post renewed 1868 and dated underneath mill. Patent sails c1912-16 replacing former canvas covered sails. Timber-framed, weather boarded and painted with brick piers. The main structure extends to the rear housing the bolter; restored fantail on ladder. The mill was last used in 1951, and was repaired in 1966. The buck is leaking and requires new weatherboarding. Mill transferred to the Great Chishill Windmill Trust who are preparing to carry out external repairs to the buck.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Large tannery building at Hutchins and Harding Ltd, High Street (east side), Sawston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1127985

C19 timber-framed skin drying shed with adjustable timber louvered walls. Major areas of roof and south and west walls exposed and admitting rain. Internal boarded floors in very bad condition and partly collapsed. Redundant and at immediate risk of further deterioration or loss of fabric. Urgent Works Notice served, scaffolding and weather protection in place. Detailed survey about to begin.

Contact: Robert Parkinson 01223 582733



© Historic England

SITE NAME:	Parish Church of St Nicolas, Great and Little Chishill
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Religious organisation
LIST ENITRY NILIMBER:	1142491

Parish church. C12 chancel, extended in C13 or early C14. Late C14 tower with C16 belfry windows. Late C14 nave and south porch. C19 restoration included replacement of C15 nave windows and building of pyramidal tower roof structure. Memorial glass by Kempe 1916, in east window. Batten failure on nave roof; tiles slipping. Parish architect and builder carried out detailed inspection and an application to the Heritage Lottery Fund Grants for Places of Worship is anticipated.

Contact: Trudi Hughes 01223 582739

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England

© Historic England

© Historic England

SITE NAME:	Parish Church of St Swithun, Barley Road, Great and Little Chishill
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1128142

Worship has been offered and the works are currently in the development phase.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Church of St Mary, High Street, Great Eversden
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1127621

Parish church rebuilt after a fire in 1466, with further restorations in 1864 and 1920. Construction materials consist of Fieldstone, clunch rubble and dressings of clunch and limestone with a tiled roof. West tower, nave and chancel. Serious structural movements. A Heritage Lottery Fund Grants for Places of Worship grant was offered in 2015 for repairs to north slopes of chancel and nave roofs, high level masonry and north porch. Repair works underway.

C13 nave and chancel. Late C14 south aisle. C15 tower. Tower collapsed in 1892; rebuilt 1897, at which time the nave and aisles were restored by F E Penrose. Early C20 vestry and organ chamber. Repairs including stabilising south porch and part renewal of drainage completed 2014. However, water ingress and possible on-going movement over tower arch is causing on-going decay to stonework internally, with cracking in other parts of church. Funding from the Heritage Lottery Fund Grants for Places of

Contact: Robert Parkinson 01223 582733



SITE NAME:

Church of St Andrew,
Burgoynes Road, Impington

DESIGNATION:

Listed Place of Worship grade I

CONDITION:

Very bad

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1178832

Early C13 nave and tower, upper stages rebuilt C14, and rood stair. South porch C15, chancel rebuilt during restoration of 1878, dated rainwater heads. Walls of Barnack limestone with limestone and pebble rubble. Timber framed porch. Plain tile roofs with gable parapets to nave and chancel with cross finials. South elevation has a three stage tower with Barnack limestone quoins. Severe cracks in tower and nave monitored 1999-2012. Movement stabilised after removal of trees pre-2009.

Contact: Robert Parkinson 01223 582733



SITE NAME:	Church of St Giles, Potton Road, Tadlow
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1317879

Parish church. C13 nave and chancel and C14 west tower. Restored c1860 under supervision of W Butterfield. Fieldstone, clunch rubble with limestone and clunch dressing. Plain tiled roof. West tower of three stages. Crack to second stage of tower on east face. Some displacement and cracking to buttress on north wall adjacent to infilled north door. Further crack to north side of east gable. Cracking to stonework and extensive ivy growth reported, deterioration continues.

Contact: David Grech 01223 582717

© Historic England

SITE NAME:	John O'Gaunt's House: a motte castle and moated s Kneesworth	ite 300m north ea	st of Haygate Farm, Bassingbourn cum
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010865
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
	, ,		,
SITE NAME:	Sites revealed by air photography, Bassingbourn cur	n Kneesworth	<u> </u>
SITE NAME: DESIGNATION:	· ·	n Kneesworth LIST ENTRY NUMBER:	1006881
	Sites revealed by air photography, Bassingbourn cur		1006881 Declining
DESIGNATION:	Sites revealed by air photography, Bassingbourn cur Scheduled Monument	LIST ENTRY NUMBER:	

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Settlement site west of Town's End Farm, Comb	erton / Barton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006879	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Settlement site by Caudle Corner Farm, Fulbour	n		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006878	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
ITE NAME:	Site revealed by aerial photography west of Whi	te Hill Farm, Great Sh	nelford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006891	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760	
ITE NAME:	Causewayed enclosure 900m west of Great Wilbraham parish church, Great Wilbraham			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009103	
CONDITION:	Extensive significant problems	TREND:	Declining	
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Henge 220m ESE of Herring's House, Great Wil	Henge 220m ESE of Herring's House, Great Wilbraham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011716	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760	
ITE NAME:	Bowl barrow 550m north east of Slip End Farm,	Guilden Morden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017328	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
ITE NAME:	Roman villa 1000yds (910m) north east of Ashw	ell village, Guilden Mo	orden	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006876	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Settlement complex north east of Haslingfield, H	aslingfield / Grantche	ster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006867	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

TEKLLAGE AT KISK 2016 / EAS	OF ENGLAND / SOUTH CAMBRIDGESHIRE		
SITE NAME:	Roman villa site south of Rose Villa, Ickleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006872
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bowl barrow 205m SSE of Lodge Cottage, Melbour	rn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011720
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bowl barrow, known as Grinnel Hill, 260m SSE of	Lodge Cottage, Me	lbourn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011719
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Five bowl barrows 790m north west of Chain Hou	se, part of the Ove	r round barrow cemetery, Over
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019874
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Three bowl barrows 380m south of Brownshill Sta	unch House, part c	of the Over round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019130
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Borough Hill: a large multivallate hillfort, Sawston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009396
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman site north of Brown Spinney, Shepreth / Fo	xton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006873
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Arrington Bridge Romano-British site, Shingay cum	Wendy / Whaddo	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006874
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Wandlebury Camp: a multivallate hillfort, earlier ur formal garden remains, Stapleford	nivallate hillfort, Iro	n Age cemetery and 17th century
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1009395
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bell barrow 500m south of Morden Grange Plantat	ion, Steeple Morde	en
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011714
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman settlement south of Chronicle Hills, Whittl	esford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006794
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Duxford Airfield, Duxford/Whittlesford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Juliette Wilson (LPA) 01954 712907
SITE NAME:	Gamlingay		
DESIGNATION:	Conservation Area, 20 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Juliette Wilson (LPA) 01954 712907
SITE NAME:	Papworth Everard		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Juliette Wilson (LPA) 01954 712907
SITE NAME:	Papworth Everard - village		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Juliette Wilson (LPA) 01954 712907

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Sawston		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Juliette Wilson (LPA) 01954 712907

#### **CENTRAL BEDFORDSHIRE (UA)**



© Historic England

SITE NAME:	Priory House (Council Offices), High Street south, Dunstable
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1114593 C18, cement rendered C19. Mansard Welsh slated roof. 2 storeys and attic. 4 round-headed windows with archivolts and keystones. Red brick, stone dressings and in-and-out quoins. Pedimented Roman Doric door case. On site of Priory guesthouse. Contains complete medieval clunch undercroft from former guesthouse and some pre-Georgian cellars. Complex structural movement and dampness issues. Following reconnaissance survey and detailed advice from Historic England, the Town Council have been awarded a Heritage at Risk grant for a detailed study to examine condition and find solutions.

Contact: Trudi Hughes 01223 582739

Contact: Clare Campbell 01223 582738



© Historic England

SITE NAME:	The Grotto, Woburn Park, Woburn
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1114010


Grotto, 1839, situated approximately 200 metres to the north east of Woburn Abbey, on the northern edge of the  $\ensuremath{\text{C18}}$  and early  $\ensuremath{\text{C19}}$  pleasure grounds. Repair works have been completed. However, the grotto work lining has delaminated in places. Discussions are on going.



© Historic England

SITE NAME:	Church of St Peter and All Saints, Battlesden
DESIGNATION:	Listed Place of Worship grade I, RPG grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1311979

Medieval church of C13 origins. Little restored. Rubble walls with later brick to both C18 tower and parapets (modern). Tower cracked and stonework much decayed.



Religious organisation

C (C)

1114060

© Historic England

	Parish church C14 and C15, reworked 1891 by E
	Browning. Coursed ironstone rubble and cobbles, with
*	ashlar dressings. Tower completely of ashlar. Stonework in
Α.	poor condition, including decayed tracery to south aisle
	windows adjacent to porch and south aisle wall. Decayed
	windows to north aisle; decayed clunch to tower stair;
	internal delamination at base of piers due to damp; decay
	to south side chancel, sedilia and low level plaster and high
	level paint delamination to chancel.
	Contact: Robert Parkinson 01223 582733

Contact: Trudi Hughes 01223 582739

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of All Saints, High Street, Houghton Regis
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1114707

Battlemented chequerwork flint and Totternhoe stone. Some C14 work in chancel and arcades which have octagonal shafts, moulded bases and capitals. Remainder of the church Perpendicular although most of the windows are C19. C15 nave roof. External masonry windows and roofs in need of repair.

Contact: Robert Parkinson 01223 582733

© Historic England

© Historic England



SITE NAME:	Church of St Mary the Virgin, Church Road, Meppershall
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1313500

Parish church dating to C12 and half rebuilt 1875-6 by Sir Arthur Blomfield. Stonework of coursed ironstone with ashlar dressings and clay tile roofs. Chancel, central tower, north and south transepts, nave, north and south aisles. Decayed clunch corner stones and tracery to the south aisle chapel and vestry. Tower in need of repointing. .

Contact: Robert Parkinson 01223 582733

A ringwork and bailey castle, ring ditch and enclosures east of Brookland Farm, Biggleswade			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010115
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Moated site at Ivy Hall, Cranfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009592
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Apsley Bury moated site and fishpond, south of Ap	sley End, Shillingtor	1
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1010927
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bowl barrow in Tingley Field Plantation, near Pegsdon, Shillington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010369
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
	00.007 0.00 8.0 110.1		

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

**ABBREVIATIONS** 

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Totternhoe Castle: a motte and bailey castle, medieval quarries and cultivation terraces, Totternhoe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020772
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	David Kenny 01223 582760

#### **ESSEX**

#### **BRAINTREE**



Codham Mill and Mill House, SITE NAME: Codham's Lane, Wethersfield DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (New entry) OWNER TYPE: Private

A timber-framed water mill with an integral dwelling thought to date to the mid-late C18. The mill building is little altered, and retains its water wheel, primary and secondary gearing and the great majority of its milling machinery. The water management system on the site is also unaltered making this ensemble of buildings, machinery and watercourses an extremely rare survival. Continuing concern over condition of mill. Local Authority monitoring.

© Historic England

LIST ENTRY NUMBER: 1123325 Contact: Trudi Hughes 01223 582739



SITE NAME: Parish Church (dedication unknown), Hall Road, Borley DESIGNATION: Listed Place of Worship grade I CONDITION: Very bad PRIORITY CATEGORY: F (F) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1169675

Church on an early manorial site, with Saxon fabric surviving in the nave. The interior has several monuments, and wall paintings are believed to be present below later limewash. The plain tiled roofs are deteriorating; many have slipped, fractured and delaminated, especially on the north side. Daylight is visible from inside through the chancel roof. Á Heritage Lottery Fund Grants for Places of Worship grant to re-roof the nave and chancel was awarded in 2016. The project development stage is underway.

Contact: Trudi Hughes 01223 582739



SITE NAME:	Church of St Mary, Church Road, Ovington
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1277192

This church dates from the C12, with C14, C15, and C16 alterations. The continuous nave and chancel roof is tiled, and has a canted plaster ceiling. There is outward movement and cracking in the north and south walls. Deformation in the roof structure and discontinuity between it and the wall plates, cracking in the ceiling, and wind-driven rainwater penetration of the roof slopes are probably causing progressive failure of the battens and tile fixings.

Contact: Malcolm Starr 01223 582723

© Historic England

© Historic England



© Historic England

SITE NAME:	Parish Church of All Saints, The Street, Stisted
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1123870

Parish church of C12 origins, with C13 and C14 additions. Some C19 restoration. A very unusual plan; the tower abutting the south side of the nave, leaving the west end as an uninterrupted symmetrical composition. Cedar shingles to the tower are in poor condition with daylight visible from inside. Masonry of tower buttresses poor, as is the nave roof, with visible decay in the rafter feet and wallplate. A Heritage Lottery Fund Grants for Places of Worship grant was accepted in February 2014. The project is in development stage.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Circular cropmark at Ferriers Farm, 190m south	west of Hill Farm, B	ures Hamlet
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010501
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman villa 480m south east of Hill Farm, Gesting	gthorpe / Wickham S	St. Paul
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011806
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Sible Hedingham South (Swan Street), Sible Hedin	ngham	
DESIGNATION:	Conservation Area, 46 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Emma Goodings (LPA) 01376 552525
SITE NAME:	Silver End		
DESIGNATION:	Conservation Area, 22 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Emma Goodings (LPA) 01376 552525

#### **BRENTWOOD**



Chantry Chapel and Mausoleum, Thorndon Park SITE NAME: Listed Building grade II\*, RPG DESIGNATION: grade II\*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

Mid C19 private Roman Catholic chapel and mausoleum of the Petre family, no longer used for worship. Designed by William Wardell and located south west of Thorndon Hall (now flats). The chapel has a leaking roof and suffers from extensive stone decay. A Historic England grant towards the project development, investigation and subsequent repair work has been offered and the repairs are anticipated to be completed by late 2016.

© Historic England LIST ENTRY NUMBER: 1293260 Contact: Malcolm Starr 01223 582723



LIST ENTRY NUMBER:

© Historic England Archive

SITE NAME:	Thoby Priory ruins, Thoby Lane, Mountnessing
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1005560 and 1293183

Contact: Deborah Priddy 01223 582720

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of St Paul, Mores Lane, Brentwood
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1207545

Parish church 1878, by E C Lee. Flint walls with stone dressings. Leaking iron gutters on stone string courses starting to cause failure in stone. Evidence of active leakage. Much Bath stone in evidence, some of which appears to be of poor quality and particularly susceptible to decay due to excess moisture.

Contact: Trudi Hughes 01223 582739

### © Historic England

### **CHELMSFORD**



		1
		Bair
		00,
Î	Î	

SITE NAME:	Church of St Michael, The Street, Roxwell
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

St Michael's Roxwell is a medieval church of probable C14 date, but much restored in the C19. Flint rubble with stone dressings, tiled roofs, timber porch and bell turret, shingled spire. The tiling of the roofs has loosened and tiles are slipping.

LIST ENTRY NUMBER: Contact: Trudi Hughes 01223 582739 1235784 © Historic England

SITE NAME:	Baddow Road		
DESIGNATION:	Conservation Area, 10 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Michael Hurst (LPA) 01245 606739
SITE NAME:	Moulsham Street		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Michael Hurst (LPA) 01245 606739
SITE NAME:	West End		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Low	CONTACT:	Michael Hurst (LPA) 01245 606739

### **COLCHESTER**



©	Historic	England
_		

SITE NAME:	Ruins of Church of St Mary, North of Birch Hall, Birch	S V
DESIGNATION:	Scheduled Monument and Listed Building grade II*	F
CONDITION:	Very bad	r
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
	1003144 11110000	,

Small Norman church dated to C12. No longer used for worship, Roofless ruin with some structural problems. Principally, the unconsolidated flint rubble walling is at risk. There is currently no public access to the site. A Conservation Management Plan has been completed, but no repair scheme has been agreed.

LIST ENTRY NUMBER: 1002144 and 1110898 Contact: David Kenny 01223 582760


### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© Essex County Council

SITE NAME:	Municipal Water Tower
	"Jumbo", Balkerne Passage
	Čolchester

DESIGNATION: Listed Building grade II\*, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: | | 123669

Monumental water tower, C19, decommissioned in the 1980s. Redundant building and local landmark. A feasibility study has been published by the Colchester and North East Essex Building Preservation Trust, and this may help to guide the search for a means of securing repair and future management.

Contact: John Neale 01223 582719



SITE NAME:	Church of St Peter, North Hill, Colchester
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | | 123570

C15 church, re-modelled C17 and with C19 alterations. Stone rubble with brick west tower of 1758, the upper two stages of which have rusticated quoins. The high level stonework is in fair condition, but the overall condition is poor as the roofs have a number of slipped slates and the interior has large areas of damp at both low and high levels, particularly in the north and south aisles.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Small multivallate hillfort known as Pitchbury Rai	mparts, Great Horkes	sley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019959
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman villa 450m south of Warren's Farm, Grea	it Tey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013516
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Remains of St Mary the Virgin's Church, Virley		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019880
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582760
SITE NAME:	Birch		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Libby Kirkby-Taylor (LPA) 01206 506374
SITE NAME:	Distillery Pond		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Libby Kirkby-Taylor (LPA) 01206 506374

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Hythe		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Libby Kirkby-Taylor (LPA) 01206 506374

### **EPPING FOREST**

The state of the s	
The state of the s	

SITE NAME: Essex Redoubt at Ongar Radio Station, North Weald Bassett / Bobbingworth DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C(C)

OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1018456

Late C19 redoubt consisting of early concrete structures and associated earthworks. Buildings at risk from failure of concrete and vandalism. Discussions with the owners and local authority currently centre on proposals to commission a Conservation Management Plan for beneficial re-use of the site as an outdoor activity centre in the context of local development proposals. These have stalled and there has been no progress in 2016.

Contact: Deborah Priddy 01223 582720

Contact: Sheila Stones 01223 582716



© Historic England

© Historic England

SITE NAME: Littlebury Farmhouse, Romford Road, Stanford Rivers DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1306771

Timber-framed house of c1540 and earlier. A lean-to roof over the single storey is not watertight and is in poor condition. The timber frame is protected by ply sheeting. The building remains unoccupied and although gutters have been cleared and vegetation cut back its condition continues to deteriorate. Discussions with owner and local planning authority are ongoing. No action/strategy identified or agreed.

© Historic England

SITE NAME: Grand Magazine, Waltham Abbey Royal Gunpowder Mills, Waltham Abbey Scheduled Monument, 2 LBs, DESIGNATION: CONDITION: Poor OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1016618 Contact: Deborah Priddy 01223 582720

A rectangular, barrel-vaulted brick structure with a smaller barrel-vaulted west "transept". Masonry has collapsed and there is extensive vegetation growth. Cracking is evident throughout the structure, with flattening to the head of the vault and extensive moisture ingress. Historic England is in discussion with the Charitable Trust over funding and maintenance of the whole site. A programme of tree clearance around the structure has been completed



© Historic England

SITE NAME: Quinan Stove, Waltham Abbey Royal Gunpowder Mills, Waltham Abbey Scheduled Monument, 2 LBs, DESIGNATION: CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D)

OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1016618

A technologically innovative building of 1935, 18 bays in length with steel hooped frames and longitudinal purlins. There is extensive evidence of steelwork corrosion and the roof and windows are deteriorating. Historic England is discussing the future management of the site with the Charitable Trust. A programme of tree clearance around the building has been undertaken.

Contact: Deborah Priddy 01223 582720

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.

Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** I PA

Conservation Area Listed Building Local Planning Authority National Park ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of St Nicholas, Willingale Road, Fyfield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1337250

C12 church, central tower incorporating re-used Roman materials, but displaying problems with eroded quoins and open joints.

© Historic England

l l	
9	

SITE NAME:	Church of St Mary the Virgin, The Street, High Ongar
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1111302

A largely mid-C19 church with some medieval features surviving internally. Nave and chancel roofs show signs of batten failure and on-going tile losses. Patching has been completed using concrete plain tiles to rear of tower, on chancel verge and elsewhere. Probable batten and tile fixing failure resulting in continuing losses of tiles. Nave and chancel require re-roofing. Church has received a Listed Places of Worship Roof Repairs grant to re-roof the nave and chancel.

Contact: Trudi Hughes 01223 582739

Contact: Malcolm Starr 01223 582723

© Historic	England
------------	---------

SITE NAME:	A London mobilisation centre known as the North	Weald Redoubt, N	North Weald Bassett / Bobbingworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018456
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Deborah Priddy 01223 582720
SITE NAME:	Waltham Abbey Royal Gunpowder Factory, Waltha	ım Abbey	
DESIGNATION:	Scheduled Monument, 2 LBs, CA	LIST ENTRY NUMBER:	1016618
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Deborah Priddy 01223 582720

### **HARLOW**



SITE NAME:	Kingsmoor House, Paringdon Road
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (A)
OWNER TYPE:	Private

This stuccoed two storey building is a late C19 rebuild of a C18 house. It has a parapet extending round a compassed window and a peg-tiled roof surmounted by two tall elegant red brick chimneys. The building suffers from serious chronic problems resulting from water penetration and inadequate ventilation that led to critical dry rot. The building is currently undergoing conversion to apartments under a recent change of ownership

LIST ENTRY NUMBER: 1337043 Contact: Sheila Stones 01223 582716 © Historic England

SITE NAME:	Roman villa 500m north east of Harlowbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014738
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### **MALDON**



© Historic England

SITE NAME:	Creeksea Place, Ferry Road, Creeksea, Burnham-on-Crouch
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1123776

Former Elizabethan courtyard house completed in 1569, but the south range was demolished in 1740 and the east range rebuilt in the C19. The house suffers from major structural problems and is extensively propped internally. In recent years the owners have stabilised the building, brought parts into use and carried out some repairs, but comprehensive works are still required. The condition of the garden walls and the main roofs are of particular concern. Historic England has offered a grant towards project development and the consultants are now producing a scheme.

Contact: Malcolm Starr 01223 582723

		6	
-			
4			
Vet.			

© Historic England

SITE NAME:	Former Stow Maries Airfield, Flambirds Farm, Stow Maries, Cold Norton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1406155

The site comprises 24 operational buildings of a former World War One Royal Flying Corps airfield; the largest known surviving group of this kind, now owned by a Trust, who, with grant aid from Historic England, WREN, and a large additional award from the Government, have to date fully repaired three of the buildings (Nos 6, 9, and 17), carried out temporary repairs to others, and will rebuild some of those lost. The site now operates as a museum and active airfield with original artefacts and flying (replica) WWI aircraft. However, some buildings remain at risk pending their full repair.

Contact: Malcolm Starr 01223 582723

SITE NAME:	Mill Mound: a bowl barrow 300m south west of	Beckingham Hall, Toll	leshunt Major
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009449
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Woodham Walter Hall: an early C16 house and	its associated garden	earthworks, Woodham Walter
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1021442
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Stow Maries World War One Aerodrome, Off H Purleigh	Hackmans Lane to rea	ar of Flambirds Farm, Cold Norton /
DESIGNATION:	Conservation Area, LB grade II*	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jackie Longman (LPA) 01621 875731

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### **TENDRING**



© Historic England

SITE NAME Martello Tower "D", 450 metres south-south-west of Clubhouse, Clacton Golf Course, Clacton on Sea Scheduled Monument and Listed DESIGNATION: Building grade II

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1016553 and 1111524 One of 29 original Martello towers built along the east coast, against the threat of French invasion. Built between 1808-12. Sold in 1904 and absorbed into a new golf course. The forward battery has been lost in 1980s during construction of new sea defences. No internal access but suffers water ingress and loss of render. Historic England funded feasibility study in 2015-6 to help Tendring District Council identify beneficial use and repair costs.

Contact: Deborah Priddy 01223 582720



© Historic England

SITE NAME: Martello Tower "E", 300 metres south west of junction of Marine Parade West and Wash Lane, Clacton on Sea

Scheduled Monument and Listed DESIGNATION: Building grade II

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER:

SITE NAME:

OWNER TYPE:

LIST ENTRY NUMBER:

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1016554 and 1337150

One of 29 original Martello towers along the east coast built between 1808-12, against the threat of French invasion. The forward battery was destroyed in 1819 and it contains a large water tank, inserted after 1935 when it became part of a holiday camp. Access by ladder to first floor. Suffers from water ingress and loss of render. Discussions with the Tendring District Council regarding repairs to defective external render and a beneficial use. Historic England funded a feasibly study for repair and reuse in 2015-6.

C18 watermill, white weather boarded over painted brick

base. Beam engine circa 1873 now gone. Mill disused since

building no longer weather tight. This is putting at grave risk

1930s. Machinery complete. Road elevation and locum

remain scaffolded. Roofs leaking; building splitting apart; front wall bulging; some of weatherboarding is missing &

Contact: Deborah Priddy 01223 582720



© Historic England

SITE NAME: Spring Valley Mill, Spring Valley Lane, Ardleigh DESIGNATION: Listed Building grade II\* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(C) OWNER TYPE:

1112053

the structure and fabric, which includes the machinery inside. Historic England has offered a HAR grant for detailed survey work which will lead to a set of prioritised and costed repairs. Some urgent works included. Private

Martello Tower "K", Kirby

Contact: Trudi Hughes 01223 582739



© Historic England

Road, Walton on the Naze. Frinton and Walton Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D)

1016787 and 1111504

Private

Martello tower, C19. Some internal alteration and problems arising from water ingress. Pre-applications discussions for domestic conversion commenced May 2014. Structural investigations have been undertaken and the principles of proposed domestic conversion have been agreed with Historic England. Pre-application discussions continued in 2015-6.

Contact: Deborah Priddy 01223 582720

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England Archive

SITE NAME:	Beacon Hill Fort, Harwich
DESIGNATION:	Scheduled Monument, part in CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners

1018958

Ruined coastal artillery fortification of late C19; refortified during the two World Wars. Fabric at risk from failure of concrete, water ingress and vandalism. Monument is in split ownership. Historic England continues to liaise with the Tendring District Council, private owners and interested third parties over potential new uses.

Remains of an Augustinian priory founded before 1127 and post-Dissolution mansion incorporating monastic remains. The site comprises a number of buildings including the main house, a gatehouse, Darcy Tower and various other buildings and standing remains, most in need of major repairs. The Darcy Tower (pictured) remains scaffolded. The "ruined range" was repaired by Historic England in

Contact: Deborah Priddy 01223 582720



© Historic England

SITE NAME:	St Osyth's Priory, St. Osyth
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade I; 3 grade II*; 6 grade II, 7 LBs, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
	1002102 and 1227150.

| 1002193 and 1337158; | 1337159; 1111495; 1308972; | 1337160; 1166310; 1111468; | 1111496; 1111460; 1111462;

1111466; 1111467

Contact: John Neale 01223 582719

2013-2015.



© Historic England

SITE NAME:	Church of St Michael, The Street, Frinton and Walton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1111500

A substantial late medieval church of flint and stone rubble, much restored in the C19. The building suffers from subsidence at the east end of the chancel, where recent repairs have failed, resulting in substantial cracks reappearing in the walls and at the junction of the chancel roof and the east gable. Structural movement continues at the east end of the church, with previously repaired areas cracking again.

Contact: Malcolm Starr 01223 582723



SITE NAME:	Church of St George, Badley Hall Road, Great Bromley
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1337189

Parish church, dating from the C14 and C15, featuring double hammerbeam nave roof with surviving original medieval polychrome decoration. Nave clerestory flushwork and windows repaired in 2012 with a joint Historic England and Heritage Lottery Fund Repair Grants for Places of Worship grant. A further Heritage Lottery Fund Grants for Places of Worship grant was offered in 2014. Development stage has successfully been completed with repair phase due to commence summer 2016.

Contact: Malcolm Starr 01223 582723

0	Historic	England

SITE NAME:	Crop mark site south of Ardleigh, Ardleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002146
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.


Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

Scheduled Monument
 Unitary Authority
 WHS World Heritage Site

SITE NAME:	Beacon Hill Fort: a late 19th and 20th century co	oastal artillery fortifica	ation, Harwich
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1018958
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Deborah Priddy 01223 582720
SITE NAME:	Clacton Seafront, Clacton-on-Sea		
DESIGNATION:	Conservation Area, 5 LBs, RPG grade II, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Philip Hornby (LPA) 01255 686170
SITE NAME:	Dovercourt, Harwich, Harwich		
DESIGNATION:	Conservation Area, 6 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Philip Hornby (LPA) 01255 686170
SITE NAME:	St Osyth, St. Osyth		
DESIGNATION:	Conservation Area, 59 LBs, RPG grade II, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Philip Hornby (LPA) 01255 686170
SITE NAME:	Thorpe-le-Soken Station and Maltings, Thorpe-le-Soken		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Philip Hornby (LPA) 01255 686170

### **UTTLESFORD**



© Historic England Archive

SITE NAME:	Bury Hill, Castle Lane, Saffron Walden
DESIGNATION:	Scheduled Monument and Listed Building grade I, 3 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1009307 and 1297737 Norman castle remains consisting of roofless ruins of the keep. Unconsolidated flint rubble. Two phases of urgent repairs undertaken in 2013-14 and further repairs in 2015 undertaken to high level wall tops. Fabric at ground level on interior faces subject to vandalism. Grant aided work to north and western walls and to fore-building, to be completed in 2016. It is hoped that the owners may then embark on a further phase to complete the full consolidation of this important monument.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Tilty Mill, Tilty
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1112221

Watermill, early C18. Machinery intact. Evidence of defective roof tiles and some structural failure. In need of urgent structural repairs and repair work to make it safe, wind and weather tight. Owners have completed some repairs to exterior of building to address much of the weathering and security issues. Discussions are on-going with the owners, the local authority and a number of interested parties over options to save the mill.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Mary the Virgin, The Street, Manuden
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Religious organisation

1233999

Church with probable C12 origins. Largely demolished and rebuilt in the 1860s. Constructed from flint rubble with stone dressings and a tile roof. Shingled spire showing signs of loss and curling of shingles; north transept (vestry) roof tiles are slipping. The latter are over a C15 roof structure with plastered ceiling and there is mould growth on the western part of the ceiling which is indicative of moisture ingress. Other tiles slipping elsewhere. The Church has applied for a grant under the Listed Places of Worship Roof Repairs grant scheme in 2016.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Roman fort, Ro	Roman fort, Roman town, Roman and Anglo-Saxon cemeteries at Great Chesterford, Great Chesterford			
DESIGNATION:	Scheduled Moni	ument, part in CA	LIST ENTRY NUMBER:	1013484	
CONDITION:	Extensive signific	cant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughin	g	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple	owners	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Romano-Celtic	Romano-Celtic temple 400m south of Dell's Farm, Great Chesterford			
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1017453	
CONDITION:	Generally satisfa problems	Generally satisfactory but with significant localised problems		Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Commercial company		CONTACT:	David Kenny 01223 582760	
SITE NAME:	Site of Waltham	n Hall, Takeley			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1002161	
CONDITION:	Extensive signific	Extensive significant problems		Declining	
PRINCIPAL VULNERABILITY:	Arable ploughin	Arable ploughing		No	
OWNER TYPE:	Commercial co	mpany	CONTACT:	David Kenny 01223 582760	
MARKET Y	SITE NAME:	Easton Lodge, Little Easton	Edwardian garde	ns designed by Harold Peto c1902,	
	DESIGNATION:	Registered Park and Garden grade II, 3 LBs	fire damaged and	ate C17/early C18 grove. The house wa I finally demolished in 1950. Converted and infill development remain. Built	
1 1111	CONDITION:	Generally satisfactory but with significant localised problems	structures within the Italian Garde	the garden have deteriorated, particula n, but planting improving. Ownership sp owners of house and an investment	



© Historic England

SITE NAME:	Easton Lodge, Little Easton
DESIGNATION:	Registered Park and Garden grade II, 3 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners

1001484

between private owners of house and an investment company. Garden continues to open to public in a limited manner under the direction of the charity, The Gardens of Easton Lodge Preservation Trust.

Contact: Deborah Priddy 01223 582720

### **HERTFORDSHIRE**

### **BROXBOURNE**

SITE NAME:	Churchgate		
DESIGNATION:	Conservation Area, 23 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Colin Haigh (LPA) 01992 785555 ext: 5951

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Wormley		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Colin Haigh (LPA) 01992 785555 ext: 5951

### **DACORUM**




© Historic England

SITE NAME:	Hemel Water Gardens
DESIGNATION:	Registered Park and Garden grade II
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001710

The Water Gardens were registered in 2010 and were the subject of a successful Heritage Lottery Fund bid in February 2014 by Dacorum Borough Council. Comprehensive refurbishment of the whole gardens proposed, including structural repairs to bridges and renewed planting scheme. Alterations to car parking and play areas included. Works began in 2015 and are ongoing.

Contact: John Neale 01223 582719

### **EAST HERTFORDSHIRE**



© Historic England

SITE NAME:	Remains of old church tower of St Mary and All Saints Church, Thundridge
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1077953

LIST ENTRY NUMBER:

Ruinous C15 west tower belonging to the C11-C12 church of St Mary and All Saints. Flint rubble with some dressings; a Romanesque doorway has been reset within the blocking of the chancel arch. The church was demolished in 1853, and only the three-stage tower remains substantially above ground. The building is suffering from decay, vandalism and anti-social behaviour. During 2015-16 repeated works to prevent access to the interior of the tower have resulted in increasingly damage. In redundancy process, discussions with diocese and the local authority continue over long term future.

Contact: Deborah Priddy 01223 582720



© Historic England Archive

SITE NAME:	Remains of St Mary and All Saints, Old Church Lane, Thundridge
DESIGNATION:	Scheduled Monument, LB grade II*, part in RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1012268

The church was demolished in 1853, only the separately listed three-stage tower (see separate entry for remains of old church tower) remains substantially above ground within the scheduled churchyard and adjacent manorial moated site. The rest of the church (demolished to foundation level) and the churchyard wall are scheduled and considered to be structurally at risk. Buried archaeological remains are also considered to be at risk from vandalism and anti-social behaviour. Long term management remains a problem to avoid repetition of vandalism.

Contact: Deborah Priddy 01223 582720



© Historic England

SITE NAME:	Church of St Andrew, St Andrew Street, Hertford
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1268748

High Victorian Gothic church 1869-70, incorporating C15 doorway from earlier church, steeple 1875-6. Flint with grey limestone dressings and bands, fine yellow sandstone windows. Welsh slated roofs with red ridge tiles. A scheme for conservation of the historic fabric supported by a Heritage Lottery Fund Repair Grants for Places of Worship grant and work is due to start summer 2016. Estimated completion date is autumn 2017.

Contact: Robert Parkinson 01223 582733

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



SITE NAME:	Parish Church of All Saints, Church Lane, Little Munden
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1102260

Parish church dating from the C12. Construction is in flint rubble, with tower and 'spike' characteristic of the county. The condition of the tiled roofs to the north east chapel, chancel and south slope of the nave is poor.

Contact: Trudi Hughes 01223 582739

© Historic England

SITE NAME:	Roman site near railway station, Braughing / Stando	on	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005249
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Settlement site north east of Letty Green, Hertingf	ordbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005240
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Thundridgebury moated enclosure and associated in Church and graveyard, Thundridge	remains of Thundri	dgebury House, St Mary and All Saints'
DESIGNATION:	Scheduled Monument, LB grade II*, part in RPG grade II*	LIST ENTRY NUMBER:	1012268
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Deborah Priddy 01223 582720

### **NORTH HERTFORDSHIRE**



© Historic	England	Archive

SITE NAME:	Ruins of Church of St Etheldreda, Chesfield, Graveley
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1003542 and 1102564

Former C14 church of St Etheldreda, part demolished 1750; now roofless ruin in private garden. Unconsolidated flint rubble. Wall facing is being lost.

Knebworth House comprises one wing of a C16 courtyard house remodelled in lavish neo-Tudor style in the mid C19. This later external work was in very poor condition for many years, and despite a major campaign of work some years ago with English Heritage grant aid, much remains to be repaired. A further phase of Historic England grant-



SITE NAME:	Knebworth House, Knebworth
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Charity (heritage)

aided work was completed in 2015.

Contact: Deborah Priddy 01223 582720

LIST ENTRY NUMBER: 1102767 Contact: Malcolm Starr 01223 582723 © Historic England

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Minsden Chapel, Whitwell Road, Langley
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1003543 and 1347462

Ruined remains of a small C14 two-cell church with bellcote. Built of flint rubble with stone dressings, plastered externally. Probably a ruin by end of C17. Church was dedicated to St Nicholas. Inspection showed loss of voussoirs from openings and general erosion of fabric which requires consolidation. Discussions with Parochial Church Council and diocese regarding repairs took place in 2013 but there has been no further progress on repair since.

Contact: Deborah Priddy 01223 582720



© Historic England

SITE NAME:	North Hertfordshire Masonic Lodge (the Cloisters), Barrington Road, Letchworth Garden City
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1102019

Built 1906-7, originally a residential school for psychology based on Arts and Crafts ethics. Patron Miss A Lawrence, Architect WH Cowlishaw, a follower of William Morris. Highly idiosyncratic design incorporating a philosophical approach to materials with traditional and progressive themes, but now costly to maintain. Currently the North Hertfordshire Masonic Lodge. Problems of rainwater entry and architectural deterioration. No action/strategy identified or agreed.

Contact: Malcolm Starr 01223 582723



© Historic England

SITE NAME:	West Barn at Rectory Farm, Shillington Road, Pirton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (D)
OWNER TYPE:	Commercial company

Tithe barn built late C15 or early C16. The building is now vacant and in need of major repairs. Other buildings on site have been converted into houses. Sympathetic proposals for repair and partial conversion have been agreed but have yet to be implemented. Barn letting in water. Historic England and local planning authority are considering options with owner to secure a solution.

LIST ENTRY NUMBER: 1175545 Contact: Trudi Hughes 01223 582739



© Barker & Associates LLP

SITE NAME:	Church of St Mary, Church Street, Baldock
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1347611

Prominently sited parish church, dating from the C13, with C14 and C15 alterations and additions. Some C19 restoration. Tower spire C19. Tower, with nave and chancel; north and south aisles and porches. Nave and south aisle roofs suffering from severe underside lead corrosion; leaking. Some of flint facework on south aisle and to south porch is loose. A Heritage Lottery Fund Repair Grants for Places of Worship grant was awarded in 2014 and the project development stage has been completed in 2016.

Contact: Malcolm Starr 01223 582723

SITE NAME:	Romano-British small town and late Iron Age settlement at Baldock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016305
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Two bowl barrows at Bygrave, 650m east of Park \	Wood, Bygrave	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009821
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Slight univallate hillfort on Wilbury Hill, Letchwortl	h Garden City / Ick	leford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016410
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Ring ditch and enclosure, Newnham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003596
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Wymondley Priory, barn, moat, associated earthwo Wymondley	orks, enclosures, pl	atforms, hollow-way and conduit head
DESIGNATION:	Scheduled Monument, 5 LBs	LIST ENTRY NUMBER:	1013338
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

### ST ALBANS



© Historic England

SITE NAME:	The Benedictine Priory of St Mary (Sopwell Priory) and the post-medieval mansions known as Sopwell House or Lee Hall
DESIGNATION:	Scheduled Monument, LB grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (A)
OWNER TYPE:	Local authority

1019137

Well preserved post-dissolution remains of Benedictine Priory. Building requires repairs to wall tops and areas of lost walling and window openings, where cracking and decay is causing loss of fabric and risk to the structure. Grant aid was agreed for a full programme of repair works to the ruins which is expected to complete in 2016. Garden walls also in need of urgent repairs.

Contact: Deborah Priddy 01223 582720

SITE NAME:	The Aubreys camp, Redbourn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003520
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

SITE NAME:

SITE NAME:	Wheathampstead earthwork incorporating Devils I	Dyke and the Slad,	Wheathampstead / Sandridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003521
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

### THREE RIVERS



SITE NAME: Langleybury House, Langleybury, Abbots Langley DESIGNATION: Listed Building grade II\* CONDITION: OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY:

Country house c1725. Formerly in use as part of a school, but vacant since 1996. Proposals for the repair of the house have yet to be implemented, and while use of the buildings for filming helps ensure their protection, the implementation of a comprehensive scheme remains desirable.

Commercial company LIST ENTRY NUMBER: 1173157 Contact: John Neale 01223 582719 © Historic England

### WATFORD



stable block, Hempstead Road, Watford DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

Late C17 house built as dower house to Cassiobury. Last occupied as offices, the building has been empty for many years. Various repairs have been carried out over this period. Lease taken by Watford Borough Council form Hertfordshire County Council who are considering an offer of a Repair Grant for Heritage at Risk from Historic England made in June 2016, towards a conservation management plan and condition survey.

© Historic England LIST ENTRY NUMBER: 1175392 Contact: Robert Parkinson 01223 582733

Little Cassiobury and former

SITE NAME: Frogmore House, High Street (north east side), Watford DESIGNATION: Listed Building grade II\* CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Commercial company

A fine house built in 1716, Frogmore House was last used as flats. The house was repaired some years ago but remained vacant due to the uncertainty surrounding the future use of adjacent land. No scheme yet forthcoming.

LIST ENTRY NUMBER: 1175515 Contact: John Neale 01223 582719 © Historic England

### WELWYN HATFIELD



@ Priest Restoration Ltd

SITE NAME:	Paine Bridge at Brocket Hall, Marford Road, Lemsford, Hatfield
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

abutments and exposed the brick core.

Very fine classical bridge, built of stone to designs of James Paine in 1772. Stonework facing has failed on all four bridge

LIST ENTRY NUMBER: 1173560 Contact: Robert Parkinson 01223 582733

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG

Unitary Authority World Heritage Site

### LLITONI (LIA)

LUTON (UA)			
SITE NAME:	High Town Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Gemma Davies (LPA) 01582 546548
			` ,
SITE NAME:	Plaiters Lea, Town Centre		
SITE NAME: DESIGNATION:	Plaiters Lea, Town Centre Conservation Area, 9 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	. ,

### **NORFOLK**

### **BRECKLAND**



SITE NAME: Shadwell Court and clock tower, Brettenham Listed Building grade I, RPG DESIGNATION: grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

Country house circa 1720 with substantial C19 additions set in the centre of C18 park. Mid C19 formal gardens to the west, now much simplified. The building has been unoccupied for many years and affected by severe dry rot outbreaks set off by leaks in the roof. Extensive roof repairs have been undertaken and the main building is now stabilising. Part of the attached stable yard is in use and maintained, but part is deteriorating.

© Historic England

LIST ENTRY NUMBER: 1076940

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Contact: David Eve 01223 582721



© Andrew Gayton

SITE NAME: Dereham Maltings (Crisp Malting), Norwich Road, East Dereham, Dereham DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Private

1246348

Large complex of C19 maltings, disused and vacant. Proposal to build houses on part of land and repair and reuse of maltings has been discussed in principle and discussions of detail on-going but not yet agreed.

Contact: David Eve 01223 582721



© Historic England

SITE NAME: Guntons Farmhouse, Reymerston Road, Garvestone DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1342566

repairs leading to areas of decay, particularly long-standing decay in rear stair tower. Long-term solution still to be agreed and implemented.

Timber-framed manor house, late C16. General lack of

Contact: David Eve 01223 582721

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Ruins of St Andrew's Church, Roudham and Larling
	Scheduled Monument I B grad

DESIGNATION:

CONDITION: Very bad

OCCUPANCY: N/A PRIORITY CATEGORY: B (B)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1004012

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Ruinous C14 church of flint with ashlar dressings, significant architectural details survive throughout. The remains form a significant monument in the local landscape but are in a dangerous condition with loose masonry and are cordoned off. Negotiations are on-going.

Contact: David Kenny 01223 582760



© Historic England

SITE NAME:	Church of All Saints, Stanford
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

1172174

Religious organisation

C12 and later medieval church now closed and owned by the Ministry of Defence. Chancel arch in danger of collapse and masonry is falling from the tower. Chancel arch propped by structural scaffold. Diocese and Military to meet with Historic England during 2016 to review.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Church of St Mary the Less, Bury Road, Thetford
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (D)
OWNER TYPE:	Religious organisation

1297899

Former church, CII foundation, fabric mainly late CI4. West tower C15, chancel rebuilt C19. Closed for worship and has suffered from decay and vandalism. A scheme for residential conversion was granted consent but has not been implemented. Some repairs to the roof have been carried out and a fresh proposal for a residential use is under discussion. Some high level tower masonry in dangerous condition.

Contact: David Eve 01223 582721



© Ruth & Peter Blackman

SITE NAME:	Church of St Mary, Church Hill, Banham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation

1169031

Parish church generally C14 and restored in 1863-5. Tower staircase is unstable; elements of chancel east window may be unstable and stained glass has cracked in many places due to structural movements in window tracery. Damp south aisle wall and monuments to immediate south west of tower all appear to be undermined. Movement at high level in south aisle west wall at high level and possible faulty drainage. A Heritage Lottery Fund Repair Grants for Places of Worship grant was offered in 2015. Project development work is underway in 2016

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Church of Holy Cross, Church Lane, Caston
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1076784

Church with thatched roofs over fine polychrome and panelled mediaeval ceilings in the nave and chancel. The thatch to both roofs is slipping and failing rapidly. An application for a Heritage Lottery Fund Repair Grants for Places of Worship grant has been submitted pending

decision in 2016.

Contact: Malcolm Starr 01223 582723

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

I PA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Peter and St Paul, Church Road, Griston
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1172332

Parish church dating from C14 comprising west tower, nave, chancel and north porch. Roofs in nave, porch and chancel date from the 1884 restoration by JB Pearce. Constructed in flint rubble with limestone dressings. Parapet at top of tower contains some loose and weathered flint flushwork panels. Loose flints have fallen on adjacent roofs. Tower roof is leaking. A Heritage Lottery Fund Repair Grants for Places of Worship grant has been offered. Development work commenced on site in 2015.

Contact: Trudi Hughes 01223 582739



SITE NAME:	Church of St Mary, Church Road, Elsing
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1342548

Parish church. Built by Sir Hugh Hastings between 1330 and 1347 replacing an earlier church of which a small fragment of walling survives in west wall of nave. West tower, exceptionally wide aisleless nave with north and south porches. High level masonry, roofs and rainwater goods failing. A Historic England and Heritage Lottery Fund Repair Grant for Places of Worship grant for work to south side was completed in 2014. Outstanding items include windows and the internal environmental conditions which threaten the important rood screen, a solution to which is yet to be agreed.

Contact: Robert Parkinson 01223 582733



© Ruth & Peter Blackman

SITE NAME:	Church of St Mary, Church Street, Kenninghall
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1168685

Medieval parish church of CII origins. Nave, north aisle and chancel C14; C15 west tower. Continual roof leaks and dampness along northern side. Nave roof is in need of recovering and there are various areas of stonework repairs required largely due to weathering. A Heritage Lottery Fund Repair Grants for Places of Worship grant was offered in summer 2015 and project development stage work is underway.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Church of St Andrew, Holme Hale
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1152077

Medieval and later church in flint with ashlar and some brick dressings. Slate and pan tiled roofs. C14 and C15 west tower with roof deteriorating. Repair grant offered in 2010 and work complete. Exceptionally, the number of bats using the nave remains an issue and impacts on the usability of the building. A joint Natural England and Historic England funded project helped research to resolve issues of bats and users of the church. Buttresses on nave south side full of vegetation; suspect faulty drainage; also some loose flints.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Church of St John Evangelist, Church Street, Ovington
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1076798

Parish church dated to C12 and restored 1867. Rubblestone construction with ashlar quoins and white pantiles. Square west tower and continuous nave and chancel. Hipped slate roof. South door C12. Serious structural cracks in tower and nave walls. Roofs leaking with associated water penetration problems. A Heritage Lottery Fund Grants for Places of Worship grant has been offered and project development work has commenced.

Contact: Robert Parkinson 01223 582733

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Andrew, Lexham	
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Very bad	
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1342495	

Parish church featuring a Saxon round tower, largely intact; nave and chancel in line and largely rendered, with evidence of long and short work at quoins. 1837 restoration provided the roofs to the nave and chancel. The round tower is surmounted by an octagonal parapet which does not fit the geometry of the walling below, which has led to excess water ingress into late Saxon walling. Roof leaks. A Heritage Lottery Fund Grants for Places of Worship grant has been offered and project development work is in progress.

Contact: Trudi Hughes 01223 582739



SITE NAME:

Church of St Andrew, Fairstead Lane, Little Cressingham

DESIGNATION:

Listed Place of Worship grade I

CONDITION:

Poor

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1077227

Parish church. The C15 tower is partially demolished and the two western most bays of the nave and south aisle are roofless. The two most western north aisle bays have been demolished except for the west wall. The present entrance is to the west in the brick wall dividing the roofed church in use from the ruin. A corrugated roof covers the south aisle, while the nave is roofed in plain tile. Roof is leaking with damp penetration in aisles. Vegetation growth is also an issue.

Contact: Trudi Hughes 01223 582739



Church of St Mary, Sporle with Palgrave

DESIGNATION: Listed Place of Worship grade I

CONDITION: Very bad

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1169820

Parish church, medieval and later. Flint with ashlar and some brick dressings. West tower, aisled nave; chancel flanked by extension of north aisle. C13/14 W tower with angle buttresses and a rectangular stair projection to south east. Remains of a C15 parclose screen and a late medieval cyclical wall painting in south aisle. The building has been the victim of heritage crime and parts of the roof have a temporary plastic covering.

Contact: Trudi Hughes 01223 582739



© Nicholas Warns Architects

SITE NAME:	Church of St Margaret, Church Lane, Stanfield	
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Very bad	
PRIORITY CATEGORY:	B (New entry)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1077388	

Parish church. Medieval and later. Flint with ashlar dressings and slate roofs. West tower, aisleless nave with south porch and chancel. Medieval chancel screen survives, with exceptionally fine mediaeval and later pews. Very damp internally due to poor ground drainage and defects in walls. A Heritage Lottery Fund Grants for Places of Worship grant has been offered and the project development stage is underway.

Contact: Malcolm Starr 01223 582723



© Historic England

© Historic England

SITE NAME:	Church of St Peter, Church Road, Shropham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077578

and slated roofs. North nave roof heavily tingled (a form of temporary repair) and may require replacement in near future. Slow decline however monitoring is on-going.

Mid C13 nave, north aisle and chancel; remodelled in C15. C15 west tower restored 1867. Flint with ashlar dressings

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Tumulus west of Leader's Spinney, Banham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003161
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman villa west of Woodrising Wood, Cranworth	h	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003930
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Leylands Farm Romano-British site, Hockwold, We	eting-with-Broomh	nill / Hockwold cum Wilton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003621
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760



© Historic England

SITE NAME:	Church of St Andrew, Tottington
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1342814

Parish church dated to 1360, restored 1885-6 by E P Willins. Rendered flint with ashlar quoins and tiled and pantiled roofs. West tower, nave, aisles and chancel. Tower of four stages. Angle buttresses to east and west becoming diagonal. Arched and moulded west door below a two light window. The condition of high level stonework on the tower is of concern and the chancel ceiling is at risk of collapse. This is one of a number of battlefield churches under review by Historic England, Norwich Diocese and the Military of Defence.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Dereham, Dereham / Scarning		
DESIGNATION:	Conservation Area, 97 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Andrew Gayton (LPA) 01362 656257
SITE NAME:	Thetford		
DESIGNATION:	Conservation Area, 170 LBs, 9 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Andrew Gayton (LPA) 01362 656257
SITE NAME: Roman enclosure 3/4 mile (1210m) north east of Panworth Hall, Ashill / Holme Hale			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003965
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Lindon ropping or in fair to good.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

DESIGNATION:

### **BROADLAND**



© Historic England

SITE NAME:	Burgh Mill, The Street, Burgh and Tuttington
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (B)

Private 1250712

Three storey C18 watermill on the River Bure. Milling has ceased and the vacant building is in disrepair. Condition survey and feasibility report undertaken. Owner has completed first phase of repairs to weatherboarding, temporary repairs to rainwater disposal arrangements. Internal structural propping still in place. Owner considering a second phase of work.

Ruinous lodge constructed early C15. In need of structural repairs including wall capping and repointing. Historic England has provided advice to the Local Authority conservation officer on repair techniques who is liaising with the owner regarding repairs. Historic England offered

Contact: Trudi Hughes 01223 582739

	١	-	
3			

© Historic England

SITE NAME:	Drayton Lodge, Drayton High Road, Drayton
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (F)

OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1003999 and 1306023

Contact: Trudi Hughes 01223 582739

a grant December 2014 towards repairs.



© Historic England

SITE NAME:	Stockhouse at Manor Farm, The Green, Freethorpe
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

Farm building, 1828. Built for the Walpole family who owned Freethorpe in the C19. This is the most complete example of probably no more than six surviving stock houses of this type. Repair works and conversion underway but not yet completed.

Church dated as C14-C15 but possibly earlier. Medieval

scissor-braced and thatched nave roof is in poor condition. Fine internal features including medieval wallpaintings,

decoration, and consecration cross. High level of damp in walls due to poor ground drainage. A Heritage Lottery Fund Grants for Places of Worship grant has been awarded

SITE NAME: Church of All Saints, Beighton, Church Hill, Beighton

1152503



© Historic England

CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1051445

Listed Place of Worship grade I

Contact: Malcolm Starr 01223 582723

and project development is in progress.

Contact: David Eve 01223 582721



© Historic England

SITE NAME:	Parish Church of St Agnes, Church Lane, Cawston
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1263465

and painted screen. Stonework decay to base of south porch. Some vegetation in tower and signs of plaster movement and water ingress. Suspected faulty drainage.

Large medieval church built on wealth of iron trade. Tower paid for by the Earl of Suffolk in C15. Hammerbeam roof

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park LPA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England Archive

© David Lemon

SITE NAME:	Church of All Saints, Norwich Road, Marsham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1250332

Parish Church. C13 and later, of flint with stone dressings and slate roof. West tower, north aisle, south aisle, south porch, nave with a hammerbeam roof, clerestory, vestry and chancel. Two-stage tower with diagonal buttresses, C14 windows, chequered flint parapet. The tower is cracking and the roof to the south porch is rotting. A Heritage Lottery Fund Grants for Places of Worship grant was offered in November 2015 and project development work is underway.

Contact: Trudi Hughes 01223 582739

	1	
	NI TI	
10		1

SITE NAME:	Church of St Peter and St Paul, Church Lane, Oulton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1372723

Parish church, comprising nave, chancel, south porch and tower with embattled parapets. The building is of flint rubble, with limestone dressings. The tower has loose masonry at parapet level and possibly below. Site visit confirmed that tower parapet has loose masonry and there are other high level structural defects to the tower which require urgent attention. A Heritage Lottery Fund Grants for Places of Worship grant has been offered in 2014. Project is well underway.

Contact: Trudi Hughes 01223 582739



© Nicholas Warns Architects

© Nicholas Warns Architects

SITE NAME:	Church of St Mary, Church Hill, Reepham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1076872

Three churches in a shared churchyard; St Michael (now a community centre), St Mary Reepham and the upstanding ruins of All Saints Hackford (destroyed in the 1540s). Tower underwent a programme of repairs in the 1950s which included renewal of roof (now failing) and heavy cementitious repairs to tower, as a result of which, pieces of masonry periodically fall onto the surrounding area. Heritage Lottery Fund Grants for Places of Worship grant has been offered in 2015. Project underway.

Contact: Trudi Hughes 01223 582739



SITE NAME:	Church of St Andrew, Reepha Road, Wood Dalling
DESIGNATION:	Listed Place of Worship grade
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172116

Parish church. C13, C14 and C15. Flint construction with limestone dressings. Extensive repairs completed in recent past to north and south aisles and to the nave. However, the chancel appears to be suffering from roof spread where the roof structure shows visible signs of sagging. Monitoring is underway.

C15 church noted for its painted screens. The building is generally in fair to good condition with the exception of the nave roof which is poor and needs replacing. A Heritage Lottery Fund Grants for Places of Worship grant has been offered and works are underway; due for completion 2016.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Church of St Helen, The Street, Woodbastwick
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1154645

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Roman settlement at Brampton, Brampton / Buxto	on with Lammas	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003698
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582760
OUTE NAME			
SITE NAME:	Roman camp and settlement site west of Horstead	l, Horstead with Sta	anninghall
DESIGNATION:	Roman camp and settlement site west of Horstead Scheduled Monument	I, Horstead with Sta	nninghall 1003928
	•		
DESIGNATION:	Scheduled Monument  Generally satisfactory but with minor localised	LIST ENTRY NUMBER:	1003928

### **GREAT YARMOUTH**



© Historic England

SITE NAME:	Tower on Great Yarmouth town walls, 2-3, Dene Street, Great Yarmouth
DESIGNATION:	Scheduled Monument, 4 LBs, 3 CAs
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1003782

Contact: David Kenny 01223 582760



© Historic England

SITE NAME:	Medieval vaults under, 50-56, Howard Street South, Great Yarmouth
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1003935

C12 and C14 vaulted undercroft of possible medieval merchant's house. Water penetration, condensation and the poor condition of existing timber shores mean that the structure is at risk of structural failure.

Derelict tower on medieval town walls dating to 1261. Structure in very poor condition and urgent conservation and repairs to the stonework is required. Discussions are ongoing with owner to agree a suitable repair strategy.



© Historic England

SITE NAME:	The Winter Gardens, Marine Parade, Great Yarmouth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1271608

Cast iron seaside winter gardens, situated on the seafront within the conservation area. Cruciform plan, with lantern over crossing. Cast iron components corroding due to excess moisture leaking into structure. Owner looking at possibility of reinstating winter gardens function. Currently the owner is discussing options which may result in bid for Heritage Lottery Fund funding.

Contact: Clare Campbell 01223 582738

Contact: Will Fletcher 01223 582710

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© Historic England

Barn at Hall Farm, Hall Road, Hemsby
Listed Building grade I
Very bad
Vacant/not in use
C (New entry)
Private

1216597

Early 14th century timber framed barn. Brick walls added in 18th century. In low key agricultural storage use. Storm damage to one end of building. Repair works under discussion. Future transfer to preservation trust also under discussion.

Contact: David Eve 01223 582721



© Nicholas Warns Architects

SITE NAME:	Church of St Peter and St Paul, Church Road, Burgh Castle
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1051008

Parish church. Late C11 west tower and C13 nave and chancel re-modelled in C15. North aisle 1847. Flint construction with ashlar dressings and some brick. Slate roofs. A Heritage Lottery Fund Grants for Places of Worship grant was offered in 2013. Repairs to address structural failure in north aisle and failure at the chancel north east corner as well as the subsidence at the foot of the chancel east gable now complete. However, there appears to be active movement in the chancel south wall which requires addressing.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Church of St Peter, Dene Side, Great Yarmouth
DESIGNATION:	Listed Place of Worship grade II, part in SM, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENITRY NILIMBER:	1096827

Parish church. 1831-3. By JJ Scoles. Greek Orthodox church from 1964. Gault brick. West tower, nave, aisles and continuous chancel. Perpendicular style. Three-stage tower, second stage with a clock face to cardinal points. Aisles clasp west end of chancel and have their west bays devoted to entrance doors. South aisle roof in very poor condition and urgent masonry repairs required. An application for a Heritage Lottery Fund Grants for Places of Worship grant was made in May 2016.

Contact: Robert Parkinson 01223 582733



© Historic England

SITE NAME:	Church of All Saints, Church Lane, Filby
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1287564

Parish church of C13 origin or earlier, with C14 and C15 alterations, and some C19 restoration, but the lower panels of the medieval rood survive with their original polychrome decoration and depictions of saints. In May 2014, Historic England produced a report confirming that rainwater goods, tower masonry, and chancel roof are in poor condition.

Contact: Malcolm Starr 01223 582723



© Historic England

SITE NAME:	Church of St Nicholas, Church Plain, Great Yarmouth
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1096813

Parish church founded in 1101 in association with adjacent Benedictine priory. Considered by Pevsner to be the largest parish church in England. Base of tower early C12; remainder C13; restored in C19. Extensively fire-damaged in World War II and rebuilt. First phase of urgent repairs completed July 2013. However, further urgent repairs are needed including stonework repairs to central tower; tower north east turret repairs; high level flashing repairs; repairs to north transept buttress stonework; various other high level stonework repairs required.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Nicholas Warns Architects

SITE NAME: Church of St Mary including church rooms and surrounding wall, Regent Road, Great Yarmouth

Listed Place of Worship grade DESIGNATION: II\*, CA

CONDITION: Very bad

PRIORITY CATEGORY:

SITE NAME:

A (C) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1245910

Roman Catholic Church, Perpendicular style with late decorated features, built 1848-1850 by JJ Ścoles for the Society of Jesus. Built of knapped flint with limestone ashlar dressings, Urgent and wide-scale structural and weathering problems. A jointly funded Historic England and Heritage Lottery Fund Repair Grants for Places of Worship grant was offered in 2011 to stabilise west end and re-roof presbytery link. Works now complete, but other urgent and wide-scale structural and weathering problems are of concern.



Road, Fleggburgh DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: F (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER:

1372907

Church of St Margaret, Main

Nave and west tower Perpendicular and ruinous. Chancel of C15 origins but substantially of 1872. Flint with ashlar dressings. Dethatching of chancel and nave roofs needed together with installation of rainwater goods and drainage and localised internal repairs. A Heritage Lottery Fund Grants for Places of Worship grant was offered in 2015. Investigation work commenced in spring 2016. Anticipated completion in autumn 2017.

Contact: Robert Parkinson 01223 582733

Contact: Trudi Hughes 01223 582739

© Historic England



© Nicholas Warns Architects

SITE NAME:	Church of All Saints, Bagthorpe with Barmer
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER: 1077802

Former parish church, now closed. CIIth or CI2th round tower. Ċ13th nave; C14th north aisle (restored 1885-6) and chancel, with early English detailing. C15th details; restoration 1885-6 by Frederick Preedy, Architect. Flint with stone dressings; slated roofs partly fish-scale pattern. West round tower, three bay nave and north aisle, twobay chancel. West round tower includes three rectangular lancet openings suggests pre-1200 date. Tower roof leaking and has a large hole in it which is admitting water; nave and chancel roofs are heavily tingled.

Gatehouse c1570 in private garden. In need of repair due to lack of maintenance. Historic England has been in discussion with the owner and an application for Historic England grant aid has been received and offered.

Condition report and schedule of works being prepared as

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Denver Hall, Ely Road, Denver
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1342309

all, Ely Road, Denver	House with original and unusual C16 features, some C18 and C20 alterations. In need of repair and improvement. Roof is in very poor condition. Historic England liaising wit owner to discuss next steps.
ding grade II*	
in use	
	Contact: Claire Fidler 01223 582735

Contact: Claire Fidler 01223 582735



SITE NAME:	Gatehouse north of Denver Hall, Ely Road, Denver
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1077847

part of a development phase.

Contact: Claire Fidler 01223 582735

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Denver Mill, Sluice Road, Denver
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1077850

Grade II\* listed mill built in 1835 and ceased working in 1941 after being struck by lightning. Repairs undertaken in the late 1990s but the render has failed and sails removed for health and safety purposes in 2011, when one of the steel stocks broke. A further programme of conservation is required to the make the building safe and put the mill into working order for demonstration purposes. Negotiations are on-going regarding ownership and access to grant funding.

Contact: Claire Fidler 01223 582735



© Historic England

SITE NAME:	Detached porch in courtyard, Hunstanton Hall, Old Hunstanton
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1077922

Freestanding porch built in 1618, in the centre of the courtyard of the Hall. Porch was retained in 1853 after the wing to which it was attached was demolished. The front piece and short return walls remain, but with no roof. Repair and consolidation needed.

Contact: David Eve 01223 582721



© Historic England Archive

SITE NAME:	Chapel of St Andrew, Barret Ringstead, Old Hunstanton
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1003986 and 1077919

LIST ENTRY NUMBER:

Former chapel, C13 and C14. Roofless and overgrown; in need of consolidation, repair and control of burrowing animals. Historic England is working with local partners to develop a strategy for repair. Condition continuing to deteriorate however it has not been possible to establish ownership.

Ruined church, C12 and C14. The only above-ground remains of the deserted medieval village. The building is a ruin with no possibility of economically beneficial use. It is

Contact: Will Fletcher 01223 582710

in need of consolidation due to loose flints.



© Historic England Archive

SITE NAME:	Ruins of Church of St Edmund, Egmere Road, Egmere, Walsingham / South Creake
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
0) 4 /4 /50 73 /05	D

Contact: David Kenny 01223 582760

N/A
C (C)
Private
1018173 and 1039409

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© Norfolk County Council

SITE NAME:	West Acre Priory, West Acre
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*; 3 grade II, 3 LBs
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (A)

Private

1077662

1008352 and 1077660:

1077661; 1342410; 1171741;

Large Augustinian priory with extensive standing remains (circa 1135). A masonry collapse in early 2005 from what appears to be the ruins of the east range of the cloister damaged other stonework which is now vulnerable to further loss. A prioritised schedule of works has been agreed and it is hoped that consolidation and repairs can commence in 2016.

Contact: David Kenny 01223 582760

<b>X</b>	人面多上	
MA	1	

© Historic England

© Historic England

SITE NAME:	Church of St Margaret, Saturday Market Place, King's Lynn
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1211336

Benedictine Priory founded 1095, now parish church known as Kings Lynn Minster. Rebuilt during C13, altered continuously since. Limestone. Lead roofs. Twin west towers, nave, aisles, transepts with crossing tower, aisled chancel. West front with central arched door under crenellated surround. An application for a Heritage Lottery Fund Grants for Places of Worship grant was made in 2016 to support repairs to decaying high level masonry and Roman Cement to West end and West Towers. HLF grant applied for summer 2016.

Contact: Robert Parkinson 01223 582733



	DI
	C
	PF
No.	0
	119

SITE NAME:	Church of All Saints, Church Lane, East Winch
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
I ICT ENITDY NII IMDED.	1242202

Parish church of C14 and C15 date with restorations in 1878 by Sir George Gilbert Scott. Constructed from rubblestone, carstone and part rendered. Slate roofs. Masonry of the tower, south aisle, and chancel deteriorating badly. Ineffective ground drainage is making the interior damp and places the historic pews at risk. A Heritage Lottery Fund Repair Grants for Places of Worship has been offered for all these repairs. Work is expected to begin summer 2016.

Contact: Malcolm Starr 01223 582723



	100	A	
443		n le	

SITE NAME:	Church of All Saints, Church Road, Hilgay
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077719

Parish church. Brick west tower of 1794, remainder of carstone with ashlar dressings. Late C14 south aisle, nave and chancel. Slate roofs. Two stage tower supported by angle buttresses to first stage where belfry is set back at string course. Three-light timber west window. Roundels to north end south. Arched belfry windows with timber trellis screen. Water and damp penetration with vegetation growing on fabric of roofs indicating failure.

Contact: Robert Parkinson 01223 582733



© Historic England

© Historic England

SITE NAME:	Church of St Andrew, Church Lane, Little Massingham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1171638

Parish church, C14 and C15. Flint rubble, dressings of squared and knapped flint, stone, red brick and red clunch. C20 machine made pan tiled nave roof; leaded aisles and chancel; West tower, south porch, three-bay nave with clerestory; north and south aisles. Three-stage tower with stone plinth and four offset buttresses on west face only. The building has been the victim of heritage crime.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



(0)	Historic	Fnσ	land

SITE NAME:	Church of St Andrew, High Street, Northwold
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LICT ENITDY NILIMBED.	1242240

failing, high level masonry poor, severe water penetration. Nave, south aisle and south porch roofs leaking; Roman cement rendered walls hollow and bursting render, putting wallpaintings at risk. Clerestory tracery in need of urgent repair. The condition of the glazing in the Chancel east window is poor. 1342348 Contact: Robert Parkinson 01223 582733



SITE NAME:	Church of St Germans, Wiggenhall St. Germans
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077892

Grade I listed church built between C13 and C16. Carved pew ends c1500 are of great historical importance. The church contains font donated in 1851 and also the font from the nearby ruined Wiggenhall St Peter's church. Stonework, render, roofs and rainwater goods are in very poor condition. The building has also been the subject of heritage crime.

Parish church. C13 nave and aisles, C14 chancel partly rebuilt 1840, enlarged 1895, late C15 west tower. Flint, rendered to nave and aisles, with ashlar dressings. Fourstage tower with flushwork diagonal buttresses. C20 roof

Contact: Janine Dykes 01223 582724

SITE NAME:	Roman fort (Branodunum), Brancaster		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003983
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Moated site and associated earthwork enclosures 190m south east of Denver Hall, Denver		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016486
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Remains of St Andrew's Church, East Walton		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019836
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
OWNER TYPE:  SITE NAME:	Private  Romano-British villa 400m west of White House, F		David Kenny 01223 582760
			David Kenny 01223 582760
SITE NAME:	Romano-British villa 400m west of White House, F	ring	·
SITE NAME: DESIGNATION:	Romano-British villa 400m west of White House, F	ring LIST ENTRY NUMBER:	1020861

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

		` ′	
SITE NAME:	Well Hall Roman settlement, Grimston / Gayton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003168
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Remains of tower on Lodge Hill, Snettisham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003912
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Moated site of Wormegay Priory, fishponds and ass	ociated enclosures	, Wormegay
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009987
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760

### NORFOLK BROADS (NP)

Halvergate Marshes, Halvergate, Halvergate / Mautby / Norton Subcourse / Reedham / Stokesby with SITE NAME: Herringby / Thurlton / West Caister / Acle / Belton with Browston / Burgh Castle / Fleggburgh / Freethorpe / Fritton and St. Olaves / Haddiscoe, Broadland

DESIGNATION Conservation Area, 28 LBs, SM NEW ENTRY?:

CONDITION: TREND: Very bad No significant change

> Ruins of Broomholm Priory, Abbey Street, Bacton

VULNERABILITY: CONTACT: Ben Hogg (LPA) 01603 756074 Medium

### **NORTH NORFOLK**



Scheduled Monument and Listed DESIGNATION: Buildings - I grade I; I grade II\*, part in CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: B (B) OWNER TYPE: Private

Priory remains, primarily C12-C13 in date. The general condition of the site has been stabilised though the introduction of a Section 17 management agreement offered by Historic England. Stabilisation of the ruins is urgently needed and a strategy has been developed for improved management and repair.

No

1003974 and 1373815; 1049146 LIST ENTRY NUMBER: Contact: Will Fletcher 01223 582710



© Nicholas Warns Architects

SITE NAME: Church of St Peter, Corpusty and Saxthorpe DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (B) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER:

1049202

Medieval former church, taken on by the Norfolk Churches Trust who have completed an extensive scheme of external fabric repairs. Building now in need of reroofing. Talks still on-going with village as to whether they are able to take on building, and if so: potential use(s). The Trust secured a Listed Places of Worship Roof Repair Fund grant in March 2015 towards the cost of re-roofing, which is now complete. Interior remains unusable. Trust looking at how building may be used.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Fakenham gas works, Hempton Road, Fakenham
DESIGNATION:	Scheduled Monument, part in CA
CONDITION:	Poor

Poor

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: B (A)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1003908 The gasworks produced town gas from 1825 until 1965 and is now the only remaining town gas works of its kind in England. Acquired in 1983 and repaired, it was opened as a museum in 1989. Damp and ground movement are causing structural weakness to key industrial buildings and machinery. Corrosion of metalwork and metal components. Major issues surround the retort housing and its ashpit.

Contact: Nick Carter 01223 582751



© Historic England

SITE NAME: Melton Constable Hall, Melton Constable Park, Melton Constable Listed Building grade I, RPG DESIGNATION: grade II\*, CA CONDITION: Poor

OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY:

C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1153044

Country house 1664-1670, enlarged to east in 1810. Service and stable range to north. South and west of Hall are formal C19 terraces, now grassed over. The Hall is on slightly elevated ground overlooking parkland and a lake to the south. The Hall is presently not used and is in need of repair, although some work has been undertaken to the east wing.

Contact: David Eve 01223 582721



© Historic England

SITE NAME: Site of Manorial Complex, Hall Farm, Waxham, Sea Palling DESIGNATION: Scheduled Monument, 3 LBs CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Private

LIST ENTRY NUMBER: 1013418

C16 wall and gatehouse. Major structural repair necessary due to lack of maintenance. Some flint facing falling away. Destructive ivy growth. Several damaged copings, Repairs to the precinct wall also necessary.

Tower mill of 1789. Restored in 1976-85 and formerly part

of a museum, now closed. The mill's cap became unstable

and has been removed for repair. Discussion about possible redevelopment of the site and details of repair to



© Historic England

SITE NAME: Sutton Mill, New Road, Sutton DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1049326

Contact: David Eve 01223 582721

mill on-going.

Contact: Will Fletcher 01223 582710



0	Historic	England
$\cup$	I IISTOLIC	Lingianic

SITE NAME:	Church of St Ethelbert, Church Road, Alby with Thwaite
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049885

Parish church of medieval origin. Constructed of flint with stone and brick dressings. Pantile roof. West tower, nave, south porch, chancel, vestry. Roof, rainwater goods and high level masonry all in very poor condition. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in 2013. Repairs phase is underway in 2016.

Contact: Robert Parkinson 01223 582733

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, Church Lane, Holt, Baconsthorpe
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Fair
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Religious organisation

1049847

Parish church dating to 1260. Fine interiors, important monument to William Heydon dated 1593. Tower rebuilt 1740 after collapse. North side very damp. A jointly funded Historic England and Heritage Lottery Fund Repair Grants for Places of Worship grant was offered in December 2011 for repairs which are now completed. However, excess dampness still affects the building throughout and inadequately weathering copings on south aisle are putting this C16 monument at risk. The gutters to the nave and aisles leak and the below ground drainage is ineffective.

Contact: Trudi Hughes 01223 582739

Inntha			
11	1000	METON.	
13			

© Historic England

SITE NAME:	Church of St Michael, Church Road, Barton Turf
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049931

Parish church featuring C14 nave and aisles, C15 west tower. Aisles and chancel remodelled 1494, South chancel chapel 1440-45. Restored 1890 and 1934. Flint with ashlar dressings and slate roofs. Three-stage tower supported by flushwork diagonal buttresses on flushwork plinth. Significant problems with structural stability water penetration and the roof. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in late 2015 and project development phase is underway. Repair phase anticipated to commence autumn 2016.

Contact: Robert Parkinson 01223 582733



SITE NAME:	Church of St Peter and St Paul, Long Lane, Honing
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1169952

Parish church dating to the C15, heavily restored in 1795. Constructed from knapped flint with ashlar dressings and a slate roof. Maintained in regular use, but roof in poor condition and interior suffering from water ingress. In June 2015 the congregation were awarded a Heritage Lottery Fund Grants for Places of Worship grant for the re-roofing of the nave and chancel; new drainage and for tower repairs. Development work completed in 2016 and the repair phase anticipated to start in 2016.

Contact: Trudi Hughes 01223 582739



© Historic England

© Historic England

SITE NAME:	Church of St Peter and St Paul, The Street, Knapton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1306264

Parish church. Early C14 north-west tower and chancel, nave re-modelled C15 when chancel altered. Restored 1882 by Sir George Gilbert Scott. South nave roof very poor and failing. Previous serious water ingress, with potential damage to important roof carvings. Rainwater goods all poor and in need of replacement. Cracks in chancel arch. Very significant stonework problems in tower. Rusting of ferrous beams supporting bell frame probably responsible. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in 2014 and subsequent repair works are underway in 2016.

Contact: Robert Parkinson 01223 582733



© Ruth & Peter Blackman

SITE NAME:	Church of St Andrew, Church Lane, Hempstead-next-the-Sea, Lessingham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1373720

Medieval church with chancel dating from C13; nave, porch and tower C15. Nave and chancel thatched; unusually wide nave at 26 feet. C14 screen. Thatch seriously defective and leaking; tower high level masonry needs repointing, stone falling. A Historic England and Heritage Lottery Fund Repair Grants for Places of Worship grant was offered in December 2011. It is anticipated that the repair work will be completed by the end of 2016.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Mary Barningham Winter, Matlask
DESIGNATION:	Listed Place of Worship grade II*, RPG grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049180

Parish church in grounds of Barningham Hall. Flint with some iron conglomerate, plain tiles. West tower, nave and south porch in ruins. Chancel in use with west addition of 1830. Chancel of uncoursed flint with diagonal buttresses. Crow stepped gables in red brick, embattled parapet in gault brick; small blocked opening in west wall with brick dressings. Crow stepped gables with medieval pierced stone quatrefoil and embattled parapet. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in 2015 and project development underway in 2016.

Contact: Robert Parkinson 01223 582733



© Historic England

SITE NAME:	Church of St Nicholas, Salthouse
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation

1152302

On an eminence, broadside to the sea. C13/14, with much dating from the late C15. Tower has been pointed in cement mortar, and rendered in cement internally at base stage. Turret stair is similarly constructed, but with walls 18 inches thick in places, many vertical cracks with cracks on stair treads. In need of urgent repair plus belfry louvres require modification to reduce the amount of salt laden moisture entering the structure. An application for a Heritage Lottery Fund Grants for Places of Worship grant in 2015 was unsuccessful.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Church of All Saints, Stibbard
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049230

Parish church featuring west tower containing early C12 flintwork. Church restored in 1742 when buttresses added to tower and again in 1861-2 by Butterfield. Constructed from flint rubble with brick quoins to post-reformation buttresses, otherwise, limestone dressings. Bulging facework on tower identified as well as deterioration to brick and flint buttresses. Tower roof requires replacement. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in 2014 and project development for the repairs underway in 2016.

Contact: Malcolm Starr 01223 582723



MATTER TO B
A CALL OF LAND
© Historic England

SITE NAME:	Church of St Giles, Church Road, Swafield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1306217

Parish church CI4 with west tower of late CI5. Flint with ashlar quoins and slate roofs. Nave and chancel. Nave aisles removed and church partly rebuilt 1786. Four-stage tower with string courses between floors. Serious problems with water penetration in tower and nave stonework poor.

Contact: Robert Parkinson 01223 582733

© Nicholas Warns Architects

SITE NAME:	Church of All Saints, Kirkgate, Wighton
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1171738

A largely CI5 church, comprising tower, south porch, north and south aisles, nave and chancel. Building suffering from damp due to inadequate below-ground drainage system. South aisle roof slates laid at too slack a pitch and letting in water. Nave roof north side is slated with fixings failing. Internally the tower east wall cement render loose and in places at imminent risk of falling. A Heritage Lottery Fund Grants for Places of Worship grant was awarded early in 2014 and the repairs completed. A second grant application has been made to Heritage Lottery Fund for further urgent work.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

**ABBREVIATIONS** 



© sent by gethin harvey

SITE NAME:	Church of St Peter, North Walsham Road, Witton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1170258

Church with early C14 nave; later C14 chancel; early C15 tower. Restorations in C18 and C19. Walls: whole flints with ashlar dressings. Roofs: slated nave; thatched chancel. The rainwater gutters are undersized and incorrectly positioned causing rainwater to fall onto the walls and on to buttress tops and window tracery. There is excess salt migration, algae growth and damage to early internal plasterwork. The pamments (floor tiles) in the chancel are damp, all of which are indicative of failed above-and belowground drainage systems. The mullions of the tower west window are falling apart.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Gatehouse at ma	anor house, East Barsham, Barsha	m	
DESIGNATION:	Scheduled Monu	ment, LB grade I, CA	LIST ENTRY NUMBER:	1003997
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - ir	n need of management	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	David Kenny 01223 582760
SITE NAME:	Cross in St Giles	churchyard, Colby		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1018300
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - ir	n need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisa	Religious organisation		David Kenny 01223 582760
SITE NAME:	RAF Neatishead	Type 84 radar modulator building	g and four radar plin	ths, Neatishead
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1021408
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners		CONTACT:	David Kenny 01223 582760
SITE NAME:	Remains of a me Wighton	dieval ringwork castle known as C	Crabb's Castle, 680m	n north east of Crabb's Castle Farm,
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1018175
CONDITION:	Extensive significa	Extensive significant problems		Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	Arable ploughing		No
OWNER TYPE:	Commercial company		CONTACT:	David Kenny 01223 582760
	SITE NAME:	Wolterton Hall, Wickmere / Erpingham / Itteringham	between Thomas	nd woodland designed as a collaboration s Ripley, Charles Bridgeman and Horatio
	DESIGNATION:	Registered Park and Garden grade II*, 13 LBs, SM, CA	mid-C19 gardens	nding an early C18 Palladian mansion with s laid out by William Sawrey Gilpin. The v Park with a focus on wildlife
	CONDITION:	Generally unsatisfactory with major localised problems	management, sor definition of lake	me fields arable others pasture. Loss of margins. Some replanting of clumps to to north of house. Built structures in very
	VULNERABILITY:	High	poor condition, F	Peach House in kitchen garden particularly
	TREND:	Stable	vulnerable.	
© Historic England	NEW ENTRY?:	No		

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D

Private 1001022

OWNER TYPE:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: David Eve 01223 582721

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Cromer		
DESIGNATION:	Conservation Area, 77 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Rhymes (LPA) 01263 516367
SITE NAME:	Fakenham		
DESIGNATION:	Conservation Area, 85 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Paul Rhymes (LPA) 01263 516367
SITE NAME:	Happisburgh		
SITE NAME:  DESIGNATION:	Happisburgh Conservation Area, 9 LBs, RPG grade II	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, 9 LBs, RPG grade II		
DESIGNATION: CONDITION:	Conservation Area, 9 LBs, RPG grade II Very bad	TREND:	Deteriorating
DESIGNATION: CONDITION:	Conservation Area, 9 LBs, RPG grade II Very bad	TREND: CONTACT:	Deteriorating Paul Rhymes (LPA) 01263 516367
DESIGNATION:  CONDITION:  VULNERABILITY:	Conservation Area, 9 LBs, RPG grade II Very bad Medium	TREND: CONTACT:	Deteriorating Paul Rhymes (LPA) 01263 516367
DESIGNATION: CONDITION: VULNERABILITY: SITE NAME:	Conservation Area, 9 LBs, RPG grade II Very bad Medium Melton Constable Park, Melton Constable / Swante	TREND:  CONTACT:  on Novers / Hindo	Deteriorating Paul Rhymes (LPA) 01263 516367  Iveston
DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:  DESIGNATION:	Conservation Area, 9 LBs, RPG grade II Very bad Medium  Melton Constable Park, Melton Constable / Swanto Conservation Area, 19 LBs, part in RPG grade II*	TREND:  CONTACT:  on Novers / Hindo  NEW ENTRY?:	Deteriorating Paul Rhymes (LPA) 01263 516367  Iveston No

### **NORWICH**



6, 9 and 10, Ninham's Court SITE NAME: DESIGNATION: Listed Building grade II\*, CA

Houses with medieval undercroft dating to C17. Painted flint rubble with brick dressings. Proposals for refurbishment and repair of roof and masonry under discussion.

Early C14 porch to former hall. Two storeys with two ground floor open bays. Window reveals and mullions, capitals, shafts and other areas of carved stonework are badly decayed. The roof upper chamber vault and windows are suffering from water ingress, and the raised ground to north and south is allowing damp to penetrate the structure. A programme of repairs has been agreed and discussions on implementation need to be re-started.

© Historic England

© Norwich City Council

CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1051924

Contact: David Eve 01223 582721

SITE NAME:	Bishop Salmon's Porch, Norwich
DESIGNATION:	Scheduled Monument and Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (E)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1004030 and 1051329 Contact: Will Fletcher 01223 582710



© Norwich City Council

SITE NAME:	Bethel Hospital, Bethel Street, Norwich
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Commercial company

1051362

Former hospital of C17 to early C18, partly converted to residential use with new uses agreed for other parts but not fully implemented. The C19 wing is in poor condition needing substantial repairs. The gable end of the C18 boardroom also in poor condition and in need of structural reinforcement.

Contact: David Eve 01223 582721

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England

Howard's House, 97, King Street, Norwich
Listed Building grade II*, CA
Poor
Vacant/not in use
D (D)
Commercial company

1372824

Long term vacant building, former house, converted to offices, now vacant. C17 with C18 and C20 alterations. Planning consent granted for redevelopment of the area including new use for the house but not implemented. Deterioration of the building arrested through temporary measures. Consent for repairs and refurbishment has been granted, initial investigation prior to works underway

Contact: David Eve 01223 582721

	1		
d			
		1	
1			
	3	$\cap$	

O Norwich City Council

SITE NAME:	St Mary the Less, Queen Street, Norwich
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Former parish church with C13 origins, currently used as an historical studies centre. The building is in need of repair, especially the roof. Tower masonry viewed from adjoining building and appeared to be in reasonable order. No action/strategy has been identified or agreed.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Octagon Chapel, Colegate, Norwich
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1280186

1051918

The Octagon Chapel is a former Presbyterian Chapel, now Unitarian Chapel. Built 1756 by Thomas Ivory. Red brick. Pantile roof. Octagonal plan. Single storey with gallery. Central door with semi-circular arch and moulded surround. Single-storeyed pedimented portico with for unfluted lonic columns and two pilasters. The door is flanked by sash windows with glazing bars and rubbed brick segmental arches. Roof leaks. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in the autumn 2015 and the project development stage is underway in 2016.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Mile Cross		
DESIGNATION:	Conservation Area, RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Chris Bennett (LPA) 01603 212513

### SOUTH NORFOLK



SITE NAME:	Church of St Wandregelius, Bixley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1050487

Parish church. Early C14 tower, remainder dates from 1868. The church was badly damaged by a fire in 2004 which destroyed the roof and interior. C16 memorial in chancel has been removed for safe storage. A repair scheme has been discussed but not implemented.

Contact: David Eve 01223 582721

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Nicholas, School Road, Bracon Ash
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1050695

1050695

Medieval parish church restored in C19. Comprises nave, south aisle; north porch, fine late C13 chancel, and mid C18 mausoleum on northern side of chancel. Rainwater gutters and downpipes causing severe deterioration on chancel north wall, also placing at risk the remains of a very significant fine C16 terracotta monument, similar in style and design to those in Oxborough church, commissioned by the Bedingfield family. First phase of a Heritage Lottery Fund Grants for Places of Worship grant has been completed. A second grant application to the Heritage Lottery Fund is to be submitted in 2016.

Contact: Malcolm Starr 01223 582723



SITE NAME:	Church of St John the Baptist, Diss Road, Bressingham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1373587

Late CI5/early CI6 church with late CI3 chancel and CI4 fabric. Water ingress above chancel arch and blown plaster at high level around eastern- and westernmost clerestory windows. Damp discolouration of plaster in north aisle. Evidence of moisture at junction of aisle roofs with arcades. Loss of render inside porch and west wall externally. Some rainwater goods missing or failed. Damage from water ingress and in need of urgent attention. A Heritage Lottery Fund Grants for Places of Worship grant was offered late 2015. Project development phase anticipated to commence summer 2016.

Contact: Robert Parkinson 01223 582733



Church of St Mary, Diss Road, SITE NAME: Burston and Shimpling Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: F (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1305672

C15 church. Nave with large replacement Perpendicular windows. Chancel rebuilt with south vestry. South porch with arch-braced roof. Tower collapsed in 1753 and west wall of nave supported by large red brick buttress. Roofs in very poor condition. A Heritage Lottery Fund Repair Grants for Places of Worship grant was awarded in 2014 and the repair works are underway and due for completion late 2016.

Contact: Robert Parkinson 01223 582733 © Historic England

1				
		1		
1		No.		

SITE NAME:	Church of St Edmund, The Street, Costessey
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1305980

The church sits on high ground at the northern end of the village of Old Costessey. Mainly C14 (Decorated), with a C15 porch. The upper section of the tower is in brick and much later, as is the bell turret. Links with the Jerninghams of Costessey Park, a prominent Catholic recusant family. The church suffers from dampness caused by deteriorating slate roofing over the nave and chancel. Both roofs have rusting fixings, and the Delabole slates are crumbling. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in 2015 and the project development phase is underway in 2016.

Contact: Trudi Hughes 01223 582739

© Historic England

© Mr D Collen

SITE NAME:	Church of St Mary, Earsham Road, Denton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1373626

Flint built with stone dressings and slate roofs. Late C13 chancel. North and south chancel windows with Y-tracery. Perpendicular north and south aisles with decorated east and west windows. Aisle roofs leaking; drainage and high level repairs now of the utmost urgency. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in January 2016. The project development stage is in progress 2016.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

© Historic England

© Historic England

SITE NAME:	Church of St Mary, Lower Street, Gissing
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation

1152891

The west tower and nave of this church date from the C11. Characteristic Norman windows of that period survive, but the nave roof was replaced in the C15 with a double hammerbeam roof, all the more remarkable for its small scale and good state of survival. Repairs are needed to the masonry and roofs of the tower, north porch and chancel. A Heritage Lottery Fund Grants for Places of Worship grant was offered 2015 and project development work commenced in 2016.

Contact: Malcolm Starr 01223 582723

	_	A	
	MI	1	1
1			1

Church of All Saints, Market Lane, Great Melton

DESIGNATION: Listed Place of Worship grade II\*

CONDITION: Fair

PRIORITY CATEGORY: F (F)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 105073 I

Church of C11 origins, with fabric surviving of that period (long and short quoins, and reused Roman tiles). The extent of C19 rebuilding or restoration is less extensive than once believed, hence its recent upgrading to II\*. Areas of flintwork in poor condition, especially on the tower. A Historic England and Heritage Lottery Fund Repair Grants for Places of Worship grant was offered in 2010 and the repairs completed in 2015. A Listed Places of Worship Roof Repairs grant was offered in March 2015 and the repairs commenced in 2016.

Contact: Malcolm Starr 01223 582723



SITE NAME:	Church of St Mary, Church Lane, Haddiscoe
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1169126

Parish church. C11 with C13 and C15 re-modelling. Round west tower, probably late C11, divided into stages by three stone bands. North west bay of chancel has C15 two-light window flanked by blocked circular openings. North aisle has two-light C13 'Y' tracery windows and, at north west corner, north doorway with billet hood mould and shaft, scallop and roll-moulded arches. Widespread damage from damp caused by inadequate disposal of rainwater is leading to deterioration of internal fabric and structural problems in external walls.

Contact: David Eve 01223 582721



SITE NAME:	Church of St Botolph, Chapel Lane, Morley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1373064

Parish church dating to the C15, restored and re-roofed in the 1960s. Constructed from flint with ashlar and brick dressings. Pantile roof. Although re-roofed in the 1960s, there are a number of slipped tiles on the south slope and heavy moss to the north, alongside blocked gutters. The rainwater goods are in a poor condition throughout. Pigeons in the tower may also be causing damage.

Contact: David Eve 01223 582721



© Historic England

SITE NAME:	Church of All Saints, Church Lane, Runhall
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1304940

Parish church dating from C12. The C12 round tower has a C19 brick corbel course and conical roof. There is a C15 porch with blind spandrel tracery to entrance. The tower is in a poor condition with large cracks at high level and slates falling from the roof. The tower is currently cordoned off for safety reasons. A Heritage Lottery Fund Grants for Places of Worship grant has been successful and the repair project is on-going in 2016.

Contact: Janine Dykes 01223 582724

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



0	<b>Historia</b>	England

SITE NAME:	Church of All Saints, Church Road, Shelfanger
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1373360

SITE NAME: Church of St Mary, Church Road, Yelverton DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: B (B) OWNER TYPE: Religious organisation

1050639

LIST ENTRY NUMBER:

Early C14 church. Tower with diagonal buttresses, embattled parapet with chequer flushwork and pyramidal tiled roof. Early C14 chancel with east window with intersecting tracery. Cl4 nave with C15 Perpendicular windows, and one decorated north window. Mural fragments in east end of chancel. Wall painting in chancel vulnerable to dampness in walls. Repair to roof needed to prevent water ingress and dampness in chancel, threatening an important medieval wall painting. Congregation is considering applying for a Heritage Lottery Fund Grants for Places of Worship grant.

Contact: David Eve 01223 582721

Parish church predominantly dating from C14 with C12 fragments, with the tower dated to C17. The masonry to part of the tower is in poor condition with detaching flints. The congregation has been offered a Heritage Lottery Fund Grants for Places of Worship grant in 2014 and the project development work is underway in 2016.

Contact: Malcolm Starr 01223 582723

© Historic England

SITE NAME:	Arminghall, sites discovered by air photographs, Bi	xley / Trowse with	Newton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003620
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Sites discovered by air photography at Markshall, (	Caistor St. Edmund	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002887
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Langley Cross 360m north of Park Farm, Chedgrave / Langley with Hardley / Thurton / Carleton St. Peter		
DESIGNATION:	Scheduled Monument, LB grade II, RPG grade II	LIST ENTRY NUMBER:	1020060
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Rain entry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Will Fletcher 01223 582710
SITE NAME:	Long barrow and round barrows on Broome Heat	h, Ditchingham / Br	oome
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004002
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Levelling	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Romano-Celtic temple 590m south east of St James	es's Church, Wickle	wood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020862
			5
CONDITION:	Extensive significant problems	TREND:	Declining
CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing	NEW ENTRY?:	Declining No
	- '		<u> </u>

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

#### PETERBOROUGH, CITY OF (UA)



© Dr Jackie Hill, Cathedral Archaeologist

SITE NAME Peterborough Cathedral precinct wall, Peterborough Scheduled Monument and Listed Buildings -  $10 \ \text{grade I}$ ,  $5 \ \text{LBs}$ , part in RPG grade II, CA DESIGNATION: CONDITION: Poor

OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE: Religious organisation

1003264 and 1126932: 1331514; 1126930; 1126937; LIST ENTRY NUMBER: 1161429; 1161668; 1331517; 1331494; 1126939; 1161737

Various sections of the Cathedral precinct wall, of medieval (and some places, perhaps, Saxon) origin with later stone and brick refacing, are in very poor condition and need significant amounts of repointing and recapping. Two sections of fallen wall and one propped section have been rebuilt. The walls are vulnerable to water penetration which has led to stone decay. Some repairs completed and discussions for further phase of repairs have been progressed during 2015-16.

An early C18 house adjacent to the remains of the cloister

at Peterborough Cathedral. The building is suffering from

covering. The building is occupied and maintained, but in

structural problems and failure of its modern flat roof

need of comprehensive structural and other repairs. Discussions continue as to how to fund this and how to use

Contact: Deborah Priddy 01223 582720



© Historic England

Laurel Court, 22, Precincts, SITE NAME: Peterborough Listed Building grade I, RPG DESIGNATION: grade II, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C)

the repaired building. Religious organisation

1310019 Contact: John Neale 01223 582719



© Historic England

SITE NAME: Barn at Wothorpe Farmhouse near Wothorpe Towers, Wothorpe DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: F (F) OWNER TYPE: Charity (heritage)

1127451

C17 stables. Repairs are well advanced. The adjoining barn and granary have been repaired and are occupied.



SITE NAME: Wothorpe Farmhouse near Wothorpe Towers, Wothorpe DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F)

C17 farmhouse. Repairs are underway three dormers on east face have been reinstated this year, and the reinstatement of the Collyweston roof slate will follow.

© Historic England

OWNER TYPE: Private LIST ENTRY NUMBER: 1265974

Contact: John Neale 01223 582719

Contact: John Neale 01223 582719

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

SITE NAME:	Fletton churchyard cross		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006839
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582760
SITE NAME:	Settlement site east of Uffington and Barnack Sta	tion, Barnack / Uffing	ton / Bainton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006792
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Four bowl barrows 690m and 550m ESE of The	Willows, Borough Fe	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021314
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman house north of Castor Mills, Castor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004673
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman site in Normangate Field, Castor / Ailswo	orth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006864
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bowl barrow 550m south east of Hill Farm, Eye		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021304
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Bowl barrow 570m north east of Slipe Farm, Eye		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021303
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman villa north of Oxey Wood, Helpston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006832
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Site revealed by aerial photography east of Lolha	ım Hall, Maxey			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006827		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760		
SITE NAME:	Three bowl barrows 390m north west of The Fi	rs, Newborough			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021317		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760		
SITE NAME:	Three bowl barrows and a ring ditch 590m and	Three bowl barrows and a ring ditch 590m and 500m north west of The Four Winds, Newborough			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021318		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760		
SITE NAME:	Sutton Heath, Romano-British site, Sutton / Sou	thorpe			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006880		
CONDITION:	Extensive significant problems	TREND:	Declining		
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582760		
SITE NAME:	A Bronze Age post alignment and timber platform at Flag Fen and associated Bronze Age and later field systems and settlement to either side of the Northey Road, Thorney				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1406460		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Deborah Priddy 01223 582720		
ITE NAME:	Bowl barrow 225m north east of Prior's Fen Far	Bowl barrow 225m north east of Prior's Fen Farm, Thorney			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021311		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760		
ITE NAME:	Bowl barrow 430m north east of Prior's Fen Farm, Thorney				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021310		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
	Commercial company	CONTACT:	David Kenny 01223 582760		
OWNER TYPE:	1 /				
OWNER TYPE:	Bowl barrow 490m west of Gores Farm, Thorne	ey .			
		LIST ENTRY NUMBER:	1021307		
SITE NAME: DESIGNATION:	Bowl barrow 490m west of Gores Farm, Thorne	•	1021307 Declining		
SITE NAME:	Bowl barrow 490m west of Gores Farm, Thorne Scheduled Monument	LIST ENTRY NUMBER:			

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME: Bowl barrow 730m WSW of Gores Farm, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021308  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 780m east of Bar Pasture Farm, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021309  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: David Kenny 01223 582760  SITE NAME: David Kenny 01223 582760  SITE NAME: David Kenny 01223 582760					
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 780m east of Bar Pasture Farm, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021309  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: David Kenny 01223 582760	SITE NAME:	Bowl barrow 730m WSW of Gores Farm, Thorney			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 780m east of Bar Pasture Farm, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021309  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: David Kenny 01223 582760	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021308	
OWNER TYPE: Commercial company  CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 780m east of Bar Pasture Farm, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021309  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: David Kenny 01223 582760	CONDITION:	Extensive significant problems	TREND:	Declining	
SITE NAME: Bowl barrow 780m east of Bar Pasture Farm, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021309  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: David Kenny 01223 582760	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021309  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: David Kenny 01223 582760	OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  OWNER TYPE: Commercial company  CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  OWNER TYPE: Private  CONTACT: David Kenny 01223 582760	SITE NAME:	Bowl barrow 780m east of Bar Pasture Farm, Thorn	ney		
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: David Kenny 01223 582760	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021309	
OWNER TYPE: Commercial company  CONTACT: David Kenny 01223 582760  SITE NAME: Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1021312  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  OWNER TYPE: Private  CONTACT: David Kenny 01223 582760	CONDITION:	Extensive significant problems	TREND:	Declining	
SITE NAME:  Bowl barrow 880m south west of Singlecote Cottage, Thorney  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1021312  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  NO  OWNER TYPE:  Private  CONTACT:  David Kenny 01223 582760	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1021312  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  NO  CONTACT:  David Kenny 01223 582760	OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: David Kenny 01223 582760	SITE NAME:	Bowl barrow 880m south west of Singlecote Cottage, Thorney			
PRINCIPAL VULNERABILITY: Arable ploughing New Entry?: No  OWNER TYPE: Private CONTACT: David Kenny 01223 582760	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021312	
OWNER TYPE: Private CONTACT: David Kenny 01223 582760	CONDITION:	Extensive significant problems	TREND:	Declining	
	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
SITE NAME: Two bowl barrows 940m south east of Bar Pasture Farm, Thorney	OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760	
	SITE NAME:	Two bowl barrows 940m south east of Bar Pasture Farm, Thorney			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021313	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021313	
CONDITION: Extensive significant problems TREND: Declining	CONDITION:	Extensive significant problems	TREND:	Declining	
DDINICIDAL VILLALITA DILITY. A	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
Arable ploughing New ENTRY: No	OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760	

## SOUTHEND-ON-SEA (UA)



SITE NAME: Manor House, Suttons Road, South Shoebury DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(C)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1306855 © Historic England

House, 1681. Currently vacant, last used as residential quarters. Re-use of the building is complicated by its location within a military site. A serious dry rot problem was treated 1998-2003, but has caused considerable damage to the interior. Building has been vacant for many years. Rigid application of 3-year break clause in all long leases granted by Ministry of Defence has seriously worsened potential for reuse by charitable trusts. On-going water ingress due to defective rainwater goods and failure of lead flashing at rear of building where main house abuts flat-roofed extension.

Contact: Sheila Stones 01223 582716

SITE NAME:	Crowstone, Westcliff-on-sea		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Abbie Greenwood (LPA) 01702 215004

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

#### **SUFFOLK**

#### **BABERGH**



SITE NAME:	Barn north east of Bentley Hall, Bentley Hall Road, Bentley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (A)
OWNER TYPE:	Private

Barn built C15, timber-framed and brick nogging. It is redundant and is only suitable for a very low-key use. It is structurally unstable and water is penetrating the walls in places, accelerating decay of its structure. Historic England and the Local Authority are involved in ongoing discussions with the owner to secure the conservation of the barn. Urgent works notice served and some repairs implemented. Work underway to prepare a Repairs Notice, anticipated for Spring 2017.

© Historic England

LIST ENTRY NUMBER: 1351965

Contact: Robert Parkinson 01223 582733

Contact: Malcolm Starr 01223 582723



SITE NAME: Church of St Mary, The Street, Arwarton DESIGNATION: Listed Place of Worship grade I CONDITION: Very bad PRIORITY CATEGORY: F (F) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1286145

Parish church located in the small hamlet of Erwarton (or "Arwarton"). Historic fabric of church datable from C14. Some interesting repairs of 1838 in the Georgian tradition, which add to the architectural character. Serious erosion of the tower facework and quoins, posing a risk of partial collapse. A Heritage Lottery Fund Grants for Places of Worship grant was offered in 2014. Repairs are due to be completed late 2016.

© Historic England

SITE NAME:	Church of St Mary, Fish Pond Hill, Harkstead
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1286085

Parish church twelfth century origins: fourteenth century south arcade and west tower, fifteenth century chancel and south porch. Victorian rebuilding of roofs chancel and north chapel. Random flint, rubble and septaria, red brick crenellations to tower, stone dressings, stone and flint flushwork to buttresses, carved stone panels to plinth of tower. Red plain tiled roofs. Decay of masonry particularly tower septaria. Roofs failing. HLF grant applied for mid 2016.

Contact: Robert Parkinson 01223 582733

Contact: Trudi Hughes 01223 582739



SITE NAME:	Church of St Nicholas, Hadleigh Road, Hintlesham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1351644

Parish church, medieval, restored C19. Tower of flint and rubble, stone dressings, nave and chancel rendered tile roofs. Various roofs are now in need of retiling. An application for a Heritage Lottery Fund Grants for Places of Worship grant was unsuccessful.

© Historic England

SITE NAME:	Enclosure east of Nether Hall, Harkstead		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005981
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Roman villa north east of Rodbridge House, Lor	g Melford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005969	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Wissington ring ditch cluster, Nayland-with-Wis	sington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003758	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Wood Hall moated site, Sudbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005997	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	David Kenny 01223 582760	
FOREST HEATH				
SITE NAME:	Bowl barrow 990m south west of Cranhouse Fa	rm, Eriswell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018100	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Three bowl barrows 750m south west of Pin Fa	Three bowl barrows 750m south west of Pin Farm, Gazeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018103	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Two bowl barrows 150m south east of Warrenhill Farm, Herringswell			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018674	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	
SITE NAME:	Bowl barrow known as How Hill, east of Heron	field Belt, Icklingham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017795	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	Yes	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760	

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Mildenhall Roman site, Mildenhall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006037
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Newmarket, Newmarket / Snailwell		
DESIGNATION:	Conservation Area, 107 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Boyd Nicholas (LPA) 01638 719248

#### MID SUFFOLK



SITE NAME: Badley Hall barn 100 metres south east of Badley Hall, Badley DESIGNATION: Listed Building grade II\*, SM CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C(C)OWNER TYPE: Private

1231085

A very well built and unusually complete C15 or early C16 timber-framed barn on a flint rubble plinth. Timber frame in need of repair.

© Historic England

LIST ENTRY NUMBER:

Contact: Clare Campbell 01223 582738



Badley Hall dovecote 60 metres SITE NAME: east of Badley Hall, Badley DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

A rare example of a near-complete C16 timber-framed dovecote. Some nesting boxes remain. First phase of repair programme carried out in 2013 and repairs ongoing.

© Historic England

LIST ENTRY NUMBER: 1231084

Contact: Malcolm Starr 01223 582723



© Historic England

Barn 200 metres west of Hall's SITE NAME: Farmhouse, Halls Lane, Norton DESIGNATION: Listed Building grade II\* CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: B (C) OWNER TYPE: Private

1352406

Timber-framed and weatherboarded barn, mid C16. High quality timber frame with some rare features. Soleplates rotted and whole barn leaning sideways. Although propped, permanent repairs now required to secure the structure. Roof was wind and weathertight on date of last visit. Discussions continue regarding repairs and potential alternative uses. Historic England Repair Grant for Heritage at Risk accepted and project development phase, including a structural survey, commenced summer 2016.

Contact: Claire Fidler 01223 582735



© Historic England

SITE NAME:	Church of St Lawrence, Church Lane, Brundish
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1352203

Parish church of Norman origins with C12 tower. C14 and C15 alterations. Very fine internal features include a window niche with surviving medieval polychrome decoration. A C15 pulpit and a collection of pews typifying their development from medieval to C18. Very poor rain and ground water disposal arrangements have resulted in extensive internal damp and initial stages of decay in the pews. This is also affecting the electrical wiring. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in 2015 and repair works are on-going due for completion late 2016.

Contact: Malcolm Starr 01223 582723

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

LIST ENTRY NUMBER



© Historic England

© Historic England

© Historic England

SITE NAME:	Church of St Mary and St Laurence, The Street, Great Bricett
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation

1352160

Formerly the monastic church of the Priory of St Leonard, founded 1114-19. The Prior's Lodgings and remains of the cloister also survive. The walls have much early, possibly original fabric with traces of medieval wallpaintings and decoration. Tiled roofs in poor condition and leaking. An application for a Heritage Lottery Fund Grants for Places of Worship grant was unsuccessful.

Contact: Malcolm Starr 01223 582723

X ASS	LA
	A TOTAL
PAR	
A	
A STATE OF THE PARTY OF THE PAR	

SITE NAME:	Church of St Mary, The Street, Horham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1032540

Medieval parish church. Core of the nave probably dates from C12. The nave contains C12 doorways. The chancel was largely rebuilt 1879-8. Beneath all the belfry lights are square flushwork. The nave seating includes C15 benches with poppyhead ends enriched with buttressing and fleurons. Principal issue of damp, particularly on external walls of the nave.

Contact: Janine Dykes 01223 582724



SITE NAME:	Church of All Saints, The Street Laxfield
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1180967

Church of C14 origins, but earlier fabric may survive. Good collection of pews from the medieval period onwards, and traces of medieval polychrome decoration surviving on the font. The very fine flushwork tower has suffered from erosion and weather ingress at high level. South and west faces have been repaired, but work is now needed urgently to the east and north before fabric is lost. Leakage at the abutment of the CI9 chancel roof to the nave. A Heritage Lottery Fund Grants for Places of Worship grant was awarded in 2015 and the repairs are underway in 2016.

Contact: Malcolm Starr 01223 582723

Contact: Trudi Hughes 01223 582739

A	

SITE NAME:	Church of St Andrew, Church Road, Redlingfield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1032497

Parish church dating back to C14. Chancel rebuilt c1800. The stump of the tower is of red brick with diaperwork in dark header bricks and above is a timber framed belfry probably C16 date. There are signs generally of masonry collapse and water penetration inside the church.

© Historic England



© Historic England

SITE NAME:	Church of St Margaret, Little Green, Thrandeston
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1032763

Medieval parish church dating from the C15 apart from the C13 chancel which was re-fenestrated in C15. The church was fully restored c1870-80. Short gabled north porch has a C19 outer arch. There is damp throughout the interior of the church which is particularly bad around the pews at low level.

Contact: Janine Dykes 01223 582724

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

SITE NAME:	Baylham Roman site, Coddenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006033
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582760



© Historic England

SITE NAME:	Shrubland Hall, Coddenham / Hemingstone / Barham
DESIGNATION:	Registered Park and Garden grade I, 22 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000155

Extensive mid-C19 Italianate garden by Charles Barry set in C17 park, for which Humphry Repton prepared a Red Book in 1789 and William Woods in 1808. Many proposals have been implemented in the expanded park. The site is in divided ownership following sale in 2009 and boundary fence erected. Management of Old Hall landscape is improving but the built garden features and planting are significantly decayed. Improved management strategies for the park as a whole need to be developed to safeguard its

Contact: Clare Campbell 01223 582738

#### ST EDMUNDSBURY



<u>බ</u>	Historic	Fngland

SITE NAME:	Atomic bomb store on Thetford Heath, Barnham
DESIGNATION:	Scheduled Monument, 5 LBs
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1020781

Former Ministry of Defence strategic defence site, built 1953-1955. Purchased and in use as an industrial estate since 1965. Elements at risk due to short term anticipated lifespan. Successive grant aided phases of work undertaken between 2011-2015 with privately funded works by the owner, have greatly improved the condition of the site. Owner has received a fifth phase of grant which includes urgent repairs to gantries in front of buildings 60 & 61, This work will be complete by the end of 2016, following which we anticipate its removal from the Heritage at Risk register.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	The Guildhall and attached Railings, Guildhall Street, Bury St. Edmunds
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1363726

Guildhall: C13; C15 with C17, C18 and C19 adaptations. Predominantly of flint and brick, with tiled and slated roofs. The front elevation dates from the early C19, but older fabric lies behind, including the two principal public rooms: both of which have a rare mid C14 timber framed roof including both king-and queen posts, with arched braced roof resting on corbels. Roof above now repaired. Roofs over adjoining Council chamber & ops room leaking badly and structural movement evident in ops room roof structure. Grant offered June 2016.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Moreton Hall, Bury St. Edmunds
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (independent)
LIST ENTRY NUMBER:	1022597

Robert Adam House of 1773. Urgent high level works to the exterior are needed.

Contact: Clare Campbell 01223 582738

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

LIST ENTRY NUMBER:

LIST ENTRY NUMBER



© Historic England

SITE NAME:	Moated site at Denham Hall, Denham
DESIGNATION:	Scheduled Monument, LB grade
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)

1019803

Private, multiple owners

Remains of brick banqueting house and associated revetting on northern corner of moat island. North-east wall and part of the underlying revetment have recently collapsed into the moat, resulting in loss of historic fabric and instability to other parts of the structure. Issues include erosion around the base, unstable ground formations behind the collapsed brickwork, a large vertical fracture in the corner of the north-west wall and lintel failures and loss of brick work around the doorway and window. Part of grade II listed garden wall also collapsed.

Contact: Nick Carter 01223 582751

SITE NAME:	Stoke College, Stoke-by-Clare	
DESIGNATION:	Listed Building grade II*, CA	
CONDITION:	Fair	
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1265211	

Originally a Benedictine Convent, converted to a college and then a mansion after the dissolution. Repairs required to the roof and other areas of building.

Contact: Clare Campbell 01223 582738



© Historic England

© Historic England

SITE NAME:	The Umbrello, Great Saxham Hall, Chevington Road, Great Saxham, The Saxhams
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

Early C19 Coade stone folly. Very poor condition: roof missing, ingress of water is rusting iron core. The proposal to dismantle it and re-erect in a new location had been granted listed building consent, but was not implemented. A programme of photographic recording and building analysis was undertaken by Historic England in 2012. No further progress has been made since this date.

Contact: Clare Campbell 01223 582738



SITE NAME:	Church of St Mary, Cavendish
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENITRY NILIMBER:	1021774

1031410

Church dating from the C14, prominently situated in the Cavendish Conservation Area at the east end of the green. Unusual features include the vaulted parvise and external arched timber bell cage and flagpole combined which sits on the tower parapet. There is some deterioration of masonry on the tower. The flagpole has begun to lean, possibly because the plated joint at low level is becoming ineffective. An application for a Heritage Lottery Fund Grants for Places of Worship grant is being considered.

Contact: Malcolm Starr 01223 582723

(C)	Historic	England

SITE NAME:	Round barrows, Risby Poor's Heath East, Flempton / Risby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006038
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Sites north west and south east of Fornham All Sai	nts, Fornham All Sa	ints / Hengrave
designation:	Scheduled Monument, 2 CAs	LIST ENTRY NUMBER:	1006018
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Interrupted ditch system west of Hall Farm, Keding	gton	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1005959
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman villa south east of Lidgate, Lidgate		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002971
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	Roman settlement south of Ixworth, Pakenham		
designation:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006019
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	East Low Hill tumulus, Rushbrooke with Rougham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002974
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582760
SITE NAME:	Haverhill Hamlet Road, Haverhill		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Johnson (LPA) 01284 75733
SITE NAME:	Haverhill Queen Street, Haverhill		
designation:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Johnson (LPA) 01284 75733

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

#### SUFFOLK COASTAL



© Historic England

Martello Tower "Z", south east of Buckanay Farm, Alderton

DESIGNATION: Scheduled Monument and Listed Building grade II

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: A (B)

1006014 and 1030773

Private

Martello Tower Z forms part of a chain of Martello towers along the south and east coast of England dating from the early C19. The tower has been unused since the Second World War. Whilst generally robust and structurally sound a recent condition survey undertaken as part of a Heritage Lottery Fund Landscape Heritage Initiative has indicated the need for repairs to prevent water ingress. Further discussions with the owner are needed to consider any urgent conservation works to the tower.

Contact: Claire Fidler 01223 582735

No. of
TRA
-

© Historic England

SITE NAME:	Transmitter Block, Bawdsey Manor, Bawdsey
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

Concrete transmitter block built in 1937. Site of pioneering radar development. Featured in BBC "Restoration" TV programme. Some repair and refurbishment works undertaken. Bawdsey Radar Group have commissioned an options appraisal. A Conservation Management Plan has been produced for the estate. A grant from Historic England has assisted in developing a repair project. The Heritage Lottery Fund offered a grant in 2013 and so have Historic England. Work expected to commence on site in 2016.

Contact: Trudi Hughes 01223 582739



© Historic England

SITE NAME:	Martello tower on golf course adjoining Woodbridge Haven., Felixstowe
	Scheduled Monument I B grade

1245307

DESIGNATION: Scheduled Monument, LB grade

condition: Poor

PRIORITY CATEGORY: D (D)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1006036

Martello Tower T on Felixstowe Golf Course. Built c1810-1812 as part of defences against Napoleonic invasion. Roof and walls in very poor condition with water penetration. Historic England in discussion with the owners over repairs and interpretation.



Part occupied/part in use

Contact: Robert Parkinson 01223 582733

One of the finest, and possibly tallest, post mills in the United Kingdom. Built in 1812 and operational until 1956. Restored in 1976; temporary supports added 2004; post

out of alignment, trestle fractured and now in need of comprehensive and permanent repair. Owner intends to self-fund a development phase during 2016 covering survey, specification and schedule of repair works needed to inform future repair phases along with costings. A Historic England grant will be discussed once this work is

complete.

•



© Historic England

SITE PORTE.	Friston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1215741

Contact: Claire Fidler 01223 582735



© Historic England

SITE NAME:	Glevering Hall Orangery, Easton Road, Hacheston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1377281

Decimus Burton. Glass missing, especially from the dome, and rusting iron cramps are forcing apart the stonework. Discussions regarding repair works ongoing.

Orangery built in classical style circa 1835. Architect

Contact: Clare Campbell 01223 582738

## PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Remains of Sibton Abbey, Sibton
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Other not for profit group

Remains of Cistercian abbey built in 1150. Damaging vegetation. Occasional trespass and vandalism. Building currently suffering ongoing decay. The building is a ruin with no possibility of economical beneficial use. Condition survey undertaken. Trees removed. A conservation repair scheme has been offered grant aid by Historic England and it is anticipated that repair works can begin in 2017.

The medieval ruins of a much larger church are at risk due to structural failure and unconsolidated walling. Some active areas of loose stonework are apparent where flint cobbles and brick are eroding out of the wall surfaces. A programme of Historic England and WREN grant funded repairs to conserve the ruins has been agreed and works are in progress. The Church of St Andrews, which is

Contact: David Kenny 01223 582760

regularly used for worship, is not at risk.

© Historic England

© Historic England

SITE NAME:	St Andrew's Church, the Street, Walberswick
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (A)
OWNED TYPE	Deliniana amandiana

1018327 and 1377160

Religious organisation

LIST ENTRY NUMBER: 1283823 Contact: David Kenny 01223 582760



SITE NAME:	Church of St Andrew, The Street, Alderton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1377186

Parish church with ruinous west tower. Chancel rebuilt in 1862 and the nave restored in 1864. The condition of the drainage and guttering is unclear; however, there is significant evidence of damp within the church interior. The ruinous tower is blocked off from the nave and is overgrown by trees and shrubs. Slow decay continues, no solution yet agreed for either the church, or the ruinous tower.

Contact: Trudi Hughes 01223 582739



11111111	1
THE P	(
-	ı
	(
	ı

SITE NAME:	Church of St Andrew, St Andrews Road, Felixstowe
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1377388

Church built c1929-31 and is an interpretation of a late C15 East Anglian church constructed using concrete. The concrete is in a poor condition and the congregation is exploring options for repair.

Contact: Robert Parkinson 01223 582733



© Historic England

© Historic England

SITE NAME:	Church of All Saints, The Street, Hacheston
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1199742

from C12, with C15 hammerbeam roof. The church requires urgent roof repairs to halt water ingress. Planning Consent and Faculty has been granted for repair works which will be funded by the PCC. The repair works are expected to commence in 2016.

Medieval parish church restored mid C19. Fabric dating

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).



SITE NAME:	Church of All Saints, Church Road, Ramsholt
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1030735

Parish church, unchanged since the early C19, with box pews, a double-decker pulpit on the south side of the nave, and no electricity: services being held by candlelight. The round tower is at least of Norman origin but is allegedly Saxon, serving as a watchtower for Viking raids. The tower roof and masonry are in very poor condition. A Heritage Lottery Fund Grants for Places of Worship grant was offered in 2013 and the repairs commenced in 2016.

Contact: Malcolm Starr 01223 582723

© Historic England



SITE NAME:	Church of St John Baptist, Church Street, Saxmundham
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1268184

Parish church, C14 with significant C19 alterations. South aisle roof leaks, gutters undersized with evidence of rot on the roof boarding. The south side roofs to the nave and chancel have many tingles, indicative of rusting ferrous slate fixings. There is a C15 hammer beam roof below nave roof slating. A Heritage Lottery Fund Grants for Places of Worship grant was offered March 2016. The project development stage commenced in 2016.

4 Contact: Trudi Hughes 01223 582739

© Historic England



SITE NAME:	Church of St Margaret, Church Lane, Shottisham
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation

The church is believed to be of C14 origins, but incorporates re-used Roman tiles and possibly Saxon or early Norman quoins. The masonry of the tower and east gable of the nave are in poor condition. An application for a Heritage Lottery Fund Grants for Places of Worship grant for this work was successful and the development phase commenced in 2016.

LIST ENTRY NUMBER: 1030736 Contact: Malcolm Starr 01223 582723

SITE NAME:	Settlement site east of the Cedars, Alderton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005977
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Settlement sites 330yds (300m) north west of Waln	nut Tree Farm, Ho	llesley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006002
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760
SITE NAME:	Rectilinear enclosures 1km south west of Boyton H	Iall Farm, Hollesley	/ Boyton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006005
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582760

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area s LB Listed Building c, LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Henge and associated barrow cemetery south of Home Whin Farm, Shottisham / Sutton			
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1017632
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial company		CONTACT:	David Kenny 01223 582760
SITE NAME:	Bowl barrow on Waldringfield Heath, 150m south of H		of Heath Farm, Wa	aldringfield
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1008506
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	David Kenny 01223 582760
	SITE NAME:	Bawdsey Manor, Bawdsey		between 1885 and 1909 on advice from
	DESIGNATION:	Registered Park and Garden grade II, 8 LBs	Pulhamite cliff ga built in the 1890s	The garden contains an extensive rden, complete with seats and alcoves, s by Pulham & Co. Site is improving with
			house no longer at risk following Historic England gran aided works which were completed in 2012. Informed	
	CONDITION:	Generally satisfactory but with significant localised problems	aided works whi	ch were completed in 2012. Informed
	CONDITION:  VULNERABILITY:		aided works which work to some ga Pulhamite cliff ga	ch were completed in 2012. Informed rden structures now being undertaken. rden in poor condition and in need of
		significant localised problems	aided works which work to some ga Pulhamite cliff ga	ch were completed in 2012. Informed rden structures now being undertaken. rden in poor condition and in need of ment; scrub clearance underway. Coast
	VULNERABILITY:	significant localised problems High	aided works which work to some gath Pulhamite cliff gath strategic manage	ch were completed in 2012. Informed rden structures now being undertaken. rden in poor condition and in need of ment; scrub clearance underway. Coast
© Historic England	VULNERABILITY: TREND:	significant localised problems High Stable	aided works which work to some gath Pulhamite cliff gath strategic manage	ch were completed in 2012. Informed rden structures now being undertaken. rden in poor condition and in need of ment; scrub clearance underway. Coast

SITE NAME:	Felixstowe South, Felixstowe		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Robert Scrimgeour (LPA) 01394 444616

#### **WAVENEY**



© Historic England

SITE NAME:	Whaley's, St James' Road, All Saints and St. Nicholas, South Elmham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1032000

Former farmhouse. Mid to late C16. 2 storeys and attics; 3cell plan, with internal chimney-stack and cross-entry. Timber-framed and rendered, with thatched roof. The internal stack has a plain red brick shaft. Plank door beneath a plain Doric portico. Good timbering exposed inside: 5 bays. The thatched roof is in a very poor condition and partially covered by tarpaulin. Several rafters and a purlin have failed. The external plaster is deteriorating and damp is becoming an issue. Highly decorative plaster ceilings and fireplaces could be at risk from damp and water ingress.

Contact: Claire Fidler 01223 582735



SITE NAME: Moat Farmhouse, Shadingfield, **Beccles** DESIGNATION: Listed Building grade II\*, SM CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1032132

C16 farmhouse with C19 alterations and brick wing to rear. Good quality timber frame, finely moulded beams and joists internally. Scheduled moated site. Under tarpaulin and scaffolded.

Contact: Clare Campbell 01223 582738 © Waveney District Council

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Bungay Castle, Bungay
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)

Charity (heritage)

1006060 and 1034404

Contact: Robert Parkinson 01223 582733

Contact: Malcolm Starr 01223 582723

SITE NAME: CONDITION:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

Mettingham Castle, Mettingham DESIGNATION: Scheduled Monument, 2 LBs Poor OCCUPANCY: N/A

B (New entry)

Private

1006055

Substantial remains of college of canons; the site and remains are in various ownerships. Many elements of structure in need of consolidation to prevent loss of medieval masonry. Repairs completed in 2009 to Keep and part of curtain wall. Further repairs needed to Gatehouse and related parts of curtain wall. A grant application to HE for this is about to be submitted.

Medieval castle built by Roger Bigod. Problems with the southern C13 tower to the gatehouse have been addressed and urgent repairs completed, discussions ongoing over further repairs and conservation work to the keep, northern gatehouse tower, and curtain and bailey walls. Conservation statement and condition survey currently being prepared to inform next steps.

© Historic England

SITE NAME: Church of St Margaret, Stoven, Brampton with Stoven DESIGNATION: Listed Place of Worship grade II\* CONDITION: Very bad PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1032100

Parish church. C12 doorways, the lower portion of the tower possibly medieval; remainder entirely rebuilt 1849-50 in neo-Norman style. The tower is of flint rubble, the bell-chamber stage faced with knapped flint; the nave and chancel are plastered; stone dressings. Slated roofs with courses of fish-scale slates. Poor construction in C19 has


resulted in serious structural failures in masonry, particularly the south nave wall, and water penetration. Roof poor; interior fair; rainwater goods satisfactory.

Contact: Robert Parkinson 01223 582733

© Historic England

SITE NAME:	Two moated sites adjoining All Saints' Church, All Saints and St. Nicholas, South Elmham		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1017633
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760

#### SUFFOLK (OFF)



© Wessex Archaeology, Crown Copyright

SITE NAME:	Dunwich Bank
DESIGNATION:	Protected Wreck Site
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
PRIORITY CATEGORY:	E (New entry)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1000073

Once suggested to be a casualty of the Battle of Sole Bay 1672, this site is now believed to be the remains of a 16th century armed merchant vessel or possibly a rare example of an early military transport vessel. The site has been placed on the Heritage at Risk register due to the discovery of the theft of a bronze gun from the site in the summer of 2015.

Contact: Chris Pater


#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

#### THURROCK (UA)



SITE NAME:	State Cinema, George Street, Grays
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1111543

The State Cinema is one of the best preserved of the 'super cinemas' of the late 1930s. It was constructed in 1938 by F G M Chancellor for Frederick's Electric Theatres. The building has suffered from heritage crime and the roof, rainwater goods and interior are in poor condition. The reuse of the vast cinema poses complex problems, as confirmed by a feasibility study some years ago. The building is in new ownership and preliminary proposals are under discussion for conversion to a public house. Currently, asbestos and bird droppings are being removed throughout the building.

Contact: Sheila Stones 01223 582716



© Historic England Archive

SITE NAME:	Coalhouse Fort, Tilbury
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1013943

Ruined C19 armoured casemate fort on site of earlier battery; refortified since the two World Wars. Problem of water ingress to casemates; barrack block in severe disrepair. Repair work to the gatehouse barrack block was completed in 2011 with grant aid. Heritage Lottery Fund scheme for conversion of generator house to cafe is now complete. Storm damage to roof of north caponier has now been repaired. Further Historic England funded repairs and project development for reuse on-going.

Contact: Deborah Priddy 01223 582720

SITE NAME:	Crop mark complex, Orsett		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002134
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582760
SITE NAME:	East Tilbury		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Planning Dept (LPA) 01375 652275

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

This document is one in a series of publications produced as part of Historic England's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at HistoricEngland.org.uk/har

Heritage at Risk

Published October 2016

1 Waterhouse Square

138–142 Holborn

London EC1N 2ST

© Copyright Historic England 2016

Product code: 52031

