Woore Parish	Council Fix My Street Log (Update 11.10.21)
--------------	---

Status	Location	Description	Date Reported	Date Fixed	Notes
	A51 at junction of Candle Lane, S/B side verge	30mph sign is obscured by overgrown by	03.008.21		No Action
	A525 W/B verge opposite TT Pumps Premises	Collapsed gullies in the verge, very dangerous	06.09.21	30.09.21	Temporary cones placed after 5 days, repairs now carried out.
	A525 on E/B Footpath adjacent to "The Meads"	Double BT Manhole Cover in footway, Covers are not seated properly after removal maintenance, and presents a trip hazard. There is a 15mm up-	11.08.21		This was originally reported on the Shropshire Council Portal some months previously. Still no action at 06.10.21! Cover marked in white paint
	Bellmouth to entrance to Ash Mount off A525	Multiple Severn Trent Covers (4)have large potholed areas around them, total area is 1.2 sum eroded to a depth of 30-40mm. Serious trip hazard, as it hit isin the line of the pedestrian	11.08.21		Previously reported to Shropshire Council some 3 months previously.
	A525 W/B carriageway, opposite the Property known as "The Brambles"	Rocking manhole cover, in danger of collapse.Severn Trent	11.08.21		This cover has previously had the blacktop surrounding it replaced, hoover the cover was not replaced at the same timelPreviously reported to Shropshire Council some 3 months previously.
	A525 E/B Carriageway opposite the entrance to Swan Farm Lane	500x500x120deep pothole in carriageway channel area.	11.08.21		This pothole has been repaired poorly previously, and has "plucked out" again. Constitutes a serious hazard for cyclists and cars . Previously reported to Shropshire Council twice in the previous 3 months, not action. It has been panted white
	A51 N/B opposite entrance to Betty's lane	Previously repaired Manhole surround, (2020), breaking up in carriageway with a significant pothole developing. Severn Trent	19.08.21		No Action
	A525 W/B carriageway opposite Red Lion Farm	Rocking manhole cover, in danger of collapse. Severn Trent	19.08.21	30.09.21	Previously reported 3 months previous to Shropshire County Council. Now fixed.
	A525 W/B carriageway opposite Property known as "Resthaven" the entrance with a 5 bar gate.	Rocking manhole cover, in danger of collapse. Severn Trent	19.08.21	30.09.21	Previously reported 3 months previous to Shropshire County Council. Now fixed.
	A51 in the middle of S/B Lane	Linear pothole, road surface breaking up over approx. 10m length. Previously patched. Also breaking up around MH in carriageway channel.	19.08.21		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.
	A51 London Road S/B carriageway. Approx. 100 m South of entrance to property known as Warren Heights	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.	19.08.21		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.
	A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.	19.08.21		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.
	A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Carriageway breaking up around gulley causing pothole in channel Very Dangerous	19.08.21		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.
	A51 Verge - Steps and Handrail Leading up to Public Footpath 0236/26/1	Steps and handrail in need of repair since the handrail has rotted and steps eroded.	30.09.21		No Action
	A51 S/B carriageway opposite junction with Bearstone Road.	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.	06.10.21		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.
16	B5026 Bearstone Road S/B carriageway opposite Dorrington Lane Crossroads.	Double BT Manhole collapsing, roads surface eroded away from frame.	06.10.21		Been in that condition for over 4 weeks
17	B5026 Bearstone Road entrance	Loose Public Footpath (0236/33/1) Sign, needs re-affixing to Stile.	30.09.21		No Action
18	Eastern end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.	07.10.21		New Report
19	Middle of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.	07.10.21		New Report

2	0 Western end	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding. This was previously repaired earlier this year, and has failed again.	07.10.21	New Report	
2		Edge of carriageway breaking up and has developed into a serious linear pothole approx 100x500x100 deep, adjacent to previous repair. Dangerous for cyclists and cars.	07.10.21	New Report	
2	2 A525 Edge of W/B carriageway approx. 35 past junction with Beech Avenue	Surround to double BT manhole cover breaking up, causing a pothole that is deteriorating. This is a previously repaired manhole.	07.10.21	New Report	
2	3 Public Footpath 236/47/1 through Woore Church Yard	Deterioration of footpath through churchyard is a hazard for pedestrians and need repair. First reported. 10.42.1 Outdoor Recreation gave Ref. No. UM110821:90a81	07.10.21	New Report	
2	Public Footpath 0236/23/21 at the entrance from Northlands	Footpath has deteriorated at the entrance to Northlands and is presenting a trip hazard. Outdoor recreation advised the following ref. No. UM110821:1a5c7	07.10.21	New Report	