

Woore Parish Council Fix My Street Log (Update 16.01.22)					
Date Reported	Status	Location	Description	Date Fixed	Notes
11/10/2019		Junction of Candle Lane and the A51 Nantwich Road - Blocked Culvert causing Flooding	This Issue was first reported to Shropshire Council 11.10.19 - On Candle Lane at the end nearest to the A51 Nantwich Road the culvert is overflowing with water, due possibly to the drain than runs under the road blocked which would allow the water to run into the field. There is also concern of two vehicles passing on this lane that due to the culvert obscured by tall grass that a vehicle may end up in the culvert.....does this sever the access sever the access		Update 16.12.21 Reported on FMS - The PC are not aware of any jettting taking place, also at the time of Reporting the Highways Technician advised installing bollards to inform road users. Since 2019 there have been two white vans gone into the culvert that I know of, noticed again yesterday that the road is flooding again!
03/08/2021		A51 at junction of Candle Lane, S/B side verge	30mph sign is obscured by overgrown by vegetation		Update 01.09.21 reported on FMS - No Action by SC.
11/08/2021		A525 W/B carriageway, opposite the Property known as "The Brambles"	Rocking manhole cover, in danger of collapse. Severn Trent		This cover has previously had the blacktop surrounding it replaced, however the cover was not replaced at the same time! Previously reported to Shropshire Council some 3 months previously - Updated on FMS 29.09.21- no action
11/08/2021		A525 E/B Carriageway opposite the entrance to Swan Farm Lane	500x500x120deep pothole in carriageway channel area.		This pothole has been repaired poorly previously, and has "plucked out" again. Constitutes a serious hazard for cyclists and cars. Previously reported to Shropshire Council twice in the previous 3 months, not action. It has been painted white around it! - Updated on FMS 29.09.21 - No Action
19/08/2021		A51 in the middle of S/B Lane	Linear pothole, road surface breaking up over approx. 10m length. Previously patched. Also breaking up around MH in carriageway channel.		Previously reported to Shropshire Council some 3 and 6 months previously. Some white paint on carriageway. Update on FMS 16.01.22 -This Pothole is now a significant danger, and is now 150mm deep and presents a significant hazard to the travelling public, and requires immediate attention. It is now over 9 months since this was first
19/08/2021		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway Update on FMS 07.03.21-This gully is on the verge of structural failure, the surround has been completely eroded, and the frame is clanking. It is compounded by the fact that the lane is now been trafficked as a single lane under traffic lights, because of Western Power's works, thus doubling the traffic as it used to be, and it will collapse and shut roads
19/08/2021		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Carriageway breaking up around gully causing pothole in channel Very Dangerous		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.
06/09/2021		Overgrown Hedge leading to Public Footpath 0236/23/1 at end of Northlands Woore	Hedge needs cutting back		New Report. Updated on FMS 04.10.21. No Action as at 06.11.21 reported on FMS.
30/09/2021		A51 Verge - Steps and Handrail Leading up to Public Footpath 0236/26/1	Steps and handrail in need of repair since the handrail has rotted and steps eroded.		No Action - Updated on FMS 29.10.21 as no action
30/09/2021		B5026 Bearstone Road entrance	Loose Public Footpath (0236/33/1) Sign, needs re-affixing to Stile.		No Action - Update posted on FMS 29.10.21 still no action
01/10/2021		Several Potholes on Dorrington Lane, Woore	Several potholes been here for months have to nearly go into stream to avoid. Between The white House and the westlands. Dorrington Lane near woore		New Report. Updated on FMS 29.10.21 - No Action
06/10/2021		A51 S/B carriageway opposite junction with Bearstone Road.	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.
06/10/2021		B5026 Bearstone Road S/B carriageway opposite Dorrington Lane Crossroads.	Double BT Manhole collapsing, roads surface eroded away from frame.		Been in that condition for over 6 weeks
07/10/2021		Eastern end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report No Action as at 06.11.21 reported on FMS
07/10/2021		Middle of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report No Action as at 06.11.21 reported on FMS
07/10/2021		Western end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding. This was previously repaired earlier this year, and has failed again.		New Report No Action as at 06.11.21 reported on FMS

07/10/2021	A525 Edge of E/B carriageway approx. 40m past junction with Beech Avenue	Edge of carriageway breaking up and has developed into a serious linear pothole approx 100x500x100 deep, adjacent to previous repair. Dangerous for cyclists and cars.		New Report No Action as at 06.11.21 reported on FMS 10.12.21 - The deficit as reported has been patched, although other adjacent areas remain unprepared.	
07/10/2021					
07/10/2021	Public Footpath 236/47/1 through Woore Church Yard	Deterioration of footpath through churchyard is a hazard for pedestrians and need repair. First reported. 10.04.21. Outdoor Recreation gave Ref. No. UM110821:90a81 Route No:0236/47/1		New Report First Reported to SC on 19.04.21	UM110821:90a81
07/10/2021	Public Footpath 0236/23/21 at the entrance from Northlands	Footpath has deteriorated at the entrance to Northlands and is presenting a trip hazard. Outdoor recreation advised the following ref. No. UM110821:1a5c7 Route No: 0236/23/1		New Report First Reported to SC on 11.08.21	UM110821:1a5c7
19/10/2021	Intersection of Public Footpaths 0236/22/1 and 236/23/1 on Eastern Boundary of Fields behind Northlands.	Post requires replacement of Field gate on Footpath 0236/23/1		New Report	
21/10/2021	B5025 Dorrington Lane and Watery Lane Crossroads	At Dorrington lane end where the 5026 leads to Irelands Cross, the constant flooding has still not been addressed and this morning, where most other flood prone sites are clear of water, this junction has a pool 2/3rds of the way across the B Road and round the corner adjacent. Our understanding is that this constantly floods due to the water running down Dorrington Lane out of the ditch and down onto the B5026. The drains are silted up and can't cope with all the water.		New Report - First reported to SC several months ago.	SR-174964-T9K7D9
21/10/2021	Severe Flooding on Bearstone Road	Bearstone Road flooding – issue is broken pipes – SC have visited site and instructed SC drainage works team to perform repairs – 3 month notice required for road closure - awaiting update.		New Report - First reported to SC several months ago. Update 10.12.21 - Shropshire Council advised that their contractor has attended site to deal with this, but couldn't do anything because of the flooding! They are to write again to adjacent landowners ref Ditch cleaning.	
21/10/2021	A525/A51 Junction, Audlem Side.	Badly deteriorated road surface, and erased stop line. Vehicles are encroaching into the A51 carriageway to gain visibility around parked cars in lay-by. The absence of the stop line is very dangerous since there is no guide to the driver to stop. Eroded road surface is danger for vehicles under heavy braking with flooded potholes and the risk of ice forming with the onset on winter.		New Report	
21/10/2021	Blocked foot way gully on A525 adjacent to Woore Post Office	Drainage gully at the back of the footpath is blocked, and or possibly the outfall drain. Water is discharging across the footpath, and is causing a dangerous surface for pedestrians. This will be exacerbated by the onset of frosty weather causing ice formation with the associated hazards.		New Report - SC attended site on 12.11.21 and attempted to clear the blockage in the outfall drain. The operatives reported to Andy Morris in Woore Country Stores, they thought that the drain was collapsed as a result of excavation work carried out by ST to install a new water meter, since there is new surfacing over the area of the drain. They have referred the matter back to the SC Drainage engineers for resolution.	SR-175797-P3B4L6
12/11/2021	Street Lamp out on Westbound side of the A525 adjacent to Buckley Hall.	Street Lamp requires replacement		New Report - Update 16.12.21 Reported on FMS The street lamp has still not been repaired by Shropshire Council . Further update on 16.01.2022 on FMS - still not repaired by SC.	
16/01/2022	Pothole at the entrance to Grove Crescent	This pothole started off as a minor hole and has now developed over the past month into significant pothole some 300x300 and 100deep. It is a danger to Both vehicular traffic and a trip hazard for the many pedestrian using this crossing point.		New Report	