

Elite Playground Inspections

Customer Name: Cerne Valley PC	Site Name: Cerne Abbas Play Area	Site No: 1	Inspected By: <i>SPC</i>	Date: 02/06/2021
---------------------------------------	---	-------------------	---------------------------------	-------------------------

Main play area surface: Grass	Type of Fencing: Chainlink/Post/Rail	No of Gates: 3	Self Closing: 0	Non Self Closing: 3
--------------------------------------	---	-----------------------	------------------------	----------------------------

Manufacturer	Year	Description	OK	WP	Surfacing	OK	WP	Comments
N/K Hags?	N/K	2 Bay Basket Seat & 1 Cradle & 1 Flat Seat Swing	√	2	Rubber Mulch	√		The swing barrier in front of the swing has a loose/rotten post
N/K	N/K	5 Tower Multi Play Unit	√	2 3	Rubber Mulch	√		Slight rot in virtually all timber slats – consider replacing all timber Chains worn to 50%+ on hanging tyre climber – replace chains etc
Kompan	N/K	Crazy Nellie Springer	√		Rubber Mulch	√		
Kompan	N/K	Ziggy Springer	√		Rubber Mulch	√		
Fencing	N/K		√					
Gates	N/K	3 (1 x vehicle Gate)	√	3		√		Gates do not self-close, they should and be closing between 4-8 seconds – fit closers to gates
N/K	N/K	Benches	√			√		
	2021	Picnic Table	√					
Swintex	N/K	Litter Bin	√	3		√		Not locked – keep locked
<u>Outside Area</u>			√			√		
N/K	N/K	Ball Court	√		Tarmac	√		
N/K	N/K	Tyre Agility Course	√		Grass	√		

Work Priority Guide			
1	Very Low	3	Medium
2	Low	4	High

Performance Indicator	
Operative	Inoperative
7/7	

Maintenance Work Carried Out / General Observations: Vehicle gate to road has a missing top rail & now another broken off bar