

# Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

## Inspections included in this report

<b>Actual Date</b>	30/09/2025 12:53:59	 30/09/2025
<b>Inspection Status</b>	Completed	
<b>Inspection Type</b>	Playground-Annual	
<b>Inspector</b>	Rachel Adams	
<b>Provider</b>	Parish Councils	
<b>Site Name</b>	Baldersby Play Area	

## Inspection - Baldersby Play Area - 30/09/2025 12:53:59

<b>Actual Date</b>	30/09/2025 12:53:59		
<b>Inspection Status</b>	Completed		
<b>Inspection Type</b>	Playground-Annual		
<b>Inspector</b>	Rachel Adams		
<b>Provider</b>	Parish Councils		30/09/2025
<b>Site Name</b>	Baldersby Play Area		

<b>Address</b>	
<b>Notes</b>	
<b>Postcode</b>	
<b>Site Name</b>	Baldersby Play Area

**Baldersby Play Area Inspected Asset List - Asset List is representative of other inspections listed for this Site (see Inspection Notes for exceptions)**

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Agility - balance trail	
<b>Asset Sub Type</b>	Trim Trail - Multi-linked Items	
<b>Asset Type</b>	Agility	
<b>Manufacturer</b>		

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Agility - Tyre Walk	
<b>Asset Sub Type</b>	Tyre Walk	
<b>Asset Type</b>	Agility	
<b>Manufacturer</b>		

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Carousel - Bowl	
<b>Asset Sub Type</b>	Type F2 Bowl (Multi User)	
<b>Asset Type</b>	Carousel	
<b>Manufacturer</b>		
		26/03/2025

<b>Asset Category</b>	Surface	
<b>Asset Name</b>	General Surface - Grass	
<b>Asset Sub Type</b>	Grass	
<b>Asset Type</b>	General Surface	
<b>Manufacturer</b>		
		19/10/2022

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Multiplay - Castle	
<b>Asset Sub Type</b>	Multiplay Unit - Junior	
<b>Asset Type</b>	Multiplay	
<b>Manufacturer</b>		
		30/09/2025

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Multiplay - Junior - Slide Climber	
<b>Asset Sub Type</b>	Slide Climber	
<b>Asset Type</b>	Multiplay	
<b>Manufacturer</b>		
		26/03/2025

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Rocker - Frog	
<b>Asset Sub Type</b>	Type 2A - Single Point - Unidirectional	
<b>Asset Type</b>	Rocker	
<b>Manufacturer</b>		
		26/03/2025

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Rocker - Stand-On	
<b>Asset Sub Type</b>	Type 1 - Axial Seesaw	
<b>Asset Type</b>	Rocker	
<b>Manufacturer</b>		
		26/03/2025

<b>Asset Category</b>	Facilities	
<b>Asset Name</b>	Seating - Picnic Table	
<b>Asset Sub Type</b>	Picnic Table	
<b>Asset Type</b>	Seating	
<b>Manufacturer</b>		
		26/03/2025

<b>Asset Category</b>	Equipment (Outdoor Play)	
<b>Asset Name</b>	Swing - Mixed - 1 Bay 1 Junior 1 Toddler Seat	
<b>Asset Sub Type</b>	Type 1 - Traditional (Mixed Seats)	
<b>Asset Type</b>	Swing	
<b>Manufacturer</b>		
		26/03/2025

## Findings reported within the Inspection

**None Recorded.**

## Previously Reported Findings Marked Complete During Inspection

### Seating - Picnic Table - Finding

<b>Asset</b>	Seating - Picnic Table	
<b>Cause</b>		
<b>Finding Date</b>	26/03/2025 11:46:49	
<b>Finding Group</b>	Maintenance	
<b>Finding Notes</b>	Caused by strimmer damage	
<b>Finding Title</b>	Timber - Decay	
<b>Location</b>		
<b>Risk Level</b>	Low	
<p>Finding Photos</p>  <p>26/03/2025</p>		