

Subject: Play Area

Date: Tuesday, 15 December 2020 at 16:38:40 Greenwich Mean Time

From: Steve Aplin

To: Parish Clerk

Hi Elizabeth

I have looked through the report and there isn't that much to worry about. The main job is to strip down the cable way and fully inspect the parts, reassemble and retention the cable, this is a two man job. I've listed the jobs we would carry out, but priced it as a lump sum, which is more realistic, I hope you find this acceptable.

Bradenstoke – Strip down the Cableway, check for wear, reassemble and tension the Cable. Supply and fit a new Chain Sleeve.

Fit rubber stop to the wooden Pedestrian gate to remove the crush point on the hanging post.

Replace the missing Sign fitting.

Rub down and treat the small areas of corrosion on the Toddler and Junior MultiPlay.

Pound Piece – Fit rubber stop to the wooden Pedestrian gate to remove the crush point on the hanging post.

Replace the missing joiner to the Assess net on the Junior Multi Play.

Secure the Anti Climb strips on the crossbars of both swing units.

Total Cost

£683.00 +vat

Kind regards

Steve Aplin

Director

S J Aplin Playgrounds Ltd

Tel: 01249812556

Mob: 07850973847



Virus-free. www.avg.com