

WEST TYTHERLEY, FRENCHMOOR & BUCKHOLT PARISH COUNCIL

RISK ASSESSMENT: BUS SHELTER

What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to control this risk?	Action by who?	Action by when?
Slips and Trips	Risk of injury to pedestrians if they trip over objects or slip on debris	General good housekeeping is carried out and bus shelter maintained	Bus shelter to be monitored for build-up of debris on floor Lengthsman Scheme in place with HCC	Cllr Koetser	At least quarterly
Hazardous building caused by:- - Deterioration through age - Vandalism - Storm damage - Collision by motor vehicle	Risk of injury to pedestrians, vandals, drivers/their passengers Building collapse and/or through impact	Visual inspection to determine wooden shelter and felted roof are in good repair – both internal and external.	Bus shelter to be monitored and visually inspected. Allocation in Budget towards 'Village Maintenance' to carry out repairs Adequately insured	Cllr Koetser Clerk/RFO Clerk/RFO	At least quarterly Immediately after a storm, report of vandalism, report of collision by motor vehicle
Potential for vehicle on pedestrian collision	Risk of injury to pedestrians viewing approaching traffic whilst waiting for a bus	No risk of restrictive view as no trees or vegetation in location	N/A		