

This document was exported from Numbers. Each table was converted to an Excel worksheet. All other objects

Numbers Sheet Name	Numbers Table Name	Excel Worksheet Name
Sheet 1 - Woore Parish Council	Table 1	Sheet 1 - Woore Parish Council
Sheet 1 - Woore Parish Council	Table 1	Sheet 1 - Woore Parish Council
Completed	Table 1	Completed

Woore Parish Council Fix My Street Log (Update 22.04.22)						
Date Reported	Status	Location	Description	Date Fixed	Notes	Shropshire Council Ref.
11/08/2021		A525 W/B carriageway, opposite the Property known as "The Brambles"	Rocking manhole cover, in danger of collapse.Severn Trent		This cover has previously had the blacktop surrounding it replaced, however the cover was not replaced at the same time!Previously reported to Shropshire Council some 3 months previously.- Updated on FMS 29.09.21 - no action	
11/08/2021		A525 E/B Carriageway opposite the entrance to Swan Farm Lane	500x500x120deep pothole in carriageway channel area.		This pothole has been repaired poorly previously, and has "plucked out" again. Constitutes a serious hazard for cyclists and cars . Previously reported to Shropshire Council twice in the previous 3 months, not action. It has been painted white around it! - Updated on FMS 29.09.21 - No Action	
19/08/2021		A51 in the middle of S/B Lane	Linear pothole, road surface breaking up over approx. 10m length. Previously patched. Also breaking up around MH in carriageway channel.		Previously reported to Shropshire Council some 3 and 6 months previously. Some white paint on carriageway. Update on FMS 16.01.22 -This Pothole is now a significant danger, and is now 150mm deep and presents a significant hazard to the travelling public, and requires immediate attention. It is now over 9 months since this was first reported.	
19/08/2021		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway Update on FMS 07.03.21-This gully is on the verge of structural failure, the surround has been completely eroded, and the frame is clanking. It is compounded by the fact that the lane is now been trafficked as a single lane under traffic lights, because of Western Power's works, thus doubling the traffic on it, and it will collapse any day! requires immediate attention.	
19/08/2021		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Carriageway breaking up around gulley causing pothole in channel Very Dangerous		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
06/09/2021		Overgrown Hedge leading to Public Footpath 0236/23/1 at end of Northlands Woore	Hedge needs cutting back		New Report. Updated on FMS 04.10.21. No Action as at 06.11.21 reported on FMS.	
30/09/2021		A51 Verge - Steps and Handrail Leading up to Public Footpath 0236/26/1	Steps and handrail in need of repair since the handrail has rotted and steps eroded.		No Action - Updated on FMS 29.10.21 as no action	
30/09/2021		B5026 Bearstone Road entrance	Loose Public Footpath (0236/33/1) Sign, needs re-affixing to Stile.		No Action - Update posted on FMS 29.10.21 still no action	
29/10/2021		Several Potholes on Dorrington Lane, Woore	Several potholes been here for months have to nearly go into stream to avoid. Between The white House and the westlands. Dorrington Lane near woore		New Report. Updated on FMS 29.10.21 - No Action	
06/10/2021		A51 S/B carriageway opposite junction with Bearstone Road.	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
07/10/2021		Eastern end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report No Action as at 06.11.21 reported on FMS	
07/10/2021		Middle of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.		New Report No Action as at 06.11.21 reported on FMS	
07/10/2021		Western end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding. This was previously repaired earlier this year, and has failed again.		New Report No Action as at 06.11.21 reported on FMS Update 06.04.22 This Manhole is now collapsing and requires rebuilding, this is blocking the sewerage flow and causing it to back up the Manhole that is opposite Moat Lane. This is a Public Health hazard. ST attended on 06.04.22, and carried out a temporary repair to the manhole, but confirmed they would need a road closure to effect the permanent repairs to the collapsing manhole. Update 05.04.22. United Utilities accrued out camera survey and confirmed blockages, probably as. result of the damaged manhole, which was causing upstream flooding on candle lane. Obstruction removed. Update 07.04.22 There was a blockage in the sewer down stream from the blocked manhole which resulted in serious flooding of the A525 carriageway and adjacent properties. United Utilities attending and cleared the blockage, which was probably caused by debris from the collapsing manhole in Candle Lane. The manhole will have to be rebuilt, but the process is being delayed waiting for Shropshire Council Highways to approve the road closure to carry our the work.	
07/10/2021		A525 Edge of E/B carriageway approx. 40m past junction with Beech Avenue	Edge of carriageway breaking up and has developed into a serious linear pothole approx 100x500x100 deep, adjacent to previous repair. Dangerous for cyclists and cars.		New Report No Action as at 06.11.21 reported on FMS 10.12.21 - The deficit as reported has been patched, although other adjacent areas remain unprepared.	

07/10/2021		Public Footpath 236/47/1 through Woore Church Yard	Deterioration of footpath through churchyard is a hazard for pedestrians and need repair. First reported. 10.04.21. Outdoor Recreation gave Ref. No. UM110821:90a81 Route No:0236/47/1		New Report First Reported to SC on 19.04.21	UM110821:90a81
07/10/2021		Public Footpath 0236/23/21 at the entrance from Northlands	Footpath has deteriorated at the entrance to Northlands and is presenting a trip hazard. Outdoor recreation advised the following ref. No. UM110821:1a5c7 Route No: 0236/23/1		New Report First Reported to SC on 11.08.21	UM110821:1a5c7
19/10/2021		Intersection of Public Footpaths 0236/22/1 and 236/23/1 on Eastern Boundary of Fields behind Northlands.	Post requires replacement of Field gate on Footpath 0236/23/1		New Report	
21/10/2021		B5025 Dorrington Lane and Watery Lane Crossroads	At Dorrington lane end where the 5026 leads to Irelands Cross, the constant flooding has still not been addressed and this morning, where most other flood prone sites are clear of water, this junction has a pool 2/3rds of the way across the B Road and round the corner adjacent. Our understanding is that this constantly floods due to the water running down Dorrington Lane out of the ditch and down onto the B5026. The drains are silted up and can't cope with all the water.		New Report - First reported to SC several months ago.	SR-174964-T9K7D9
21/10/2021		Severe Flooding on Bearstone Road	Bearstone Road flooding – issue is broken pipes – SC have visited site and instructed SC drainage works team to perform repairs – 3 month notice required for road closure - awaiting update.		New Report - First reported to SC several months ago. Update 10.12.21 - Shropshire Council advised that their contractor has attended site to deal with this, but couldn't do anything because of the flooding! They are to write again to adjacent landowners ref Ditch cleaning.	
21/10/2021		A525/A51 Junction, Audlem Side.	Badly deteriorated road surface, and erased stop line. Vehicles are encroaching into the A51 carriageway to gain visibility around parked cars in lay-by. The absence of the stop line is very dangerous since there is no guide to the driver to stop. Eroded road surface is danger for vehicles under heavy braking with flooded potholes and the risk of ice forming with the onset on winter.		New Report	
21/10/2021		Blocked foot way gully on A525 adjacent to Woore Post Office	Drainage gully at the back of the footpath is blocked, and or possibly the outfall drain. Water is discharging across the footpath, and is causing a dangerous surface for pedestrians. This will be exacerbated by the onset of frosty weather causing ice formation with the associated hazards.		New Report - SC attended site on 12.11.21 and attempted to clear the blockage in the outfall drain. The operatives reported to Andy Morris in Woore Country Stores, they thought that the drain was collapsed as a result of excavation work carried out by ST to install a new meter, since there is new surfacing over the area of the drain. The drain is now blocked and the SC Drainage team are to investigate further.	SR-175797-P3B4L6
11/12/2021		Pothole at the entrance to Grove Crescent	This pothole started off as a minor hole and has now developed over the past month into significant pothole some 500x500 and 100deep. It is a danger to Both vehicular traffic and a trip hazard for the many pedestrian using this crossing point.		New Report No Action as at 22.04.22 reported on FMS	
19/03/2022		Footpath Post opposite Bankfoot in Gravenhunger Lane Woore	Post is rooted and snapped off, requires replacement, lying against the hedge.		New Report on FMS 19.03.22	
25/03/2022		Rocking Gully Grid on the A51 Opposite Phenix Rise Pipe Gate.	Gully grating is loose as road surface has collapsed around it. Dangerous to all passing traffic, danger of collapse.		New Report on FMS 25.03.22	
06/04/2022		Gateway and signage Gravenhunger Lane Woore	These signs are looking dilapidated, and overgrown. It needs the vegetation and bushes cutting back, and the signage refurbishing or replacing. This is a very well used pedestrian route, and the signage is there to warn motorists of the speed limit and presence of pedestrians. It was installed by SC as part of the quiet lanes initiative.		New Report on FMS 06.04.22	

Date Reported	Status	Location	Description
11/10/2019		Junction of Candle Lane and the A51 Nantwich Road - Blocked Culvert causing Flooding	This Issue was first reported to Shropshire Council 11.10.19 - On Candle Lane at the end nearest to the A51 Nantwich Road the culvert is overflowing with water, due possibly to the drain than runs under the road blocked which would allow the water to run into the field. There is also concern of two vehicles passing on this lane that due to the culvert obscured by tall grass that a vehicle may end up in the culvert.....does this require some signage?
3/8/20		Junction of A51 and A5026	Direction sign severely damaged by a collision with an HGV
8/3/21		A51 at junction of Candle Lane, S/B side verge	30mph sign is obscured by overgrown by vegetation
11/08/2021		Bellmouth to entrance to Ash Mount off A525	Multiple Severn Trent Covers (4) have large potholed areas around them, total area is 1.2 sum eroded to a depth of 30-40mm. Serious trip hazard, as it hit is in the line of the pedestrian crossing of the junction.
11/08/2021		A525 on E/B Footpath adjacent to "The Meads"	Double BT Manhole Cover in footway, Covers are not seated properly after removal maintenance, and presents a trip hazard. There is a 15mm up-stand
19/08/2021		A51 N/B opposite entrance to Betty's lane	Previously repaired Manhole surround, (2020), breaking up in carriageway with a significant pothole developing. Severn Trent
19/08/2021		A525 W/B carriageway opposite Red Lion Farm	Rocking manhole cover, in danger of collapse. Severn Trent
19/08/2021		A525 W/B carriageway opposite Property known as "Resthaven" the entrance with a 5 bar gate.	Rocking manhole cover, in danger of collapse. Severn Trent
19/08/2021		A51 London Road S/B carriageway. Approx. 100 m South of entrance to property known as Warren Heights	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.
06/09/2021		A525 W/B verge opposite TT Pumps Premises	Collapsed gullies in the verge, very dangerous
06/10/2021		B5026 Bearstone Road S/B carriageway opposite Dorrington Lane Crossroads.	Double BT Manhole collapsing, roads surface eroded away from frame.
26/10/2021		Inspection cover On Lamppost Ref: 8146-2 lying on pavement, electrics exposed On Audlem Road	Lamppost Inspection cover lying on the pavement with exposed electrics on the Eastbound pavement of A525 Audlem Road in Woore Village. This is a danger to the public, and requires Immediate attention.
28/10/2021		Streetlight - very bright light shining onto property	The streetlight outside the property referenced below has had the bulb/head replaced fairly recently and since then, the light is significantly brighter than the others and is also now shining directly onto the property opposite (Elmhurst Lay, Woore, CW3 9RQ). The light seems brighter than an average streetlight bulb. It is causing an issue for the residents of that property. Please can it be addressed.

12/11/2021		Street Lamp out on Westbound side of the A525 adjacent to Buckley Hall.	Street Lamp requires replacement
10.07.21		A525 Edge of W/B carriageway approx. 35 past junction with Beech Avenue	Surround to double BT manhole cover breaking up, causing a pothole that is deteriorating. This is a previously repaired manhole.
16/03/2022		Street. Lamp No 38 on the A51 at Crossways	Street Lamp is continuously illuminated
16/03/2022		30 mph sign in verge on approach to Woore Village from Audlem	Sign post is snapped off and laying in the verge.

Date Fixed	Notes
06.04.22	Update 16.12.21 Reported on FMS - The PC are not aware of any jetting taking place, also at the time of Reporting the Highways Technician advised installing bollards to inform road users. Since 2019 there have been two white vans gone into the culvert that I know of, noticed again yesterday that the road is flooding again! Update 06.04.22 SC updated FMS to say the issue had been fixed.
10/28/21	This sign has been in a damaged state for 2 years, aspire repeated requested requests to Shropshire Council to repair it. Fixed on 19/03/22 some years after being reported !!!!
10/28/21	Update 01.09.21 reported on FMS - No Action by SC. Problem cleared by annual hedge cutting FMS updated.
10/28/21	Previously reported to Shropshire Council some 3 months previously - Repaired 28.02.21 full patch
28.02.22	This was originally reported on the Shropshire Council Portal some months previously. Still no action at 06.10.21! Cover marked in white paint with S81.- Updated on FMS 29.10.21 - No Action-Fixed 28.02.22 by BT Emergency Crew!
10/17/21	Repaired by ST on 17.10.21
9/30/21	Previously reported 3 months previous to Shropshire County Council. Now fixed.
9/30/21	Previously reported 3 months previous to Shropshire County Council. Repaired by ST 17.10.21
10/17/21	Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway. Repaired by ST 17.10.21
9/30/21	Temporary cones placed after 5 days, repairs now carried out.
	Been in that condition for over 6 weeks
10/28/21	New Report - Repaired
06.11.21	New Report. The Lamp has been replaced with an LED Unit that does not sit within a cover. All SC Lamps are being replaced with LED Units as they fail. Issue to be taken up with SC by the Resident direct, since it is policy issue.

17.03.22	Repaired by SC, head and lamp replaced with LED unit.
04.03.22	Repaired on 04.03.22, surfacing was dressed into soil on the verge side, so will probably fail soon again!
	New Report - Reported by resident on Shropshire portal. Now reported on FMS 25.03.22. - 31.03.22 Lamp appears to be working normally now.
04.04.21	New Report Update 04.04.21 - Sign pole replaced and signs re-erected on pole by Shropshire Council

Shropshire Council Ref.				
New Report - Update 16.12.21 Reported on FMS The street lamp has still not been repaired by Shropshire Council . Further update on 16.01.2022 on FMS - still not repaired by				
Fixed on 23.10.22 by BT, FMS Updated				
SR-175453-Z1W3V4				
SR175833-B5S4P9				

New Report - Update 16.12.21 Reported on FMS The street lamp has still not been repaired by Shropshire Council . Further update on 16.01.2022 on FMS - still not repaired by SC. 17.03.22 - Repaired FMS updated.				
New Report No Action as at 06.11.21 reported on FMS				

