

Woore Parish Council Fix My Street Log (Update 06.11.21)

	Status	Location	Description	Date Reported	Date Fixed	Notes	Shropshire Council Ref.
1		A51 at junction of Candle Lane, S/B side verge	30mph sign is obscured by overgrown by vegetation	03/08/2021		No Action	
3		A525 on E/B Footpath adjacent to "The Meadows"	Double BT Manhole Cover in footway, Covers are not seated properly after removal maintenance, and presents a trip hazard. There is a 15mm up-stand	11/08/2021		This was originally reported on the Shropshire Council Portal some months previously. Still no action at 06.10.21! Cover marked in white paint with S81.- Updated on FMS 29.10.21 - No Action	
4		Bellmouth to entrance to Ash Mount off A525	Multiple Severn Trent Covers (4) have large potholed areas around them, total area is 1.2 sum eroded to a depth of 30-40mm. Serious trip hazard, as it hit is in the line of the pedestrian crossing of the junction.	11/08/2021	28/10/2021	Previously reported to Shropshire Council some 3 months previously - Repaired 28.02.21 full patch	
5		A525 W/B carriageway, opposite the Property known as "The Brambles"	Rocking manhole cover, in danger of collapse. Severn Trent	11/08/2021		This cover has previously had the blacktop surrounding it replaced, however the cover was not replaced at the same time! Previously reported to Shropshire Council some 3 months previously.- Updated on FMS 29.09.21- no action	
6		A525 E/B Carriageway opposite the entrance to Swan Farm Lane	500x500x120 deep pothole in carriageway channel area.	11/08/2021		This pothole has been repaired poorly previously, and has "plucked out" again. Constitutes a serious hazard for cyclists and cars . Previously reported to Shropshire Council twice in the previous 3 months, not action. It has been painted white around it! - Updated on FMS 29.09.21 - No Action	
7		A51 N/B opposite entrance to Betty's lane	Previously repaired Manhole surround, (2020), breaking up in carriageway with a significant pothole developing. Severn Trent	19/08/2021	17/10/2021	Repaired by ST on 17.10.21	
8		A525 W/B carriageway opposite Red Lion Farm	Rocking manhole cover, in danger of collapse. Severn Trent	19/08/2021	30/09/2021	Previously reported 3 months previous to Shropshire County Council. Now fixed.	
10		A51 in the middle of S/B Lane	Linear pothole, road surface breaking up over approx. 10m length. Previously patched. Also breaking up around MH in carriageway channel.	19/08/2021		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
12		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.	19/08/2021		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
13		A51 London Road S/B carriageway. Opposite entrance to property known as Farcross	Carriageway breaking up around gulley causing pothole in channel Very Dangerous	19/08/2021		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
9		A525 W/B carriageway opposite Property known as "Resthaven" the entrance with a 5 bar gate.	Rocking manhole cover, in danger of collapse. Severn Trent	19/08/2021	30/09/2021	Previously reported 3 months previous to Shropshire County Council. Repaired by ST 17.10.21	
11		A51 London Road S/B carriageway. Approx. 100 m South of entrance to property known as Warren Heights	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.	19/08/2021	17/10/2021	Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway. Repaired by ST 17.10.21	

2	A525 W/B verge opposite TT Pumps Premises	Collapsed gullies in the verge, very dangerous	06/09/2021	30/09/2021	Temporary cones placed after 5 days, repairs now carried out.	
32	Overgrown Hedge leading to Public Footpath 0236/23/1 at end of Northlands Woore	Hedge needs cutting back	06/09/2021		New Report. Updated on FMS 04.10.21. No Action as at 06.11.21 reported on FMS	
14	A51 Verge - Steps and Handrail Leading up to Public Footpath 0236/26/1	Steps and handrail in need of repair since the handrail has rotted and steps eroded.	30/09/2021		No Action - Updated on FMS 29.10.21 as no action	
17	B5026 Bearstone Road entrance	Loose Public Footpath (0236/33/1) Sign, needs re-affixing to Stile.	30/09/2021		No Action - Update posted on FMS 29.10.21 still no action	
33	Several Potholes on Dorrington Lane, Woore	Several potholes been here for months have to nearly go into stream to avoid. Between The white House and the westlands. Dorrington Lane near woore	01/10/2021		New Report. Updated on FMS 29.10.21 - No Action	
15	A51 S/B carriageway opposite junction with Bearstone Road.	Rocking manhole cover, in danger of collapse. Severn Trent. Very Dangerous.	06/10/2021		Previously reported to Shropshire Council some 3 and six months previously. Some white paint on carriageway.	
16	B5026 Bearstone Road S/B carriageway opposite Dorrington Lane Crossroads.	Double BT Manhole collapsing, roads surface eroded away from frame.	06/10/2021		Been in that condition for over 6 weeks	
18	Eastern end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.	07/10/2021		New Report No Action as at 06.11.21 reported on FMS	
19	Middle of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding.	07/10/2021		New Report No Action as at 06.11.21 reported on FMS	
20	Western end of Candle Lane	Subsiding Severn Trent manhole cover, surround is breaking up and cover is subsiding. This was previously repaired earlier this year, and has failed again.	07/10/2021		New Report No Action as at 06.11.21 reported on FMS	
21	A525 Edge of E/B carriageway approx. 40m past junction with Beech Avenue	Edge of carriageway breaking up and has developed into a serious linear pothole approx 100x500x100 deep, adjacent to previous repair. Dangerous for cyclists and cars.	07/10/2021		New Report No Action as at 06.11.21 reported on FMS	
22	A525 Edge of W/B carriageway approx. 35 past junction with Beech Avenue	Surround to double BT manhole cover breaking up, causing a pothole that is deteriorating. This is a previously repaired manhole.	07/10/2021		New Report No Action as at 06.11.21 reported on FMS	
23	Public Footpath 236/47/1 through Woore Church Yard	Deterioration of footpath through churchyard is a hazard for pedestrians and need repair. First reported. 10.04.21. Outdoor Recreation gave Ref. No. UM110821:90a81	07/10/2021		New Report	

	24	Public Footpath 0236/23/21 at the entrance from Northlands	Footpath has deteriorated at the entrance to Northlands and is presenting a trip hazard. Outdoor recreation advised the following ref. No. UM110821:1a5c7	07/10/2021		New Report	
	25	Intersection of Public Footpaths 0236/22/1 and 236/23/1 on Eastern Boundary of Fields behind Northlands.	Post requires replacement of Field gate on Footpath 0236/23/1	19/10/2021		New Report	
	26	B5025 Dorrington Lane and Watery Lane Crossroads	At Dorrington lane end where the 5026 leads to Irelands Cross, the constant flooding has still not been addressed and this morning, where most other flood prone sites are clear of water, this junction has a pool 2/3rds of the way across the B Road and round the corner adjacent. Our understanding is that this constantly floods due to the water running down Dorrington Lane out of the ditch and down onto the B5026. The drains are silted up and can't cope with all the water.	21/10/2021		New Report - First reported to SC several months ago.	SR-174964-T9K7D9
	27	Severe Flooding on Bearstone Road	Bearstone Road flooding – issue is broken pipes – SC have visited site and instructed SC drainage works team to perform repairs – 3 month notice required for road closure - awaiting update.	21/10/2021		New Report - First reported to SC several months ago.	
	28	A525/A51 Junction, Audlem Side.	Badly deteriorated road surface, and erased stop line. Vehicles are encroaching into the A51 carriageway to gain visibility around parked cars in lay-by. The absence of the sop line is very dangerous since there is no guide to the driver to stop. Eroded road surface is danger for vehicles under heavy braking with flooded potholes and the risk of ice forming with the onset on winter.	21/10/2021		New Report	
	30	Blocked foot way gully on A525 adjacent to Woore Post Office	Drainage gully at the back of the footpath is blocked, and or possibly the outfall drain. Water is discharging across the footpath, and is causing a dangerous surface for pedestrians. This will be exacerbated by the onset of frosty weather causing ice formation with the associated hazards.	21/10/2021		New Report	SR-175797-P3B4L6
	29	Inspection cover On Lamppost Ref:8146-2 lying on pavement, electrics exposed On Audlem Road	Lamppost Inspection cover lying on the pavement with exposed electrics on the Eastbound pavement of A525 Audlem Road in Woore Village. This is a danger to the public, and requires Immediate attention.	26/10/2021		New Report	SR-175453-Z1W3V4
	31	Streetlight - very bright light shining onto property	The streetlight outside the property referenced below has had the bulb/head replaced fairly recently and since then, the light it significantly brighter than the others and is also now shining directly onto the property opposite (Elmhurst Lay, Woore, CW3 9RQ). The light seems brighter than an average streetlight bulb. It is causing an issue for the residents of that property. Please can it be addressed.	28/10/2021	06.11.21	New Report. The Lamp has been replaced with an LED Unit that does not sit within a cover. All SC Lamps are being replaced with LED Units as they fail. Issue to be taken up with SC by the Resident direct, since it is policy issue.	SR175833-B5S4P9

--	--	--	--	--	--	--