

RE: Virgins Croft Plot 3A

Jane de Garston <asstclerk@battletowncouncil.gov.uk>

Fri 23/10/2020 12:12

To:

Cc:

Dear S

Thank you for your email.

The access path suffers from erosion which is difficult to repair.

I have asked the grounds staff to look at the path when they are completing the winter maintenance at the site to see if anything can be done. We will also submit a report to the Environment Committee of your concerns.

Kind regards

Jane de Garston

Assistant to Town Clerk

Battle Town Council

You have received this email from Battle Town Council. The content of this email is confidential may be legally privileged and intended for the recipient specified in message only. It is strictly forbidden to share any part of this message with any third party, without a written consent of the sender. If you received this message by mistake, please reply to this message and follow with its deletion. Battle Town Council ensures that email security is a high priority. We have put efforts into ensuring that the message is error and virus free. Unfortunately, full security of the email cannot be ensured as, despite our efforts, the data included in emails could be infected, intercepted or corrupted. Therefore, the recipient should check the email for threats with proper software, as the sender does not accept liability for any damage inflicted by viewing the content of this email.

-----Original Message-----

From:

Sent: 07 October 2020 12:39

To: Enquiries <enquiries@battletowncouncil.gov.uk>

Subject: Virgins Croft Plot 3A

Virgins Croft Allotment plot 3A

Hi

I've noticed over the past few years that the border of the allotment access path, on the left as one walks down to the plots from Virgins Lane, has become dangerously subsided. This is particularly bad from the first plot on the right, (Plot 1 I believe) and continues down past our plot 3A.

There are also wide gaps towards the stream that runs parallel to the path, wide enough for someone to slip down into.

I am very concerned that the combination of subsidence and the gaps could cause a serious accident. The path also narrows considerably near our plot, adding to the hazard.

Kind regards

S G