



Pavement ends

Restricted width to road due to large hedge. Convention is that vehicles coming out of Cheriton give way to those coming in. Not always observed by unfamiliar road users

Generally no pavement in this section of the village (other than where marked). Pedestrians feel vulnerable when walking into the village.

Pavement begins

Pedestrians vulnerable on this bend

Dangerous crossroads. Speed limit 30 but regularly exceeded. Poor sight lines to right when coming out of New Cheriton.