

# community flood plan

Parishes and communities working together

#### **Contents**

1. Flood roles & contacts

1A- Roles & contact

1B- Flood volunteers

2. Flood zones

2A - Winterborne St Martin CP flood zone map

2B - South Winterborne detailed flood management maps

3. Actions to be taken before a flood

3A - Issues to consider for resolution before a flood

2B - Locations at higher risk of flooding

4. Actions to be taken during a flood

A - Local flood volunteer actions

Community	Willebonie St Martin Fansh Council					
Address		clerk@winterbornestmartin-pc.gov.uk 07359 243559				
Plan history		10 December 2019 27 Jan 2020 minor revision November 2020 no revision necessary November 2021 revision postponed until diversion flood risk resolved 27 Jan 2021 minor revisions 26 Feb 2023 Update of Council personnel				

Winterhorne St Martin Parish Council

Local flood alert trigger: High water (clearance less than 150mm):

- under bridge east of Parish Office
- under bridge at allotment/small holding west of Brewers Arms

**EA flood alert registration:** South Winterborne ground water, measured at Kingston Russell borehole.

The purpose of this plan is to:

Community

- 1. document the watercourse risk in residential areas;
- 2. identify actions and sources of assistance in the event of a flood, and
- 3. maintain a free and unimpeded watercourse with due regard for the environment.

It's intended audience is primarily the Parish Council, riparian owners and flood volunteers. It is a dynamic document that is updated annually prior to the November meeting of the Parish Council.

# 1A – Roles and Contacts during a flood: Important telephone numbers

Organisation	Telephone (office hours)	Telephone (out of hours)	Role, website etc		
Floodline	0345 988 1188	0345 9881188	https://www.gov.uk/government/publications/flooding-from-groundwater		
			https://www.gov.uk/prepare-for-flooding		
			https://www.gov.uk/sign-up-for-flood-warnings		
Environment Agency	Local Blandford office 0370 8506506	0800 807060	Issues groundwater information and flood alerts. Receives and records details of all flooding incidents, monitors the situation and advises other organisations, responds to pollution incider advises householders on protection measures. Licenses alterations to main river banks and advises on current legislation regarding river management. Visit the EA website for flood information, guidance & warnings in local areas but DC are responsible for managing flood riswww.environment-agency.gov.uk  https://flood-warning-information.service.gov.uk/warnings  DC hold responsibility for the South Winterbourne as it is a watercourse and no longer classer main river. The EA will only be interested in pollution or similar events, plus reporting.		
Dorset Council	01305 221000 Advice on flooding issues: 01305 225424 / 221837 Sandbags 01305 252479		www.dorsetcouncil.gov.uk  Lead Flood Authority for South Winterbourne.  Brian Richards, Flood Risk Manager, Assets & Property Dorset Council  DC are responsible for the South Winterbourne as it is classed as a watercourse rather than a river. They are responsible for the watercourse flood risk management and have permissive powers to enforce the laws relating to watercourses.  Relevant legislation: The Public Health Act 1936. • The Land Drainage Acts of 1991 and 1994. • Water Resources Act 1991. • Environment Agency Land Drainage Byelaws 1981		
Dorset Council Highways	01305 221000.		https://dorset-self.achieveservice.com/service/report-a-gullydrain-or-flooding-issue  Maintains safe conditions on the roads; puts flood warning signs on the highway and organises road closures/traffic diversions; clears blockages on highway drainage systems and culverts; and may take action to protect property from flooding by water from the highway where there is a failure of the highway drainage system.		

			Martinstown – (east approach) – flood sign stored with sandbags at east end of parish office. Sign to be erected on grass area to east of parish office near turning to Ewe Leaze Farm  Martinstown - (west approach) – flood sign stored as above. Sandbags at Brewers Arms. Sign to be erected on south side of road opposite new bridge to Church Farm about 15 metres from speed sign.
Contractors	Jon Buddle Tree Surgery 01305 889982 07775806488		Removal of tree limbs overhanging or fallen into stream. No contractual arrangements for stream clearance but may be able to provide chargeable service in an emergency
Parish Council	07359 243559	07359 243559	The Parish Council receives reports from the volunteer flood groups and any residents It maintains stocks of sandbags and emergency road signs provided by DC.
			Chair Mark Pemberton mvpcowleaze@gmail.com
			Clerk Marion Baird clerk@winterbornestmartin-pc.gov.uk
Riparian Owners			If a property is adjacent to,or borders a watercourse, or a watercourse runs through land privately owned, the owner of that property is known as a riparian owner. As a riparian owner, one assumes both rights and responsibilities upheld by legislation, laws and byelaws which govern activities within 8 metres from either bank, above or below the watercourse. Detailed information is set out in a booklet published by the Environment Agency (EA)called 'Living on the edge' which can be downloaded free of charge, or see <a href="https://www.gov.uk/guidance/owning-a-watercourse">https://www.gov.uk/guidance/owning-a-watercourse</a> . Failing to abide by the contained in this booklet and web site could lead to legal action being taken against the riparian owner
			The EA expectations are summarised below:
			<ul> <li>Riparian Owners should enable unimpeded flow of water through their property by</li> <li>ensuring vegetation and trees are kept under control (particularly highly invasive species Himalayan Balsam, Giant Hogweed, Ragwort, Fools water-cress, Common Reed, Willow herb)</li> <li>maintaining existing trees, and not allowing new trees or shrubs on the banks without permission from EA;</li> <li>not allowing branches or other debris to obstruct the watercourse</li> <li>not allowing object matter, vegetation, fallen branches to drift along the watercourse;</li> <li>accepting flood flows through your land;</li> <li>keeping banks, culverts, trash screens/traps etc. clear of debris;</li> <li>maintain the quality and quantity of water flowing onwards</li> </ul>

Adjacent Town/Parish Councils	Winterbourne Abbas/Steepleton Group 01305 889411  Winterbourne Farrington Group 01305 534661	clerk@winterb ourneabbasste epleton- pc.gov.uk  winterbornefar ringdon@dors et-aptc.gov.uk	https://www.winterbourneabbassteepleton-pc.gov.uk/ Clerk - Mr S Slade Chair - Richard Crumblehome  https://www.dt3web.co.uk/wfpc Clerk Mr A Harrison Chair Ms Jenny Webster. Vice Chair Mr Charles Norman
	Dorset Councillor 01305 62359 07543288636		http://moderngov.dorsetcouncil.gov.uk/mgUserInfo.aspx?UID=437 cllrroland.tarr@dorsetcouncil.gov.uk
Animals	RSPCA Weymouth 01305 259672		www.westdorsetrspca.org
Elderly	AGE UK Dorchester 01305 269444		www.ageuk.org
Hospital	01305 251150		www.dch.org
Magna Housing	01305 214027		magna.org.uk
Stress/Anxiety	Freephone 116123		www.samaritans.org
South Winterbourne Community Flood Action Group			<pre>swcfag@gmail.com https://sites.google.com/site/swcfag/ Chair: Richard Crumblehome Following intervention by WSMPC is no longer considered part of SWCFAG</pre>
Water Company	Wessex Water Water Supply 0345 6004600		Removal of ground water from sewer system  Clearance of blockages in public drains

	Drainage & Sewerage 0345 8505959	Wessex Water have not extracted water from the aquifer under the valley since 2014 The EA usually advise WW to cease water addition when ground water levels rise at the Kingston Russell bore hole.
Electricity Company	National Grid Electricity Infrastructure only 0800 404090	https://www.nationalgrid.com/uk/electricity-transmission/network-and-infrastructure/electricity-emergencies-and-safety-advice
	National Grid Power cuts 103	https://www.nationalgrid.com/uk/electricity-transmission/contact-us/power-cuts
Gas Company	Southern Gas Networks (SGN) Emergency 0800 111999	Gas infrastructure only
Telecommunications Company	BT Openreach 0800 023 2023 (option 1)	Responsible for telecoms infrastructure only. Subscriber services are the responsibility of individual resident contracts.
Fire & Rescue Service	999 for emergencies 0306 7990019 for non- emergencies	
Police	999 for emergencies 101 for non- emergencies	
Ambulance Service	999 for emergencies	

#### 1B - Local flood volunteers


Volunteers should be registered on the Environment Agency's Flood Line Warnings Direct service so they receive the advance flood alerts. It is best to have volunteers who are not riparian owners as they may be distracted by their own issues. Volunteers must not put their own safety at risk.

Flood volunteers have no statutory responsibility; they are simply community helpers that are attached a particularly area of the watercourse. They will, help with flood warning dissemination; have access to appropriate signs which will be deployed as necessary; liaise with the Parish Council, monitor blockages within the river system and provide information where required; provide help and advice where needed; help to provide assistance to vulnerable people where possible.


Name	Address	Telephone / Mobile	Email	Role
Karen Delafield	Washing Pool House DT2 9LD	01305 889301/07796838416	kdelafield@winterbornestmartin-	Parish Council Rep &
			pc.gov.uk	contact
Volunteer				Flood Vol, Area 8
				Rew Manor West
Volunteer				Flood Vol, Area 9
				Rew Manor East
				Stream junction only
Volunteer				Flood Vol, Area 10
				West
Volunteer				Flood Vol, Area 11
				Centre West
Volunteer				Flood Vol, Area 12
				Centre East
N/ 1 /				
Volunteer				Flood Vol, Area 13
				East

### 2A - Winterborne St Martin CP flood zone: Map showing direction of flooding


Areas officially prone to flooding – blue Winterborne St Martin CP boundaries – purple South Winterbourne flows North West to South West



#### 2B – Winterborne St Martin CP detailed flood management maps










Environment Agency – Community Flood Plan



Environment Agency - Community Flood Plan



Environment Agency – Community Flood Plan



Environment Agency – Community Flood Plan

# **3A – Issues to consider for resolution before a flood:** Locations at risk of flooding / source of flooding

Area number Location at risk		Source of flooding	Direction of flooding	
Area 08 Rew Manor West	Junction of North Rew Lane  Below Rew Manor	Surface water run-off from lane discharges into B3159 road and gullies	South	
		This section of road is low & floods as there is little height above the watercourse levels		
Area 09 Rew Manor East	None identified	Piped run-off to and overflow to roadside watercourse; disused sluice Flow to WP and road-side stream needs documented monitoring and adjustment to ensure proper balance and minimise flood risk to either channel.	On to B3159 or excess flow to WP	
Area 10 Martinstown West	At northernmost watercourse bend	Stream bifurcation with 225mm diameter corrugated plastic pipe (without a gulley) presumed to discharge downstream of culvert? Prone to frequent blockages causing road flooding. Pipe direct water from west east flow to roadside. West east channel overflow to roadside.	South	
		North South watercourse by new Church farm access road shown on map has now been diverted into plastic pipe.		
		Very low bridge leading to allotments/smallholding		
Area 11 Martinstown	Grove Hill road bridge Rectory bridge	Low bridges restricting flow	NSEW	
Centre West	Brewers Arms bridge under B3159	Gulleys uder B3159 get blocked with silt		
	Washing Pool watercourse	Narrow channels leading to WP with heavy silting due to agricultural land run off		
Area 12 Manor House access bridge has restricted flow and risk of blockage Centre East		Low bridge restricting flow	NSEW	
	B3159 either side of Manor Grove, camber prevents surface water draining	Poor road drainage		
Area 13 Martinstown East	Turnpike House	Low banks which overflow		
	Rear of Parish Office	Agricultural land with excess run-off forming seasonal ponds	North	
	Ewe Leaze Farm access road – low bridge	Low bridge restricting flow		

DC owned land around the Pump House not	Debris in watercourse	
maintained		

## 3B - Locations at higher risk of flooding

Area number	Location of risk	Trigger level	Actions
Area 08 Rew Manor West	Identified by SWCFAG survey     Junction of North Rew Lane – surface water run-off from lane discharges into B3159 road and gullies      Below Rew Manor -This section of road is low & floods as there is little height above the watercourse levels. Possible solution is to increase the height of the road surface, this was suggested to DCC when the bridge was reconstructed in 2013	Water on B3159	Alert Dorset Council as LFA Alert Dorset Council Highways
Area 09 Rew Manor East	None identified by SWCFAG or DC survey	Excess water on road or excess flow to Washing Pool	Adjust informal overflow to balance flow
Area 10 Martinstown West	Only partially surveyed by SWCFAG  At northernmost watercourse bend - 225mm diameter corrugated plastic pipe (without a gulley) presumed to discharge downstream of culvert? Prone to frequent blockages causing road flooding.  DC survey  Purbeck House bridge has restricted flow and risk of blockage  Other	Water on B3159	Alert Dorset Council as LFA Alert Dorset Council Highways
	Narrow channels leading to WP		Alert riparian owners
Area 11 Martinstown Centre West	Not surveyed by SWCFAG  Identified by DC survey      Grove Hill Road bridge has restricted flow and risk of blockage     Rectory bridge has restricted flow and risk of blockage     Brewers Arms bridge under B3159 has restricted flow and risk of blockage  Other Under road gullies by Brewers Arams frequent sand/silt build up	Water backing up by a bridge	Alert riparian owners  Alert Dorset Council as LFA Alert Dorset Council Highways Alert adjacent residents  Erect Flood Warning road signs  Martinstown – (east approach) – flood sign stored with sandbags at east end of parish office. Sign to

	Broken sewer pipes allow ground water ingress and overflow	Water seeping from manhole covers in road	be erected on grass area to east of parish office near turning to Ewe Leaze Farm  Martinstown - (west approach) – flood sign stored as above. Sign to be erected on south side of road opposite new bridge to Church Farm about 15 metres from speed sign.  Alert Wessex Water, obtain incident report number
Area 12 Martinstown Centre East	Not surveyed by SWCFAG  Identified by DC survey  • Manor House access bridge has restricted flow and risk of blockage  • B3159 either side of Manor Grove, camber prevents surface water draining	Water backing up by bridge Water pooling on B3159	Alert Dorset Council as LFA Alert Dorset Council Highways Alert adjacent residents  Erect Flood Warning road signs  Martinstown – (east approach) – flood sign stored with sandbags at east end of parish office. Sign to be erected on grass area to east of parish office near turning to Ewe Leaze Farm  Martinstown - (west approach) – flood sign stored as above. Sign to be erected on south side of road opposite new bridge to Church Farm about 15 metres from speed sign.
	Broken sewer pipes allow ground water ingress and overflow	Water seeping from manhole covers in road	Alert Wessex Water, obtain incident report number
Area 13 Martinstown East	Not surveyed by SWCFAG  Identified by DC survey  Turnpike House – low banks which overflow  Rear of Parish Office – agricultural land excess run-off forms pools		

Ewe Leaze Farm access road – low bridge restricting waterflow	Water backing up by bridge	Alert Dorset Council as LFA Alert Dorset Council Highways Alert adjacent residents
Other indicators		Erect Flood Warning road signs
East Lodge junction (C53/B3159) – ditches at capacity with flowing water on C53 east side, surface water flowing down road from Batts Lane		Martinstown – (east approach) – flood sign stored with sandbags at east end of parish office. Sign to be erected on grass area to east of parish office
<ul> <li>Parish Office. Very large ponds of water formed in agricultural land at rear</li> </ul>		near turning to Ewe Leaze Farm  Martinstown - (west approach) – flood sign stored
Park Farm House pumping water from its basement		as above. Sign to be erected on south side of road opposite new bridge to Church Farm about 15 metres from speed sign.

# **3C – Actions to be taken during a flood:** local flood actions

Area number	Location at risk	Action / trigger	Local action	Equipment required	Time required
Area 08 Rew Manor West	Junction of North Rew Lane  Below Rew Manor	Water on B3159	Alert Dorset Council Erect Flood Warning road signs	Martinstown - (west approach) – flood sign stored as above. Sandbags at Brewers Arms. Sign to be erected on south side of road opposite new bridge to Church Farm about 15 metres from speed sign.	1 hour
Area 09 Rew Manor East	Stream junction	Water on B3159 Flooding in water meadow or excess water in Washing Pool channels	Alert Dorset Council Erect Flood Warning road signs	Alert FVs and rebalance flow at informal weir.  A log of inspection visits and changes to be maintained,	1-2 hours
Area 10 Martinstown West	At northernmost watercourse bend	Water on B3159	Erect Flood Warning road signs  Alert Dorset Council	As above	1 hour
Area 11 Martinstown Centre West	Grove Hill road bridge Rectory bridge Brewers Arms bridge under B3159	Water backing up by a bridge	Erect Flood Warning road signs  Alert Dorset Council	As above	1 hour
Area 12 Martinstown Centre East	Manor House access bridge has restricted flow and risk of blockage  B3159 either side of Manor Grove, camber prevents surface water draining	Water backing up by bridge  Water pooling on B3159	Erect Flood Warning road signs  Alert Dorset Council	Martinstown – (east approach) – flood sign stored with sandbags at east end of parish office. Sign to be erected on grass area to east of parish office near turning to Ewe Leaze Farm	1 hour
Area 13 Martinstown East	Turnpike House  Rear of Parish Office  Ewe Leaze Farm access road – low bridge  Pump House	Water backing up by bridge Water failing to exit village	Erect Flood Warning road signs  Alert Dorset Council	As above	