## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>V</b>			
Environment				
Floor surface				
Signs	<b>V</b>			
Gates	<b>V</b>			
Fences	<b>V</b>			
Benches	<b>V</b>			
	21/2		Risk	Time Scale
Equipment	OK?	Issues	L/M/H	
Turnstile				
Multi Play	<b>V</b>			
Roundabout	<b>V</b>			
Spring See-Saw	<b>V</b>			
2Bay Swing	<b>V</b>			

Date	17/11/2023	Time Complete	<b>d</b> 10.30				
Weather Conditions. Sunny, wet underfoot.							
Additional Observations							
Signatu	reB Nanson	Name					
Signatu	re	Name					

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>V</b>			
Pavilion Inc fire extinguishers	<b>V</b>			
Defibrillator – solid icons displayed	<b>~</b>			
CCTV Cameras - free from cobwebs	<b>V</b>			
Sewerage Plant (Listen and warning light)	<b>~</b>			
Container	<b>V</b>			
Outfield	<b>V</b>			
Site Boundaries, Fences and Hedges	<b>V</b>			
Bins				

Weather C	Conditions.	Sunny,	wet	underfoot
-----------	-------------	--------	-----	-----------

## **Additional Observations**

Signature	B Nanson	Name	
J			
Signature		Name	
Date17/	11/2023		