## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>√</b>			
Environment	<b>,</b>			
Floor surface	<b>✓</b>			
Signs	<b>√</b>			
Gates	✓			
Fences	<b>√</b>			
Benches	<b>√</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	$  \checkmark  $			
Multi Play	<b>√</b>			
Roundabout	<b>√</b>			
Spring See-Saw	<b>√</b>			
2Bay Swing	<b>√</b>			

Date 14<sup>rd</sup> May 2023 Time Completed 2:00pm

Weather Conditions Sunny, warm, dry

**Additional Observations** 

Signature CJLing Name CJLing

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>√</b>			
Pavilion Inc fire extinguishers	<b>✓</b>			
Defibrillator – solid icons displayed	<b>√</b>			
Sewerage Plant (Listen and warning light)	<b>√</b>			
Container	<b>✓</b>			
Outfield	<b>✓</b>			
Site Boundaries, Fences and Hedges	<b>✓</b>			
Bins	×	None had been emptied.		

Weather Conditions	Sunny, warm, dry
--------------------	------------------

## **Additional Observations**

Signature CJ Ling Name CJ Ling

Date 14<sup>th</sup> May 2023