## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General				
Environment	<b>V</b>			
Floor surface	<b>/</b>			
Signs	<b>/</b>			
Gates	<b>~</b>			
Fences	<b>/</b>			
Benches	<b>~</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>/</b>			
Multi Play	<b>~</b>			
Roundabout	<b>~</b>			
Spring See-Saw	<b>/</b>			
2Bay Swing	<b>/</b>			

Date	21/04/2021Time Completed14.30								
Weathe	er Conditions: Sunny								
Additional Observations									
Signatu	reDavid Stevens								
Signatu	re Name								

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>/</b>			
Pavilion Inc fire extinguishers	<b>/</b>			
Sewerage Plant (Listen and warning light)	<b>\</b>			
Container	<b>/</b>			
Outfield	<b>/</b>			
Site Boundaries, Fences and Hedges	<b>/</b>			
Bins	<b>/</b>	Car park ½ full White Horse ½ full		

Weather Conditi	ions: Fair	
Additional Obse	rvations	
Signature	NameDavid Stevens	
Signature	Name	
Date		