AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface				
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	V			
Roundabout	V			
Spring See-Saw	V			
2Bay Swing	V			

Date	28/02	/2021	Time Co	mplete	d 1100	
Weather Conditions Dry & dull						
Additional Observations						
Signatu	re			Name	Bryan Nanson	
Signatu	re			Name		

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•		, ,	
Pavilion Inc fire extinguishers	•			
Sewerage Plant (Listen and warning light)	V			
Container	•			
Outfield				
Site Boundaries, Fences and Hedges				
Bins	•			

Mosthar	Conditions	Day 9. du	11
weather	Conditions	Drv & du	H

Additional Observations

Signature		Name	Bryan Nanson
Signature		Name	
Date 28/0	2/2021		