AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General				
Environment	V			
Floor surface	/			
Signs	/			
Gates	~			
Fences	/			
Benches	~			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	~			
Roundabout	/			
Spring See-Saw	~			
2Bay Swing	~			

Date	21/02/2022Time Completed15:00				
Weather Conditions - Sunny					
Additional Observations					
Signatu	NameDavid Stevens				
Signatu	Name				

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	/			
Pavilion Inc fire extinguishers	~			
Defibrillator – solid icons displayed	~			
Sewerage Plant (Listen and warning light)	~			
Container	/			
Outfield	~			
Site Boundaries, Fences and Hedges	~	Moved a few branches		
Bins	~	Both ¼ full		

٠.			:	:	C
v	veatn	ercc	naiti	ıons:	Sunny

Additional Observations

Signature	<u> </u>		Name	David Stevens
Signature		Name		
Date				