## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General				
Environment				
Floor surface	<b>V</b>			
Signs	<b>V</b>			
Gates	<b>V</b>			
Fences	<b>V</b>			
Benches	<b>V</b>			
Faviorent	OK?	l	Risk	Time Scale
Equipment	-	Issues	L/M/H	
Turnstile				
Multi Play	<b>V</b>			
Roundabout	<b>V</b>			
Spring See-Saw	<b>V</b>			
2Bay Swing	<b>V</b>			

Date	04/07/2023	Time Complete	<b>d</b> 1430						
Weather Conditions - overcast, light showers									
Additional Observations									
Signatı	ıreB Nansı	on Name							
Signati	ıre	Name							

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>V</b>			
Pavilion Inc fire extinguishers	<b>V</b>			
Defibrillator – solid icons displayed	<b>V</b>			
Sewerage Plant (Listen and warning light)	<b>V</b>			
Container	<b>V</b>			
Outfield	<b>V</b>			
Site Boundaries, Fences and Hedges	•			
Bins	<b>~</b>			

## **Additional Observations**

Signature	B Nanson	Name	
Signature		Name	
Date04/07	/2023		