AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	/			
Floor surface	~			
Signs	~			
Gates	/			
Fences	/			
Benches	/			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	~			
Roundabout	~			
Spring See-Saw	~			
2Bay Swing	~			

Date	06/10/2021Time Completed10:45				
Weather Conditions: Sunny					
Additional Observations					
Signatur	eDavid Stevens				
Signatur	e Name				

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
	?		L/M/H	
Entrances	/			
Pavilion Inc fire extinguishers	/			
Sewerage Plant (Listen and warning light)	\			
Container	/			
Outfield	~			
Site Boundaries, Fences and Hedges	/			
Bins	/	Car park 1/2 full White Horse full	М	

W	'eather	Condi	itions:	Sunny
---	---------	-------	---------	-------

Additional Observations

Signatur	re			Name	David Stevens	
Signatur	re		Name	·		
Date	06/10,	/2021				