AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface	•			
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Equipment	OK:	1334C3	L/141/11	
Turnstile				
Multi Play	V			
Roundabout	V			
Spring See-Saw	V			
2Bay Swing	V			

Date28/11/2022Time Completed1330							
Weather Conditions - Dull, overcast & light rain							
Additional Observations							
Signature	B Nanson	Name					
Signature		Name					

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•			
Pavilion Inc fire extinguishers	•			
Defibrillator – solid icons displayed	•			
Sewerage Plant (Listen and warning light)	V			
Container	•			
Outfield	•			
Site Boundaries, Fences and Hedges	•			
Bins	•			

Weather Conditions Dull, overcast & light rain

Additional Observations

Signature	B Nanson	Name	
Signature		Name	
Date 28/11	/2022		