

**AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 37**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	OK			
Floor surface	OK			
Signs	Ok			
Gates	OK			
Fences	OK			
Benches	OK			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	OK			
2Bay Swing	OK			

**Date** ...26/10/2020..... **Time Completed** ...13:30.....

**Weather Conditions** Showers, sun

**Additional Observations**

Signature ..... Name Graham Roads

.....

Signature ..... Name .....

**AMPFIELD RECREATION GROUND INSPECTION** No. 2020 / 37

<b>Area</b>	<b>OK ?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
Entrances	OK			
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK			
Container	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	OK			
Bins		Required emptying		

**Weather Conditions** sun, showers

**Additional Observations**

Signature ..... Name ...Graham Roads.....

Signature ..... Name .....

Date : 26/10/2020

**Date** .....