## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	<b>/</b>			
Floor surface	<b>~</b>			
Signs	<b>~</b>			
Gates	<b>/</b>			
Fences	<b>/</b>			
Benches	<b>/</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>~</b>			
Multi Play	<b>~</b>			
Roundabout	<b>~</b>			
Spring See-Saw	<b>~</b>			
2Bay Swing	<b>~</b>			

Date	10/10/2021Time Completed14:30		
Neather Conditions: Sunny			
Additional Observations			
Signatu	reDavid Stevens		
Signatu	re Name		

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	ОК	Issues	Risk	Time Scale
Entrances	?		L/M/H	
Pavilion Inc fire extinguishers	<b>/</b>			
Sewerage Plant (Listen and warning light)	<			
Container	<b>/</b>			
Outfield	<b>/</b>			
Site Boundaries, Fences and Hedges	<b>~</b>			
Bins	<b>/</b>	Car park: empty White Horse: empty		

W	'eather	Condi	itions:	Sunny
---	---------	-------	---------	-------

## **Additional Observations**

Signature	NameDavid Stevens
Signature	Name
Data	40/40/2024