AMPFIELD RECREATION GROUND Playground Inspection No. 2021 / 03

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	/			
Environment	ľ			
Floor surface	√			
Signs	√			
Gates	√			
Fences	√			
Benches	√			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	√			
Roundabout	√			
Spring See-Saw	√			
2Bay Swing	√			

Date	12/02/2021	Time Completed 11	:55
------	------------	-------------------	-----

Weather Conditions Dry and sunny, cold

Additional Observations

Signature C J Ling Name C J LING

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 38

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	√			
Sewerage Plant (Listen and warning light)	√			
Container	√			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	√			

۱۸/	eather	Cana	litions
٧v	eauner	Cond	nuons

Sunny and dry, cold

Additional Observations

Signature CJLing Name CJLING

Date 12/02/2021