

Worksheet Ref	Date Receiv	Complainant Name Add1	
WK/000134571	12/02/2021	?	Misson
WK/000134568	16/02/2021	BI	Misson
WK/000134540	16/02/2021	Q	Misson
WK/000134569	17/02/2021	BI	Misson
WK/000134493	17/02/2021	G	Misson
WK/000134570	18/02/2021	BI	Misson
WK/000134542	18/02/2021	D	Misson
WK/000134709	21/02/2021	G	Misson
WK/000134711	22/02/2021	G	Misson
WK/000134712	23/02/2021	G	Misson
WK/000134715	23/02/2021	BI	Misson
WK/000134713	24/02/2021	G	Misson
WK/000134714	25/02/2021	D	Misson
WK/000134716	25/02/2021	BI	Misson
WK/000134751	26/02/2021	BI	Misson
WK/000134771	26/02/2021	G	Misson
WK/000134795	28/02/2021	R	Misson
WK/000134818	28/02/2021	BN	Austerfield

Details

Complainant moved into village on 12th February. See attached. Complaining about the odour and feeling nauseous after taking the dog for a walk.
Odour complaint - Driving into Misson about 6.30pm. See attached.
Report of terrible smell from above for few days, worse on 16th Feb. In village and driving past site.
Odour complaint - Driving past site at 2:45pm
TT stench Mon 15, Tues 16 & Wed 17 Feb, either driving past site or in village, also Tues night 7.30pm onwards in Misson
Odour complaint - 12:30 pm West Street - See attached.
1120 odour in Village
See attached complaint about the bad odour from the above.
See attached complaint about the bad odour from the above.
See attached complaint about the bad odour from the above.
See attached complaint about the bad odour from the above.
See attached complaint about the bad odour from the above.
See attached complaint about the bad odour from the above.
See attached complaint about the bad odour from the above.
Odour noticed at 5.25am & 9am . 2 complaints. Emails attached.
Friday 26th Feb - the most horrendous sickening TT stench from early morning my home & garden - hope you all have a stink free week
Between 9am-11am smelt bad. In bawtry area.
Tunnel Tech Odour smelling on sunday 10am-3pm.

Location	Odour	Detect
Misson		
Newington Rd		
Newington Rd		
Newington Rd		
Misson		
Misson		
Misson		
Misson Or Newington Rc		
Misson Or Newington Rc		
Misson Or Newington Rc		
Outskirts of Village		
Misson Or Newington Rc		
Newington Rd		
Misson		
Misson		
Misson		
Bawtry		
Austerfield		

Duration of odour	Wind Direction at Time of Complaint
?	ESE SE
Driving Past	SSW
Driving Past	SSW
Driving Past	SSW
?	SSW
?	SW
?	SW
?	Unclear when odour was detected
?	Unclear when odour was detected
?	Unclear when odour was detected
On walk, unclear.	S SSW
?	Unclear when odour was detected
Driving Past	WNW W
Detected at 0925	WNW
Detected at 0525 and 0900	W
Early Morning	W
0900-1100	WSW
1000 to 1500	WSW SE