

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 26

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓	Playground sign present at one entrance only	L	3 months
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date 10/08/2020 **Time Completed** 12:25

Weather Conditions Hot and sunny

Additional Observations

Signature C J Ling

Name C J LING

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 26

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✗	Service is due	M	1 month
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditions

Hot and sunny

Additional Observations

Signature C J Ling

Name C J LING

Date 10/08/2020