## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	ОК			
Environment				
Floor surface	ОК			
Signs	OK			
Gates	ОК			
Fences	ОК			
Benches	ОК			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	OK			
2Bay Swing	OK			

Date	05/10/22	Tir	ne Complete	<b>d</b> 09:00 am				
Weather Conditions dry overcast windy								
Additional Observations								
Signatu	re		Name	G Roads				
Signatu	re		Name					

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	OK		2,101,111	
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK	Noise, no light		
Container	ОК			
Outfield	ОК			
Site Boundaries, Fences and Hedges	ОК			
Bins	OK	Bin in car park needs emptying	L	

Weather Conditions: dry, overcast, windy						
Additional Observations						
Signature	NameG Roads					
Signature	Name					
<b>Date</b> 05/10/2022						