

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	OK			
Floor surface	OK			
Signs	OK			
Gates	OK			
Fences	OK			
Benches	OK			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	OK			
2Bay Swing	OK			

Date ...19/12/2021..... **Time Completed** 12:15 pm.....

Weather Conditions cloud, some sun

Additional Observations

Signature Name ...G Roads.....

Signature Name

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	OK			
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK	Noise, no light		
Container	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	OK			
Bins	OK	The two on the eastern side. Did not look in the bin by the car park entrance		

Weather Conditions Cloud, some sun

Additional Observations

Signature Name ...G Roads.....

Signature Name

Date 19/12/2021

.....