AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	/			
Environment	_			
Floor surface	~			
Signs	/			
Gates	/			
Fences	/			
Benches	~			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	/			
Multi Play	\			
Roundabout	~			
Spring See-Saw	~			
2Bay Swing	~			

Date	16/11/2021 Time Completed14:30			
Weather Conditions - Cloudy				
Additional Observations				
Signatur	e NameDavid Stevens			
Signatur	e			

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	/			
Pavilion Inc fire extinguishers	/			
Defibrillator – solid icons displayed	/			
Sewerage Plant (Listen and warning light)	~			
Container	/			
Outfield	/			
Site Boundaries, Fences and Hedges	/			
Bins	/	Both ¼ full		

Weather	Conditions:	Cloudy
---------	-------------	--------

Additional Observations

Signature	Na	ameDavid	d Stevens
Signature	 Name		
Date			