

**AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 36**

<b>Auxiliary Items</b>	<b>OK?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
<b>Equipment</b>	<b>OK?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

**Date** 22/10/2020      **Time Completed** 12:00

**Weather Conditions**      **Overcast and dry**

**Additional Observations**

Signature      C J Ling

Name C J LING

**AMPFIELD RECREATION GROUND INSPECTION** No. 2020 / 36

<b>Area</b>	<b>OK ?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

**Weather Conditions**

Overcast and dry

**Additional Observations**

Signature      C J Ling

Name C J LING

**Date**    22/10/2020