## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

| Auxiliary      |          |        | Risk          | Time Scale |
|----------------|----------|--------|---------------|------------|
| Items          | OK?      | Issues | L/M/H         |            |
| General        | <b>V</b> |        |               |            |
| Environment    |          |        |               |            |
| Floor surface  | •        |        |               |            |
| Signs          | <b>V</b> |        |               |            |
| Gates          | <b>V</b> |        |               |            |
| Fences         | <b>V</b> |        |               |            |
| Benches        | <b>V</b> |        |               |            |
| Equipment      | OK?      | Issues | Risk<br>L/M/H | Time Scale |
| Equipment      | OK:      | 1334C3 | L/141/11      |            |
| Turnstile      |          |        |               |            |
| Multi Play     | <b>V</b> |        |               |            |
| Roundabout     | <b>V</b> |        |               |            |
| Spring See-Saw | <b>V</b> |        |               |            |
| 2Bay Swing     | <b>V</b> |        |               |            |

| Date                               | ate20/07/2022Time Completed11.00 |          |      |  |  |  |
|------------------------------------|----------------------------------|----------|------|--|--|--|
| Weather Conditions - dry, overcast |                                  |          |      |  |  |  |
| Additional Observations            |                                  |          |      |  |  |  |
|                                    |                                  |          |      |  |  |  |
| Signatu                            | re                               | B Nanson | Name |  |  |  |
| Signatu                            | re                               |          | Name |  |  |  |

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

| Area  | OK<br>? | Issues | Risk<br>L/M/H | Time Scale |
|---|---------|--------|---------------|------------|
| Entrances                                       | •       |        |               |            |
| Pavilion<br>Inc fire extinguishers              | •       |        |               |            |
| Defibrillator – solid<br>icons displayed        | •       |        |               |            |
| Sewerage Plant<br>(Listen and warning<br>light) | •       |        |               |            |
| Container                                       | •       |        |               |            |
| Outfield  | •       |        |               |            |
| Site Boundaries,<br>Fences and Hedges           | •       |        |               |            |
| Bins  | •       |        |               |            |

| Weather | Conc | litions | – dry, | overcast |
|---------|------|---------|--------|----------|
|---------|------|---------|--------|----------|

## **Additional Observations**

| Signature  | B Nanson | Name |  |
|------------|----------|------|--|
| Signature  |          | Name |  |
| Date 20/07 | /2022    |      |  |