## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General				
Environment	<b>V</b>			
Floor surface	<b>/</b>			
Signs	<b>/</b>			
Gates	<b>~</b>			
Fences	<b>~</b>			
Benches	<b>~</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>/</b>			
Multi Play	<b>~</b>			
Roundabout	<b>~</b>			
Spring See-Saw	<b>/</b>			
2Bay Swing	<b>/</b>			

Date	<b>25/07/2021</b> Time Completed16.40					
Weathe	eather Conditions: Cloudy					
Additio	dditional Observations					
Signatuı	eDavid Stevens					
Signatu	e Name					

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>\</b>			
Pavilion Inc fire extinguishers	<b>/</b>			
Sewerage Plant (Listen and warning light)	<b>\</b>			
Container	<b>/</b>			
Outfield	<b>/</b>			
Site Boundaries, Fences and Hedges	<b>/</b>			
Bins	<b>/</b>	Car park 1/4 full White Horse full	М	

Weather	Conditions:	Cloudy
---------	-------------	--------

## **Additional Observations**

Signature	David Stevens
<b>.</b>	
Signature	Name
Date .	.25/07/2021