

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date ...25/04/2021..... **Time Completed** ...12:30.....

Weather Conditions Dry, Warm, Sunny, Windy

Additional Observations

Signature ...C J Ling..... NameC J Ling.....

Signature ...C J Ling..... NameC J Ling.....

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditions

Dry, Warm, Sunny, Windy

Additional Observations

There has been a small fire at the South West corner of the recreation ground with some logs and other materials burnt.

SignatureC J Ling..... NameC J Ling.....

SignatureC J Ling..... NameC J Ling.....

Date25 April 2021.....