

AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 33

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date ...27/09/2020..... **Time Completed** ...10.30am.....

Weather Conditions: Bright & dry, cool

Additional Observations

Signature NameBryan Nanson....

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 33

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditions

Bright, dry, cool

Additional Observations

Signature Name ...Bryan Nanson.....

Signature Name

Date ...27/09/2020.....