

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	OK	All bins require emptying		
Floor surface	OK			
Signs	OK			
Gates	OK			
Fences	OK			
Benches	OK			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	OK			
2Bay Swing	OK			

Date ...13/07/2022..... **Time Completed** 17:00

Weather Conditions Sunny, hot

Additional Observations

Signature Name ...G Roads.....

Signature Name

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	OK			
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK			
Container	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	OK			
Bins	OK	Very full		

Weather Conditions Sunny, hot

Additional Observations: the ANBCC groundsman was working on site. He asked whether he should expect the cleaner this week. Apparently, she has not attended and cleaning was overdue. He also advised that the kitchen at the ARG was down to its last roll of kitchen paper. Could he have some more?

As previously agreed with the chairman, the two bags of FOCW tools and equipment were stored in the cupboard of the APC container. The cupboard door was unlocked but, as it now contains tools, it was locked on departing.

Signature Name ...G Roads.....

Signature Name

Date 13/07/2022

.....