AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	\checkmark			
Environment	•			
Floor surface	\checkmark			
Signs	\checkmark			
Gates	\checkmark			
Fences	\checkmark			
Benches	\checkmark			
			Risk	Time Scale
Equipment	ОК?	Issues	L/M/H	
Turnstile	\checkmark			
Multi Play	\checkmark			
Roundabout	\checkmark			
Spring See-Saw	\checkmark			
2Bay Swing	\checkmark			

Date 21st June 2022 Time Completed 12:15pm

Weather Conditions Hot, sunny

Additional Observations

Weeds round edge of play area and adjoining path

Signature CJLing Name CJLing

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	~			
Pavilion Inc fire extinguishers	\checkmark			
Defibrillator – solid icons displayed	\checkmark			
Sewerage Plant (Listen and warning light)	~			
Container	\checkmark			
Outfield	\checkmark			
Site Boundaries, Fences and Hedges	\checkmark			
Bins	\checkmark	All three bins full		

Weather Conditions

Hot, sunny

Additional Observations

Signature CJLing Name CJLing

Date 21st June 2022