## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>√</b>			
Environment	_			
Floor surface	<b>✓</b>			
Signs	<b>√</b>			
Gates	<b>√</b>			
Fences	<b>√</b>			
Benches	<b>√</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>√</b>			
Multi Play	<b>√</b>			
Roundabout	<b>√</b>			
Spring See-Saw	<b>√</b>			
2Bay Swing	<b>√</b>			

Date	25 <sup>th</sup> March 2022	Time Completed	10:30am
------	-----------------------------	----------------	---------

Weather Conditions Sunny, dry

**Additional Observations** 

Signature CJ Ling Name CJ Ling

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>√</b>			
Pavilion Inc fire extinguishers	<b>√</b>			
Defibrillator – solid icons displayed	<b>√</b>			
Sewerage Plant (Listen and warning light)	<b>√</b>			
Container	<b>√</b>			
Outfield	✓			
Site Boundaries, Fences and Hedges	<b>√</b>			
Bins	<b>✓</b>			

Weather	Conditions	
vveatner	Conditions	

Sunny, dry

**Additional Observations** 

Signature CJ Ling Name CJ Ling

Date 25<sup>th</sup> March 2022