

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date ...09/10/2022..... **Time Completed**11.00 AM.....

Weather Conditions - sunshine

Additional Observations

SignatureB Nanson..... Name

Signature Name

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Defibrillator – solid icons displayed	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	X	Bin at A3090 entrance is overfull and was not emptied on 07/10/2022. Report submitted to TVBC.		

Weather Conditions – sunshine

Additional Observations

SignatureB Nanson..... Name

Signature Name

Date ...09/10/2022.....