

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

Date 21/02/2021..... **Time Completed** ...12.30pm.....

Weather Conditions: Cloudy

Additional Observations

Signature  NameDavid Stevens.....


Signature Name

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✗	Drainpipe detached (nearest to the entrance from the White Horse).	L	
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓	Three mole hills near the golf course boundary	L	
Bins	✓	Both bins ¾ full		

Weather Conditions: Cloudy

Additional Observations

Signature  NameDavid Stevens.....

Signature Name

Date