AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 03

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
	 	issues	L/IVI/П	
General	$\overline{}$			
Environment				
Floor surface	√			
Signs	√			
Gates	√			
Fences	√			
Benches	√			
			Risk	Time Scale
Equipment	ок?	Issues	L/M/H	Time Seale
2 x Cradle	/			
Swings	•			
2x Flat Swings	√			
Stepping Pods	√			
Spinning Pole	√			
Two Up One	/			
down slide unit	V			
See-Saw	√			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	√			

Date	11th February 2020	Time Completed	10:45am				
Weather Conditions Bright, cool, dry, windy							
Additional Observations							

Signature	 Name	C J LING
Signature	 Name	

AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 03

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	√		Ly IVI) II	
Pavilion Inc fire extinguishers	√			
Sewerage Plant (Listen and warning light)	√			
Container	√			
Outfield	√			
Site Boundaries, Fences and Hedges	√			
Bins	√	Green bin at "White Horse" gate about three quarters full		

Weather Conditions Bright, cool, dry, windy

Additional (Observations
--------------	--------------

Signature	 Name	C J LING
Signature	 Name	

Date 11th February 2020