

**t:** +44 (0)1202 84 96 95  
**e:** safe@thefirepoint.co.uk  
**w:** thefirepoint.co.uk  
**m:** Unit 3 Old Manor Farm Buildings  
 187 Leigh Road  
 Wimborne  
 Dorset  
 BH21 2BT



West Moors Memorial Hall & Social Club  
 Station Road  
 West Moors  
 Ferndown  
 Dorset  
 BH22 0HZ

Inspection Date: 02/05/2025  
 Duration Test:


### Emergency Lighting Inspection Report

Area	Device type	Function	Status	Comments
Hall Entrance (external)	Bulkhead	180	Passed	
Hall Entrance (external)	Bulkhead	180	Passed	
Hall Entrance	Bulkhead	180	Passed	
Ladies W/C	Bulkhead	180	Passed	
Gents W/C	Bulkhead	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Bulkhead	180	Passed	
Hall	Twinspot	180	Passed	
Hall	Bulkhead	180	Passed	
Hall	Twinspot	180	Passed	
Hall	Bulkhead	180	Passed	
Hall	Twinspot	180	Passed	
Hall to Circulation	Bulkhead	180	Passed	
Hall Fire Exit External	Bulkhead	180	Passed	
Stage	Bulkhead	180	Passed	
Stage	Bulkhead	180	Passed	
Stage	Bulkhead	180	Passed	
Small Meeting Room	Bulkhead	180	Passed	
Small Meeting Room	Bulkhead	180	Passed	
Small Meeting Room	Bulkhead	180	Passed	
Stage Circulation Space	Ceiling Mount	180	Passed	
Stage Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	




Extinguisher Supplies

*Quality Assured Fire Protection.*



Inspection Date: 02/05/2025

*Quality Assured Fire Protection.*



Inspection Date: 02/05/2025

[illegible]

*Quality Assured Fire Protection.*