

**Greenhead Parish Council – Asset Inventory and Condition Check 2026**

<b>ITEM</b>	<b>LOCATION</b>	<b>CONDITION</b>	<b>ACTION REQUIRED</b>	<b>URGENCY</b>	<b>COMPLETED</b>
<b>A. STREET FURNITURE</b>					
1.BUS SHELTER	A69 (UNDERPASS)				
2.BUS SHELTER	A69				
3.BUS SHELTER	A69				
4.BUS SHELTER	A69				
5.UNIPART STREET SIGN	GLENWHELT BANK				
6.STONE BUS SHELETER	GILSLAND CORNER	Stone work fine but, wood roof starting to rot.	Roof slats to be replaced	Summer	
7. a BENCH - WOOD b BENCH -GLASDON	GILSLAND CORNER	Satisfactory			
7.STONE FOUNTAIN	GREENHEAD CENTRE	Planters need attention	To be weeded and looked after	Spring/summer	
8.WAR MEMORIAL	GREENHEAD CENTRE	Satisfactory			
9.NOTICEBOARD	VILLAGE HALL	Satisfactory			

Undertaken Date: 2<sup>nd</sup> March 2026

Signed: S M Saunders – Clerk

## Greenhead Parish Council – Asset Inventory and Condition Check 2026

10.NOTICEBOARD	BANK FOOT	Moisture getting in	Add absorbent sachets	ASAP	
11.FINGER POST SIGN	GREENHEAD CENTRE	Satisfactory			
12.BIN	WALLTOWN	Not attached to concrete	refix	ASAP	
13.BIN	VILLAGE HALL	Satisfactory			
14.TOMMY STATUE	GREENHEAD CENTRE	Satisfactory			
<b>B. PLAYGROUND</b>	BY SCHOOL				
1.SWINGS		Signs of rust	Re-painted	Spring	
2.SEESAW		Satisfactory			
3.SPINNER		Satisfactory			
4.ROCKER		Spring is very rusty	Needs replacing	ASAP	
5.PLAYHOUSE		To be purchased and positioned			
6.SEATS a – on RHS b – on LHS c- On Cemetery wall.		All wood seats which need a varnish.	Varnish	Spring/summer	
7.BIN		Satisfactory			
AREA IN GENERAL		Weed free, old mat to remove.	Bark for swings and keep on top of weeds and raking.	All year	
<b>C. MILLENNIUM GREEN</b>					
1.GREEN WOOD & STONE SEATS a– RHS B - LHS		Wood looking worn	Re-paint wood	Spring/summer	
2. PICNIC BENCH ON RHS - MARMAX		Satisfactory			

Undertaken Date: 2<sup>nd</sup> March 2026

Signed: S M Saunders – Clerk

## Greenhead Parish Council – Asset Inventory and Condition Check 2026

3.BENCH – BY STREAM RHS- MARMAX		Satisfactory			
4.BENCH BY STREAM CENTRE- MARMAX		Satisfactory			
5. BENCH IN STONE AREA		Wood – needs a varnish	Varnish	Spring/summer	
6.BENCH ON LHS - MARMAX		Satisfactory			
7. PICNIC BENCH ON LHS - MARMAX		Satisfactory			
8.GLOBE PLAQUE		Satisfactory			
9.PLAQUES a – LHS b- RHS		Satisfactory			
10. BINS a – ? b-by entrance		Satisfactory			
11. GATES & RAILINGS		Small gate looking rusty.	Re-paint gate and check railings to see if they need attention	Spring/summer	
<u>AREA IN GENERAL</u> LAND WALL		Satisfactory			

Undertaken Date: 2<sup>nd</sup> March 2026

Signed: S M Saunders – Clerk

**PHOTOS**

**A. Street Furniture**

Undertaken Date: 2<sup>nd</sup> March 2026

Signed: S M Saunders – Clerk

**Greenhead Parish Council – Asset Inventory and Condition Check 2026**



A.6. Stone Bus Shelter



A.7a Bench



A.7b Bench



A.7. Stone Fountain



A.8 War Memorial



A.9 Noticeboard

Undertaken Date: 2<sup>nd</sup> March 2026

Signed: S M Saunders – Clerk


Greenhead Parish Council – Asset Inventory and Condition Check 2026



A.11 Finger Post



A.13 Bin



A.14 Tommy Statue

Undertaken Date: 2<sup>nd</sup> March 2026

Signed: S M Saunders – Clerk

**B. Playground**



B1.2 Swing & Seesaw



B.3 Spinner



B.4 Rocker

B.6c Bench



B.6a Bench



B.6b Bench

C.1b Seat

