AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	√			
Items General Environment Floor surface Signs Gates Fences Benches Cuipment Turnstile Multi Play Roundabout Spring See-Saw				
Floor surface	✓	Few weeds in surface of play area at South end.		
Signs	√			
Gates	√			
Fences	√			
Benches	√			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<			
Multi Play	√			
Roundabout	√			
Spring See-Saw	√			
2Bay Swing	√			

Date	30/05/2021	Time Completed11	:00				
Weather Conditions Dry, Hot, Sunny							
Additional Observations							
Signatu	reC J Ling	NameC	J Ling				
Signatu	re	Name					

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	√			
Pavilion Inc fire extinguishers	√	Away changing room has bin full of beer cans		
Sewerage Plant (Listen and warning light)	√			
Container	√			
Outfield	√			
Site Boundaries, Fences and Hedges	√			
Bins	√	Brown bin 7/8 full		

Bins	√	Brown bin 7,	/8 full				
					_		
Weather Condition	ons						
Dry, Hot, Sunny							
Additional Observations							
Signature			Name				
Signature			Name				
Date 30 M	ay 2021						