## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>V</b>			
Environment				
Floor surface	<b>~</b>			
Signs	<b>V</b>			
Gates	<b>V</b>			
Fences	<b>V</b>			
Benches	<b>✓</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Equipment	4	issues	L/ IVI/ II	
Turnstile				
Multi Play	<b>V</b>			
Roundabout	<b>V</b>			
Spring See-Saw	V			
2Bay Swing	<b>V</b>			

Date	06/04/2022Time Completed	d10.3	30		
Weather Conditions - overcast with intermittent rain					
Additional Observations					
Signatu	reB Nanson	Name			
Signatı	re	Name			

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>V</b>			
Pavilion Inc fire extinguishers	•			
Defibrillator – solid icons displayed	•			
Sewerage Plant (Listen and warning light)	•			
Container	•			
Outfield	<b>~</b>	Reviewed from pavilion verandah		
Site Boundaries, Fences and Hedges	•			
Bins	•	Ready for emptying		

Weather Conditions -	· overcast with	intermittent	rain

## **Additional Observations**

Signature	B Nanson	Name	
Signature		Name	
Date 06/04	./2022		