

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	OK			
Floor surface	OK			
Signs	OK			
Gates	OK			
Fences	OK			
Benches	OK			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	OK			
Multi Play	OK			
Roundabout	OK			
Spring See-Saw	OK			
2Bay Swing	OK			

**Date** ...10/03/2022..... **Time Completed** 12:15 pm.....

**Weather Conditions** cloud, dry

**Additional Observations**

Signature ..... Name ...G Roads.....

Signature ..... Name .....

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	OK			
Pavilion Inc fire extinguishers	OK			
Sewerage Plant (Listen and warning light)	OK	No noise, no light		
Container	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	OK			
Bins	OK			

**Weather Conditions** Cloud,

### Additional Observations

**A member of the public walking their dog around the field pointed out a gap between the gate on the western side of the carpark and the 3m? boundary fence and asked whether this might be closed?**

Signature ..... Name ...G Roads.....

Signature ..... Name .....

**Date** 10/03/2022

.....