AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface				
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	V			
Roundabout	V			
Spring See-Saw	V			
2Bay Swing	V			

Date	21/07/202	1	Time Co	mplete	d 1145	
Weather Conditions Hot and sunny						
Additional Observations						
Signatu	re			Name	Bryan Nanson	
Signatu	re			Name		

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•			
Pavilion Inc fire extinguishers	~			
Sewerage Plant (Listen and warning light)				
Container	•			
Outfield	•			
Site Boundaries, Fences and Hedges	•			
Bins	•			

14/46	C = 10 d 14 = 10 =	11-4	
weather	Conditions	Hot and	sunnv

Additional Observations

Signature		Name	Bryan Nanson
Signature		Name	
Date 21/0	7/2021		