## AMPFIELD RECREATION GROUND Playground Inspection No. 2020 / 28

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	1			
Environment				
Floor surface				
Signs	<b>-</b>			
Gates	<b>-</b>			
Fences	<b>-</b>			
Benches	<b>-</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile				
Multi Play	<b>\</b>			
Roundabout				
Spring See-Saw				
2Bay Swing				

Date	24/08/2020 Time C	omplete	<b>d</b> 11.30am			
Weather Conditions: Mild, dry and dull						
Additional Observations						
Signatu	e	Name	Bryan Nanson			
Signatu	e	Name				

1

<sup>\*</sup>Inspection number to be added by Inspector

## AMPFIELD RECREATION GROUND INSPECTION No. 2020 / 28

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion Inc fire extinguishers	<b>✓</b>			
Sewerage Plant (Listen and warning light)				
Container				
Outfield	•			
Site Boundaries, Fences and Hedges				
Bins	I.			

14/	C I'A'
weather	Conditions

Mild, dry and dull r

## **Additional Observations**

Signature		Name	Bryan Nanson
Signature		Name	
Date24/0	08/2020		

2

<sup>\*</sup>Inspection number to be added by Inspector