### **B4449 ISSUES**


PICTURES TAKEN BY

JOE DEAN

GRAHAM DIXON-BROWN

KEITH HICKSON

GILL SELLARS



### EXAMPLES OF POORLY MAINTAINED DRAINAGE




#### **EXAMPLES - DRAINAGE ISSUES**





EXAMPLES OF DAMAGED VERGES







# EXAMPLES OF MISALIGNED MAN-HOLE & DRAINS COVERS RESULT IN EXCESSIVE NOISE & VIBRATION









PATCHED ROADS ADDS TO THE NOISE AND VIBRATION ISSUE







### NARROW ROAD - DIFFICULT FOR HGVS

HGV NEED TO TRAVEL OVER THE CENTRE LINE



HGV NEED TO TRAVEL ON THE VERGE TO PASS EACH OTHER



#### LITTLE ROOM FOR CYCLISTS



# THE PAVEMENTS WE DO HAVE ARE DIRTY & UNEVEN







# DIRT ON THE ROAD, VERGES AND PAVEMENTS (WHERE WE HAVE THEM)



